Rog 19-108 NATIONAL TRANSPORTATION SAFETY BOARD WASHINGTON, D.C.

/ ISSUED: August 19, 1977

Forwarded to:

Honorable John M. Sullivan Administrator Federal Railroad Administration 400 7th Street, S.W. Washington, D.C. 20590

SAFETY RECOMMENDATION(S) R-77-24

About 11:35 a.m., on August 18, 1976, Greater Cleveland Regional Transit Authority (RTA) train No. 461 struck the rear of train No. 409 which was standing near the East 79th Street Station in Cleveland. Twenty persons were injured and property damage was estimated to be \$61,000. 1/

Investigation of the accident indicates that the method employed in the application of the automatic train stop (ATS) nullifies any protection that could be afforded by that system for an occupied signal block. Train No. 461 was only required to reduce speed to pass a stop signal with the trip arm in an up position. However, after No. 461 passed the stop signal, it resumed speed and passed the stop signal of the occupied block. The trip arm at this signal was not activated. Safety for the movement of the train rested with the operator, who failed to discharge his responsibility, sped past the signal, and struck the standing train.

The investigation also disclosed that the operators are orally informed of operating and safety rules during training and that they are not provided with a copy of those rules. Since the operators are not given refresher courses, the rules become vague and some are forgotten. Some operators have an almost indifferent attitude to the rules.

I/ For more detailed information on this accident, read "Railroad Accident Report, Rear End Collision of Two Greater Cleveland Regional Transit Authority Trains, Cleveland, Ohio, August 18, 1976" (NTSB-RAR-77-5).

RTA operators are not required to make predeparture tests of ATS, ATC, cab signals, brakes or radio equipment. A record of tests made by maintenance personnel is not provided to the operators. Also, cars that are disconnected from multicar trains to be used as single-unit trains may not be tested at all. The brakes are not tested by the operator until after the train departs the terminal.

The requirement that delays be reported to central control is apparently not being enforced. All delays beyond a normal station stop should be immediately reported and central control should in turn notify all trains in the area.

The Safety Board also believes that the Federal Railroad Administration should begin exercising its regulatory responsibilities relative to rapid transit systems. There is a need for operating standards and a system of checks and balances to insure conformance.

Therefore, the National Transportation Safety Board recommends that the Federal Railroad Administration:

> Establish operating and procedure standards for rail rapid transit systems. (Class II, Priority Followup) (R-77-24)

TODD, Chairman, BAILEY, Vice Chairman, McADAMS, HOGUE, and HALEY, Members, concurred in the above recommendations.

Jay Bailey

By: Webster B. Todd, Jr.