



U.S. Department of Labor ● Occupational Safety and Health Administration ● Kansas City Region VII No. 23

ACCIDENT SUMMARY

Accident Type: Fall

Weather Conditions: 75 degrees - some rain

Type of Company: Construction (repair/repaint water tanks)

Size of Work Crew: 5

Union or Non-Union: Non-union

Worksite Inspections

Conducted: No

Designated Competent

Person on Site: No

Employer Safety

and Health Program No

Training and Education for Employees: No

Craft of Deceased

Employee: Painter/Sandblaster

Age/Sex: 51/Male

Time on the Job: 2 days

Time at the Task: 1 hour

SOURCES OF HELP

- ♦ OSHA standards, regulations, documents and technical information are available on the Internet World Wide Web at http://www.OSHA.gov./. That information also is on CD-ROM, which may be purchased from the Government Printing Office, phone (202) 512-1800 or fax (202) 512-2250, Order No. 729-13-00000-5; cost \$79 annually; \$28 quarterly.
- ♦ For hard copies of OSHA Construction Standards [29 CFR Part 1926], which include all OSHA job safety and health rules and regulations covering construction, contact Government Printing Office, phone (202) 512-1800, fax (202) 512-2250, order number 869-022-00114-1, \$33.
- ♦ OSHA-funded free consultation services listed in telephone directories under U.S. Labor Department or under the state government section where states administer their own OSHA programs.
- ♦ OSHA Safety and Health Training Guidelines for Construction, Volume III (Available from the National Technical Information Service, 5285 Port Royal Road, Springfield, VA 22161; phone (703)487-4650; Order No. PB-239-312/AS, \$25 to help construction employers establish a training program.
- ♦ Courses in construction safety are offered by the OSHA Training Institute, 1555 Times Drive, Des Plaines, IL 60018, (847) 297-4810, and the Metropolitan Community Colleges Business & Technology Center, 6899 Executive Drive, Kansas City, MO 64120, (816) 482-5210.

BRIEF DESCRIPTION OF ACCIDENT

The employee/contractor climbed on top of the tank and entered the tank through a man-hole to help attach the ladder/platform device to be used to sandblast and paint the inside of the water tank. He apparently stepped from the "overflow box" under the man-hole to the ladder/platform device to secure that end of the ladder. The victim slipped and fell approximately 40 feet to the floor of the tank.

ACCIDENT PREVENTION RECOMMENDATIONS

- 1. Install and use personal fall arrest systems.
- 2. Install safety nets.
- 3. Install and use proper scaffolding.
- Proper use and installation of ladders.

the incident case. Your company or organization is eligible to receive one free copy of this leaflet which you may deshare with your co-workers. To be placed on the distribution list, send your name, title and address to: U.S. Department of the company of the send of the company of the send of the company						