




## Conclusion:

Although loose material has been moved around within the plunge pool, there appears to be no significant damage caused by normal discharges from the powerplant and outlet works, or occasional spillway flows.





Dimensioning layout for typical draft tube for Francis turbines.













