




Structurally Deficient Bridges on the National Highway System Michigan - Congressional District 10



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 251 structurally deficient NHS bridges in Michigan, 15 could not be geocoded because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	44144043000S070	I-69 WB	1.0 MI S OF LAPEER ,M-24
2	32132021000B010	M-142	1.0 MI W OF PIGEON
3	44144044000S090	I-69 EB	3.7 M W OF IMLAY CITY
4	44144044000R030	I-69 EB	2 MI SW IMLAY CITY
5	32132031000B010	M-53	2.0 MI N OF SANILAC CO LI
6	74174012000B030	M-53	5.8 MI S OF HURON CO LINE
7	44144032000B020	M-53	.2 MI S OF SANILAC CO LIN
8	44144031000B020	M-53	2.6MI S OF IMLAY CITY
9	74174061000B020	M-46	2.0 MI W OF M19
10	50150111000S274	I-94 WB	0.5 MI SE OF MT CLEMENS
11	50150111000S273	I-94 EB	0.5 MI SE OF MT CLEMENS
12	50150111000S284	I-94 WB	1.5 MI SW OF M-59
13	74174062000B010	M-46	5.6 MI E OF M-19
14	77177023000R030	I-69 WB.	1.5 MI W OF I-94
15	77177023000R010	I-69 EB	1.5 MI W OF I-94
16	77177111000S150	I-69 EB	@ I-69
17	77177111000S184	I-94 WB	.2 MI NE OF I-69
18	77177111000S183	I-94 EB	.2 MI NE OF I-69
19	77177023000R020	I-69 EB.	.7 MI E OF I-94
20	77177023000R040	I-69 WB.	.7 MI E OF I-94
21	77177111000B030	I-94	I-94