

---

# Corrections

Federal Register

Vol. 68, No. 139

Monday, July 21, 2003

---

This section of the FEDERAL REGISTER contains editorial corrections of previously published Presidential, Rule, Proposed Rule, and Notice documents. These corrections are prepared by the Office of the Federal Register. Agency prepared corrections are issued as signed documents and appear in the appropriate document categories elsewhere in the issue.

---

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39****[Docket No. 2003-CE-23-AD; Amendment 39-13173; AD 2003-11-14]****RIN 2120-AA64****Airworthiness Directives; The New Piper Aircraft, Inc. Models PA-34-200T, PA-34-220T, PA-44-180, and PA-44-180T Airplanes***Correction*

In rule document 03-13650 beginning on page 33356 in the issue of

Wednesday, June 4, 2003, make the following correction:

**§ 39.13 [Corrected]**

On page 33358, in § 39.13(d), in the first column, in the table, under the column heading "Actions", correct (1) to read as follows:

"(1) Visually inspect any installed aircraft heater fuel pump (model 91E92-1 or model 91E93-1) for leakage."

[FR Doc. C3-13650 Filed 7-18-03; 8:45 am]

**BILLING CODE 1505-01-D**