

**Authority:** 7 U.S.C. 8301–8317; 7 CFR 2.22, 2.80, and 371.4.

■ 2. In § 77.7, paragraph (b) is revised to read as follows:

**§ 77.7 Accredited-free States or zones.**

\* \* \* \* \*

(b) The following are accredited-free zones:

(1) A zone in Michigan known as the Upper Peninsula that comprises Alger, Baraga, Chippewa, Delta, Dickinson, Gogebic, Houghton, Iron, Keweenaw, Luce, Mackinac, Marquette, Menominee, Ontonagon, and Schoolcraft Counties.

(2) All of the State of New Mexico except for the zone that comprises those portions of Curry and Roosevelt Counties, NM, described in § 77.9(b)(2).

\* \* \* \* \*

■ 3. In § 77.9, paragraph (b)(1) is revised to read as follows.

**§ 77.9 Modified accredited advanced States or zones.**

\* \* \* \* \*

(b) \* \* \*

(1) The following are modified accredited advanced zones: All of the State of Michigan except for the zones that comprise those counties or portions of counties in Michigan described in § 77.7(b)(1) and § 77.11(b).

\* \* \* \* \*

Done in Washington, DC, this 30th day of September 2005.

**W. Ron DeHaven,**

*Administrator, Animal and Plant Health Inspection Service.*

[FR Doc. 05–20098 Filed 10–5–05; 8:45 am]

BILLING CODE 3410–34–P

653, 654, and 655 on July 14, 2005 (70 FR 40635). This final rule ensures that the Federal Agricultural Mortgage Corporation (Farmer Mac) continues to hold high-quality, liquid investments to maintain a sufficient liquidity reserve, invest surplus funds, and manage interest-rate risk, while maintaining non-program investments at appropriate levels considering Farmer Mac's status as a Government-sponsored enterprise. In accordance with 12 U.S.C. 2252, the effective date of the final rule is 30 days from the date of publication in the **Federal Register** during which either or both Houses of Congress are in session. Based on the records of the sessions of Congress, the effective date of the regulation is September 30, 2005.

**EFFECTIVE DATE:** The regulation amending 12 CFR parts 620, 621, 650, 651, 652, 653, 654, and 655 published on July 14, 2005 (70 FR 40635) is effective September 30, 2005.

**FOR FURTHER INFORMATION CONTACT:**

Joseph T. Connor, Associate Director for Policy and Analysis Office of Secondary Market Oversight, Farm Credit Administration, McLean, VA 22102–5090, (703) 883–4364, TTY (703) 883–4434; or Jennifer A. Cohn, Senior Attorney, Office of General Counsel, Farm Credit Administration, McLean, VA 22102–5090, (703) 883–4020, TTY (703) 883–4020.

(12 U.S.C. 2252(a)(9) and (10))

Dated: September 30, 2005.

**Jeanette C. Brinkley,**

*Secretary, Farm Credit Administration Board.*

[FR Doc. 05–20036 Filed 10–5–05; 8:45 am]

BILLING CODE 6705–01–P

repetitive inspections for environmental damage, including corrosion, of the fuselage and wing structure, and corrective actions if necessary. This AD results from information indicating the potential for environmental damage of the fuselage and wing structure. We are issuing this AD to detect and correct such damage, including corrosion, in the fuselage and wing structure, which could result in cracking and consequent reduced structural integrity of the fuselage and wing structure.

**DATES:** This AD becomes effective October 21, 2005.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of October 21, 2005.

We must receive comments on this AD by December 5, 2005.

**ADDRESSES:** Use one of the following addresses to submit comments on this AD.

- DOT Docket Web Site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-Wide Rulemaking Web Site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, Room PL–401, Washington, DC 20590.

- Fax: (202) 493–2251.

- Hand Delivery: Room PL–401 on the plaza level of the Nassif Building, 400 Seventh Street SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact British Aerospace Regional Aircraft American Support, 13850 Mclearen Road, Herndon, Virginia 20171, for service information identified in this AD.

**FOR FURTHER INFORMATION CONTACT:**

Todd Thompson, Aerospace Engineer, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 227–1175; fax (425) 227–1149.

**SUPPLEMENTARY INFORMATION:**

**Discussion**

The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom, notified us that an unsafe condition may exist on all BAE Systems (Operations) Limited Model ATP airplanes. The CAA advises that there is a potential for environmental damage of the fuselage and wing structure. New inspections for environmental damage were added to the ATP Maintenance Review Board

**FARM CREDIT ADMINISTRATION**

12 CFR Parts 620, 621, 650, 651, 652, 653, 654, and 655

RIN 3052–AC18

**Disclosure to Shareholders; Accounting and Reporting Requirements; Federal Agricultural Mortgage Corporation General Provisions; Federal Agricultural Mortgage Corporation Governance; Federal Agricultural Mortgage Corporation Funding and Fiscal Affairs; Federal Agricultural Mortgage Corporation Disclosure and Reporting Requirements; Effective Date**

**AGENCY:** Farm Credit Administration.

**ACTION:** Notice of effective date.

**SUMMARY:** The Farm Credit Administration (FCA) published a final rule under parts 620, 621, 650, 651, 652,

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA–2005–22583; Directorate Identifier 2002–NM–303–AD; Amendment 39–14318; AD 2005–20–22]

RIN 2120–AA64

**Airworthiness Directives; BAE Systems (Operations) Limited Model ATP Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule; request for comments.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all BAE Systems (Operations) Limited Model ATP airplanes. This AD requires

(MRB) Report and the Maintenance Planning Document (MPD). However, no compliance statements were included in these documents to advise operators when the first inspections must be performed. Environmental damage such as corrosion, if not corrected, could result in cracking and consequent reduced structural integrity of the fuselage and wing structure.

#### Relevant Service Information

BAE Systems (Operations) Limited has issued Service Bulletin ATP-51-001, dated August 14, 2002. The service bulletin describes procedures for repetitive detailed visual inspections for environmental damage, including but not limited to corrosion, of the fuselage and wing structure, and corrective actions if necessary. If damage is found, the service bulletin specifies to refer to the structural repair manual (SRM) for corrective action (repair). If the damage is outside the limits specified in the SRM, the service bulletin specifies to contact the manufacturer for repair instructions. The service bulletin also specifies reporting the inspection results to the manufacturer. The service bulletin specifies that the repetitive interval for the inspections in the service bulletin is stated in the MRB Report and the MPD. This repetitive interval is 8 years.

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. The CAA mandated BAE Systems (Operations) Limited Service Bulletin ATP-51-001 to ensure the continued airworthiness of these airplanes in the United Kingdom.

#### FAA's Determination and Requirements of This AD

This airplane model is manufactured in the United Kingdom and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above. We have examined the CAA's findings, evaluated all pertinent information, and determined that we need to issue an AD for products of this type design that are certificated for operation in the United States.

Therefore, we are issuing this AD to detect and correct environmental damage, including corrosion, of the fuselage and wing structure, which could result in cracking and consequent reduced structural integrity of the fuselage and wing structure. This AD

requires accomplishing the actions specified in BAE Systems (Operations) Limited Service Bulletin ATP-51-001, described previously, except as discussed under "Differences Between the AD and Service Information."

#### Clarification of Inspection Terminology

In this AD, the "detailed visual inspections" specified in BAE Systems (Operations) Limited Service Bulletin ATP-51-001 are referred to as "detailed inspections." We have included the definition for a detailed inspection in a note in the AD.

#### Differences Between the AD and Service Information

If damage is found that is outside the limits specified in the SRM, BAE Systems (Operations) Limited Service Bulletin ATP-51-001 specifies reporting the details of the damage to In-Service Engineering and asking for repair instructions. This AD requires repairing any damage that is outside the limits specified in the SRM in accordance with a method that we or the CAA (or its delegated agent) approve. In light of the type of repair that would be required to address the unsafe condition, and consistent with existing bilateral airworthiness agreements, we have determined that, for this AD, a repair we or the CAA approve would be acceptable for compliance with this AD.

BAE Systems (Operations) Limited Service Bulletin ATP-51-001 specifies reporting the inspection results to the manufacturer. This AD does not require that action.

#### Costs of Compliance

None of the airplanes affected by this action are on the U.S. Register. All airplanes affected by this AD are currently operated by non-U.S. operators under foreign registry; therefore, they are not directly affected by this AD action. However, we consider this AD necessary to ensure that the unsafe condition is addressed if any affected airplane is imported and placed on the U.S. Register in the future.

If an affected airplane is imported and placed on the U.S. Register in the future, the required actions would take about 44 work hours per airplane, at an average labor rate of \$65 per work hour. Based on these figures, the estimated cost of the AD would be \$2,860 per airplane, per inspection cycle.

#### FAA's Determination of the Effective Date

No airplane affected by this AD is currently on the U.S. Register. Therefore, providing notice and

opportunity for public comment is unnecessary before this AD is issued, and this AD may be made effective in less than 30 days after it is published in the **Federal Register**.

#### Comments Invited

This AD is a final rule that involves requirements that affect flight safety and was not preceded by notice and an opportunity for public comment; however, we invite you to submit any relevant written data, views, or arguments regarding this AD. Send your comments to an address listed in the **ADDRESSES** section. Include "Docket No. FAA-2005-22583; Directorate Identifier 2002-NM-303-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the AD that might suggest a need to modify it.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this AD. Using the search function of that web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

#### Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701,

“General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

- Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

**2005–20–22 BAE Systems (Operations) Limited (Formerly British Aerospace Regional Aircraft):** Amendment 39–14318. Docket No. FAA–2005–22583; Directorate Identifier 2002–NM–303–AD.

### Effective Date

- (a) This AD becomes effective October 21, 2005.

### Affected ADs

- (b) None.

### Applicability

- (c) This AD applies to all BAE Systems (Operations) Limited Model ATP airplanes, certificated in any category.

### Unsafe Condition

(d) This AD results from information indicating the potential for environmental damage of the fuselage and wing structure. We are issuing this AD to detect and correct such damage, including corrosion, in the fuselage and wing structure, which could result in cracking and consequent reduced structural integrity of the fuselage and wing structure.

### Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

### Repetitive Inspections and Corrective Actions

(f) Within 18 months after the effective date of this AD, perform detailed inspections for environmental damage, including but not limited to corrosion, of the fuselage and wing structure and any applicable corrective action in accordance with the Accomplishment Instructions of BAE Systems (Operations) Limited Service Bulletin ATP–51–001, dated August 14, 2002, except as provided by paragraph (g) of this AD. Any applicable corrective actions must be accomplished before further flight. Thereafter, repeat these inspections at intervals not to exceed those specified in the ATP Maintenance Review Board Report and the Maintenance Planning Document, as applicable, in accordance with the service bulletin.

**Note 1:** For the purposes of this AD, a detailed inspection is: “An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required.”

### Exception to Service Bulletin Instructions

(g) If damage is found that is outside the limits specified in the structural repair manual, as referenced in BAE Systems (Operations) Limited Service Bulletin ATP–51–001, dated August 14, 2002, and the service bulletin specifies reporting the details of the damage to In-Service Engineering and asking for repair instructions: Before further flight, repair the damage in accordance with a method approved by either the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the Civil Aviation Authority (or its delegated agent).

### No Reporting

(h) Although British Aerospace ATP Service Bulletin ATP–51–001, dated August 14, 2002, specifies reporting inspection results to the manufacturer, this AD does not require that action.

### Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, International Branch, ANM–116, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with 14 CFR 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

### Related Information

- (j) None.

### Material Incorporated by Reference

(k) You must use BAE Systems (Operations) Limited Service Bulletin ATP–51–001, dated August 14, 2002, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact British Aerospace Regional Aircraft American Support, 13850 Mclearn Road, Herndon, Virginia 20171, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL–401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741–6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 26, 2005.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 05–19833 Filed 10–5–05; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2005–22586; Directorate Identifier 2002–NM–258–AD; Amendment 39–14315; AD 2005–20–19]

**RIN 2120–AA64**

### Airworthiness Directives; BAE Systems (Operations) Limited Model ATP Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).