# **Rules and Regulations**

Federal Register

Vol. 70, No. 6

Monday, January 10, 2005

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

#### **SMALL BUSINESS ADMINISTRATION**

#### 13 CFR Part 125

RIN 3245-AF12

Small Business Government Contracting Programs; Subcontracting; Correction

**AGENCY:** Small Business Administration. **ACTION:** Final rule: correction.

**SUMMARY:** The U.S. Small Business Administration (SBA) is correcting a final rule that appeared in the Federal Register of December 20, 2004 (69 FR 75820). Among other things, the document issued a list of factors to consider in evaluating a prime contractor's performance and good faith efforts to achieve the requirements in its subcontracting plan and authorized the use of goals in subcontracting plans, and/or past performance in meeting such goals, as a factor in source selection when placing orders against Federal Supply Schedules, governmentwide acquisition contracts, and multiagency contracts. This document incorrectly stated that the final rule was effective on December 20, 2004. The document did not put the public on notice that the final rule had been designated as a major rule under the Congressional Review Act.

**DATES:** Effective January 10, 2005, the effective date of the final rule published on December 20, 2004 (69 FR 75820) is corrected to February 18, 2005.

# FOR FURTHER INFORMATION CONTACT:

Dean Koppel, Assistant Administrator, Office of Policy and Research, (202) 401–8150 or dean.koppel@sba.gov.

**SUPPLEMENTARY INFORMATION:** In 69 FR appearing on page 75820 in the **Federal Register** of Monday, December 20, 2004, the following corrections are made:

1. On page 75820, in the second column, the **DATES** section, "**DATES**: This rule is effective on December 20, 2004"

is corrected to read "**DATES:** This rule is effective on February 18, 2005."

2. On page 75824, in the first column, the second paragraph in the "Compliance with Executive Orders 13132, 12988 and 12866, the Regulatory Flexibility Act (5 U.S.C. 601–612), and the Paperwork Reduction Act (44 U.S.C. Ch. 35)" section, "The Office of Management and Budget (OMB) has determined that this rule constitutes a significant regulatory action under Executive Order 12866. The rule revises the SBA regulation governing small business contracting assistance to define good faith effort" is corrected to read The Office of Management and Budget (OMB) has determined that this rule constitutes an economically significant regulatory action under Executive Order 12866. OMB's determination is based on the expectation that this rule will expand the number of subcontracting awards currently received by small businesses pursuant to Federal prime contracts, which were worth \$34.4 billion in FY 2002. In addition, this rule has been designated as a major rule under the Congressional Review Act because even a marginal increase in the number of subcontract awards received by small businesses pursuant to Federal prime contracts as a result of this rule will exceed the \$100 million threshold for major rules."

Dated: January 4, 2005.

# Allegra F. McCullough,

Associate Deputy Administrator for Government Contracting and Business Development.

[FR Doc. 05–414 Filed 1–7–05; 8:45 am]

BILLING CODE 8025-01-P

# **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

### 14 CFR Part 39

[Docket No. 2003-NM-166-AD; Amendment 39-13936; AD 2005-01-12]

# RIN 2120-AA64

Airworthiness Directives; Boeing Model 757–200, –200PF, and –200CB Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT. **ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing Model 757-200, -200PF, and -200CB series airplanes, that requires an inspection of certain ballscrews of the trailing edge flap system to find their part numbers, and replacement of the ballscrews with new, serviceable, or modified ballscrews if necessary. This action is necessary to prevent a flap skew due to insufficient secondary load path of the ballscrew of the trailing edge flaps in the event that the primary load path fails, which could result in possible loss of a flap and reduced controllability of the airplane. This action is intended to address the identified unsafe condition.

**DATES:** Effective February 14, 2005. The incorporation by reference of a certain publication listed in the regulations is approved by the Director of the **Federal Register** as of February 14, 2005.

**ADDRESSES:** The service information referenced in this AD may be obtained from Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: http://www.archives.gov/ federal\_register/ code\_of\_federal\_regulations/ ibr locations.html.

# FOR FURTHER INFORMATION CONTACT:

Douglas Tsuji, Aerospace Engineer, Systems and Equipment Branch, ANM– 130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 917–6487; fax (425) 917–6590.

# SUPPLEMENTARY INFORMATION: A

proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Boeing Model 757–200, –200PF, and –200CB series airplanes was published in the **Federal Register** on April 1, 2004 (69 FR 17105). That action proposed to require an inspection of certain ballscrews of the trailing edge flap system to find their part numbers, and replacement of the ballscrews with new, serviceable, or modified ballscrews if necessary.