

acquired during the 2005–06 crop year and continue in effect until all 2005–06 reserve raisins are disposed of under the order. Accordingly, § 989.258 will appear in the Code of Federal Regulations.

A small business guide on complying with fruit, vegetable, and specialty crop marketing agreements and orders may be viewed at: <http://www.ams.usda.gov/fv/moab.html>. Any questions about the compliance guide should be sent to Jay Guerber at the previously mentioned address in the **FOR FURTHER INFORMATION CONTACT** section.

After consideration of all relevant material presented, including the Committee's recommendation, and other information, it is found that finalizing the interim final rule, without change, as published in the **Federal Register** (71 FR 29567, May 23, 2006) will tend to effectuate the declared policy of the Act.

List of Subjects in 7 CFR Part 989

Grapes, Marketing agreements, Raisins, Reporting and recordkeeping requirements.

PART 989—RAISINS PRODUCED FROM GRAPES GROWN IN CALIFORNIA

■ Accordingly, the interim final rule amending 7 CFR part 989 which was published at 71 FR 29567 on May 23, 2006, is adopted as a final rule without change.

Dated: January 12, 2007.

Lloyd C. Day,

Administrator, Agricultural Marketing Service.

[FR Doc. E7–623 Filed 1–17–07; 8:45 am]

BILLING CODE 3410–02–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2006–25584; Directorate Identifier 2000–NE–62–AD; Amendment 39–14733; AD 2006–17–12]

RIN 2120–AA64

Airworthiness Directives; Rolls-Royce plc RB211 Series Turbofan Engines; Correction.

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: This document makes corrections to Airworthiness Directive (AD) 2006–17–12. That AD applies to

Rolls-Royce plc RB211 series turbofan engines. We published AD 2006–17–12 in the **Federal Register** on August 23, 2006 (71 FR 49339). An incorrect engine model number exists in the applicability paragraph and in the title of Table 5. Also, an incorrect serial number appears in Table 1. This document corrects these numbers. In all other respects, the original document remains the same.

DATES: *Effective Date:* Effective January 18, 2007.

FOR FURTHER INFORMATION CONTACT: Ian Dargin, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA, 01803; telephone (781) 238–7178; fax (781) 238–7199.

SUPPLEMENTARY INFORMATION: A final rule AD, FR Doc. E6–13910, that applies to Rolls-Royce plc RB211 series turbofan engines was published in the **Federal Register** on August 23, 2006 (71 FR 49339). The following corrections are needed:

§ 39.13 [Corrected]

■ On page 49340, in the third column, in applicability paragraph (c), in the fourth line, “RB211–535E4–C” is corrected to read “RB211–535E4–C–37”. Also, on page 49341, in Table 1, in the fourth column, in the last line, “WGQDY90005” is corrected to read “WGQDY0005”. Also, on page 49342, in the first column, in the Table 5 title, “RB211–02” is corrected to read “RB211–22B–02”.

Issued in Burlington, MA, on January 10, 2007.

Francis A. Favara,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E7–497 Filed 1–17–07; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2007–26855; Directorate Identifier 2006–NM–264–AD; Amendment 39–14888; AD 2007–02–01]

RIN 2120–AA64

Airworthiness Directives; Dassault Model F2000EX Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as incorrect monitoring of the fire detection system; therefore, its integrity is not guaranteed at all times. This AD requires actions that are intended to address the unsafe condition described in the MCAI.

DATES: This AD becomes effective February 2, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain document listed in this AD as of February 2, 2007.

We must receive comments on this AD by March 19, 2007.

ADDRESSES: You may send comments by any of the following methods:

- *DOT Docket Web Site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Fax:* (202) 493–2251.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL–401, Washington, DC 20590–0001.

- *Hand Delivery:* Room PL–401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Federal Rulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647–5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–1137; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION: