

(3) If the FDIC has established a restoration plan pursuant to section 7(b)(3)(E) of the Federal Deposit Insurance Act, the FDIC may elect to restrict the application of credit amounts, in any assessment period, to the lesser of:

- (i) The amount of an insured depository institution's assessment for that period; or
- (ii) The amount equal to 3 basis points of the institution's assessment base.

§ 327.36 Requests for review of credit amount.

(a)(1) An insured depository institution may submit a request for review of the FDIC's final determination of the institution's credit amount as shown on the Statement of One-time Credit ("Statement") within 30 days of the date the FDIC makes the Statement available. Such review may be requested if:

- (i) The institution disagrees with a determination as to eligibility for the credit that relates to that institution's credit amount;
- (ii) The institution disagrees with the calculation of the credit as stated on the Statement; or
- (iii) The institution believes that the 1996 assessment base ratio attributed to the institution on the Statement does not fully or accurately reflect its own 1996 assessment base or appropriate adjustments for successors.

(2) If an institution does not submit a timely request for review, that institution may not subsequently request review of its credit amount, subject to paragraph (e) of this section.

(b)(1) An insured depository institution may submit a request for review of the FDIC's adjustment to the credit amount in a quarterly invoice within 30 days of the date on which the FDIC provides the invoice. Such review may be requested if:

- (i) The institution disagrees with the calculation of the credit as stated on the invoice; or
- (ii) The institution believes that the 1996 assessment base ratio attributed to the institution due to the adjustment to the invoice does not fully or accurately reflect appropriate adjustments for successors since the last quarterly invoice.

(2) If an institution does not submit a timely request for review, that institution may not subsequently request review of its credit amount, subject to paragraph (e) of this section.

(c) The request for review shall be submitted to the Division of Finance and shall provide documentation sufficient to support the change sought by the institution. At the time of filing

with the FDIC, the requesting institution shall notify, to the extent practicable, any other insured depository institution that would be directly and materially affected by granting the request for review and provide such institution with copies of the request for review, the supporting documentation, and the FDIC's procedures for requests under this subpart. The FDIC shall make reasonable efforts, based on its official systems of records, to determine that such institutions have been identified and notified.

(d) During the FDIC's consideration of the request for review, the amount of credit in dispute shall not be available for use by any institution.

(e) Within 30 days of the filing of the request for review, those institutions identified as potentially affected by the request for review may submit a response to such request, along with any supporting documentation, to the Division of Finance, and shall provide copies to the requesting institution. If an institution that was notified under paragraph (c) of this section does not submit a response to the request for review, that institution may not:

(1) Subsequently dispute the information submitted by other institutions on the transaction(s) at issue in the review process; or

(2) Appeal the decision by the Director of the Division of Finance.

(f) If additional information is requested of the requesting or affected institutions by the FDIC, such information shall be provided by the institution within 21 days of the date of the FDIC's request for additional information.

(g) Any institution submitting a timely request for review will receive a written response from the FDIC's Director of the Division of Finance:

- (1) Within 60 days of receipt by the FDIC of the request for revision;
- (2) If additional institutions have been notified by the requesting institution or the FDIC, within 60 days of the date of the last response to the notification; or

(3) If additional information has been requested by the FDIC, within 60 days of receipt of the additional information, whichever is later. Whenever feasible, the response will notify the institution of the determination of the Director as to whether the requested change is warranted. In all instances in which a timely request for review is submitted, the Director will make a determination on the request as promptly as possible and notify the institution in writing of the determination. Notice of the procedures applicable to reviews will be

included with the Statement and assessment invoices.

(h) Subject to paragraph (e) of this section, the insured depository institution that requested review under this section, or an insured depository institution materially affected by the Director's determination, that disagrees with that determination may appeal to the FDIC's Assessment Appeals Committee on the same grounds as set forth under paragraph (a) of this section. Any such appeal must be submitted within 15 calendar days from the date of the Director's written determination. Notice of the procedures applicable to appeals under this section will be included with the Director's written determination. The decision of the Assessment Appeals Committee shall be the final determination of the FDIC.

By order of the Board of Directors.

Dated at Washington, DC, this 9th day of May, 2006.

Federal Deposit Insurance Corporation.

Robert E. Feldman,

Executive Secretary.

[FR Doc. E6-7583 Filed 5-17-06; 8:45 am]

BILLING CODE 6714-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-24793; Directorate Identifier 2006-NM-056-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A330, A340-200, and A340-300 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus Model A330, A340-200, and A340-300 airplanes. This proposed AD would require replacing the attachment landing assemblies of certain blow-down panels of the wing leading edges with new, improved landing assemblies. This proposed AD results from several reports of full or partial loss of certain blow-down panels of the wing leading edges during flight. We are proposing this AD to prevent damage to the airplane and hazards to persons or property on the ground.

DATES: We must receive comments on this proposed AD by June 19, 2006.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.
- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.
- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590.
- *Fax:* (202) 493-2251.
- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT: Tim Backman, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2797; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number “FAA-2006-24793; Directorate Identifier 2006-NM-056-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal

information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT’s complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

The European Aviation Safety Agency (EASA) notified us that an unsafe condition may exist on certain Airbus A330, A340-200, and A340-300 airplanes. The EASA advises that several operators have reported full or partial loss of certain blow-down panels of the wing leading edges during flight. Analysis showed that wing vibration resulted in wear formation of the rivet slots or complete shearing of the attaching rivets of the blow-down panel landings. This condition, if not corrected, could result in damage to the airplane and hazards to persons or property on the ground.

Relevant Service Information

Airbus has issued Service Bulletins A330-57-3091; and A340-57-4100;

both dated October 25, 2005. The service bulletins describe procedures for replacing the attachment landing assemblies of certain blow-down panels of the wing leading edges with new, improved landing assemblies. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. The EASA mandated the service information and issued the EASA airworthiness directive 2006-0048, dated February 16, 2006, to ensure the continued airworthiness of these airplanes in the European Union.

FAA’s Determination and Requirements of the Proposed AD

These airplane models are manufactured in France and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to FAA Order 8100.14A, “Interim Procedures for Working with the European Community on Airworthiness Certification and Continued Airworthiness,” dated August 12, 2005, the EASA has kept the FAA informed of the situation described above. We have examined the EASA’s findings, evaluated all pertinent information, and determined that we need to issue an AD for products of this type design that are certificated for operation in the United States.

Therefore, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

The following table provides the estimated costs for U.S. operators of Model A330 airplanes to comply with the modifications required by this proposed AD. The estimated labor rate is \$80 per work hour.

ESTIMATED COSTS

Airplane group	Work hours	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
1, 2, 3, 4, 5	68	\$25,120	\$30,560	5 (group 2 only)	\$152,800
6	11	2,480	3,360	22	73,920

Currently, there are no Model A340-200 or A340-300 airplanes on the U.S. Register. However, if an affected Model A340-200 or A340-300 airplane is imported and placed on the U.S. Register in the future, the estimated

costs shown in the table above will apply to accomplish the required actions of this proposed AD for that airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII,

Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13

by adding the following new airworthiness directive (AD):

Airbus: Docket No. FAA-2006-24793; Directorate Identifier 2006-NM-056-AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by June 19, 2006.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Airbus A330, A340-200, and A340-300 airplanes, certificated in any category; all serial numbers; except for airplanes which have received both Airbus modification 47249 and Airbus modification 53383 in production.

Unsafe Condition

(d) This AD results from several reports of full or partial loss of certain blow-down panels of the wing leading edges during flight. We are issuing this AD to prevent damage to the airplane and hazards to persons or property on the ground.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Replacement

(f) Within 56 months after the effective date of this AD, replace the landing assemblies of certain blow-down panels of the wing leading edges with new, improved landing assemblies; in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-57-3091; or Airbus Service Bulletin A340-57-4100; both dated October 25, 2005; as applicable.

Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(h) The European Aviation Safety Agency airworthiness directive 2006-0048, dated February 16, 2006, also addresses the subject of this AD.

Issued in Renton, Washington, on May 9, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-7560 Filed 5-17-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-22630; Directorate Identifier 2001-NM-323-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300 B4-600, B4-600R, and F4-600R Series Airplanes, and Model C4-605R Variant F Airplanes (Collectively Called A300-600 Series Airplanes); and Airbus Model A310-200 and -300 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Supplemental notice of proposed rulemaking (NPRM); reopening of comment period.

SUMMARY: The FAA is revising an earlier NPRM for an airworthiness directive (AD) that applies to all Airbus Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model C4-605R Variant F airplanes (collectively called A300-600 series airplanes); and A310-200 and -300 series airplanes. The original NPRM would have required a one-time inspection of the trimmable horizontal stabilizer actuator (THSA), corrective actions if necessary, and follow-on repetitive tasks. The original NPRM resulted from reports of THSAs that have reached their design operational life. This operational life can be extended provided an initial inspection and follow-on repetitive tasks are accomplished. This action revises the original NPRM by revising the initial compliance time. It also allows the component maintenance manual as an alternative repair method. We are proposing this supplemental NPRM to extend the operational life of the THSA to prevent a possible failure of high-time THSAs, which could result in reduced controllability of the airplane.

DATES: We must receive comments on this supplemental NPRM by June 12, 2006.

ADDRESSES: Use one of the following addresses to submit comments on this supplemental NPRM.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.