

**General Electric Company
Pittsfield, Massachusetts**

**Groundwater Management Area 1
NAPL Monitoring Report for
Fall 2006**

Volumes I and II of II

February 2007

Table of Contents

Volume I of II

Section 1 – Introduction
Section 2 – Background Information
Section 3 – Historical NAPL Monitoring and Recovery Activities
Section 4 – Fall 2006 NAPL Monitoring and Recovery Activities and Results
Section 5 – Effectiveness Evaluation and Future Program Modifications
Section 6 – Schedule for Future Activities

Tables

Figures

Volume II of II

Appendices

Appendix A – Automated Recovery System Construction Details
Appendix B – Summary of Historical NAPL Recovery
Appendix C – Summary of Automated LNAPL Recovery
Appendix D – Summary of Automated DNAPL Recovery
Appendix E – Groundwater Elevation and NAPL Thickness/Recovery Data
Appendix F – East Street Area 2-South LNAPL Recovery/Efficiency Data
Appendix G – River Bank Inspection Forms