

**APPENDIX A
SITE INSPECTION PHOTO LOG**



Photo 1: Site inspection team discussing monitoring well locations and sample results for site WP45/SS57. The inspection team includes USAF, USEPA, and ADEC representatives, by EA Engineering staff.



Photo 2: Garrison Slough exiting the Water Treatment Plant Pond at SS35.



Photo 3: Fish screens along Garrison Slough.



Photo 4: Containment cells storing POL impacted soils at LF03.



Photo 5: Fire Training Facility at FT09.



Photo 6: Munitions storage facility constructed at LF03.



Photo 7: Looking north at WP38.



Photo 8: Engineer Hill (ST56) septic system location.