

## **Appendix H**

### Elderberry Shrubs at Erosion Sites



**Appendix H**  
**The Erosion Repair of 13 Bank Protection Sites**  
 Elderberry Shrubs at Erosion Sites

Erosion Site	ID	Northing	Easting	Zone <sup>i</sup>	In Riparian Habitat?	Stems 1"≤X<3" <sup>ii</sup>	Stems 3"≤X<5"	Stems 5"≤X	Bore Holes 1"≤X<3"	Bore Holes 3"≤X<5"	Bore Holes 5"≤X	Total Stems <sup>iii</sup>
LAR 0.3L	E001	1981215.1	6704605.5	O	Yes	2	0	0	1	0	0	2
LAR 0.3L	E002	1981217.4	6704601.7	O	Yes	1	0	0	0	0	0	1
LAR 0.3L	E003	1981217.9	6704601.5	O	Yes	1	0	0	0	0	0	1
LAR 0.3L	E004	1981209.4	6704585.7	O	Yes	1	0	0	0	0	0	1
LAR 0.3L	E005	1981203.3	6704581.4	O	Yes	1	0	0	0	0	0	1
LAR 0.3L	E006	1981198.6	6704601.8	O	Yes	1	0	0	0	0	0	1
LAR 0.3L	E007	1981197.5	6704575.4	O	Yes	1	0	0	0	0	0	1
LAR 0.3L	E008	1981169.4	6704520.8	O	Yes	1	0	0	0	0	0	1
LAR 0.3L	E009	1981109.8	6704345.4	CE	Yes	9	3	3	0	1	3	15
LAR 0.3L	E010	1981097.6	6704315.7	CE	Yes	13	5	2	0	4	4	20
LAR 0.3L	E011	1981066.3	6704262.3	CE	Yes	9	4	4	2	4	14	17
LAR 0.3L	E012	1981044.0	6704229.6	CE	Yes	11	1	0	4	0	0	12
Sac 53.5R	E027	1951472.0	6697321.3	CE	Yes	29	2	8	0	0	0	39
Sac 77.2L	E040	2039024.0	6678096.9	CE	Yes	10	0	0	0	0	0	10
F 28.5R	E031	2175649.5	6673918.2	CE	Yes	1	0	0	0	0	0	1
F 28.5R	E032	2175638.0	6673920.8	CE	Yes	1	0	0	0	0	0	1
F 28.5R	E033	2175540.3	6673953.7	O	Yes	0	3	1	0	0	0	4
F 28.5R	E034	2175530.7	6673950.8	O	Yes	5	1	1	0	0	0	7
F 28.5R	E036	2175749.3	6673843.6	PF	Yes	9	10	3	0	1	0	22

<sup>i</sup> PF = within Project Footprint, CE = within construction easement, O = outside of erosion site and construction easement

<sup>ii</sup> Diameter at ground level

<sup>iii</sup> Only stems ≥ 1" at ground level included