



Front View



Rear View




Loose/broken/delaminated
Damage/wear/hole

Previous repair
Replaced piece

Missing
Spindles not original to desk


Add-ons
Inscriptions

Right Side




- Loose/broken/delaminated
- Damage/wear/hole
- Previous repair
- Replaced piece



Left Side







- Missing
- Add-ons
- Spindles not original to desk
- Inscriptions



Top




 Loose/broken/delaminated
 Damage/wear/hole

 Previous repair
 Replaced piece


 Missing
 Spindles not original to desk

 Add-ons
 Inscriptions

Bottom



Bottom




Loose/broken/delaminated
Damage/wear/hole

Previous repair
Replaced piece


Missing
Spindles not original to desk

Add-ons
Inscriptions

Drawer Front, Outer Surface



Rear Surface of Drawer Front



Loose/broken/delaminated
Damage/wear/hole



Previous repair
Replaced piece

Missing
Spindles not original to desk

Add-ons
Inscriptions

Inside Surface of Left Drawer Side

Inside Surface of Right Drawer Side




Loose/broken/delaminated
Damage/wear/hole

Previous repair
Replaced piece


Missing
Spindles not original to desk



Add-ons
Inscriptions



Rear Surface of Drawer Back





Front Surface of Drawer Back



 Loose/broken/delaminated
 Damage/wear/hole



 Previous repair
 Replaced piece

 Missing
 Spindles not original to desk

 Add-ons
 Inscriptions

Upper Surface of Drawer Bottom

Lower Surface of Drawer Bottom



Loose/broken/delaminated
Damage/wear/hole


Previous repair
Replaced piece


Missing
Spindles not original to desk


Add-ons
Inscriptions


Outside Surface, Right Drawer Side


Outside Surface, Left Drawer Side





 Loose/broken/delaminated


 Previous repair

 Missing

 Add-ons

 Damage/wear/hole

 Replaced piece

 Spindles not original to desk

 Inscriptions