

U.S. Senate Desk Description and Condition Report

Desk No : **66.00036.000**

Paper Label No.(on shelf bottom): **64**

Painted No. (on bottom): **N/A**

Other identifying labels or marks (specify location): Stretcher: 63, 64, XXXVI / Top: (stamped) 63/ Drawer Bottom: outside - No. 29 ; inside - /Drawer Back: / Bottom of Shelf (other than paper label): / Drawer Blade: Inside Case Back: / Inkwell: (pencil) 76

Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height:	34 7/8	32 9/16		
Width (front)	28 1/2	26 1/2	25 5/8	
Width (rear)	26 3/4	25	24 1/4	
Depth	20	20	19 1/8	9 9/16

* Note: Dimensions do not include "booster" blocks added to feet or writing top.

Woods

Primary:

Mahogany

Mahogany veneer

Rosewood veneer

Other Wood (specify): _____

Character of case mahogany:

Plain

Ribbon

Mottled

Crotch

Other

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides				✓	
Drawer Bottom			✓		
Drawer Back			✓		
Case Interior		✓			
Drawer Front	✓				

Condition of Desk

Structure

Previous breaks in structural elements: Yes
(shown on schematic)
No

Current split or broken elements: Yes
(shown on schematic)
No

Other loose or damaged joinery: Yes
(describe in narrative)
No

Damage to drawer front: Extreme
Moderate
Minor

Drawer lock: relocated on face Yes
Drawer lock: resized on inside Yes

Cockbead on drawer front: Damaged
(show on schematic)
Missing
Loose
Replacements

Replaced drawer-side runners: Yes
No

Replaced case-side runners: Yes
No

Drawer bottom pieced-out at back edge: Yes
No

Wear on Feet	Extreme	Moderate	Minor
Front		✓	
Rear			✓

Number of loose spindles: No: 2

Number of replaced spindles: No: 1
(show on schematic)

Replaced veneers and cross-banding: Yes
(show on schematic)
No

Missing veneers and cross-banding: Yes
(show on schematic)
No

Delaminated/loose veneers & cross-banding: Yes
(show on schematic)
No

Shelf supports: Original/old
New/recent
Missing

Spindle support board in case: Yes
No