#### UNITED STATES DEPARTMENT OF THE INTERIOR

# MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

# ACCIDENT INVESTIGATION REPORT

1.	OCCURRED	8.	CAUSE: EQUIPMENT FAILURE			
	DATE: 30-OCT-2005 TIME: 1500 HOURS		HUMAN ERROR			
2.	OPERATOR: Marlin Energy Offshore, L.L.C.		EXTERNAL DAMAGE			
			SLIP/TRIP/FALL			
			WEATHER RELATED			
	REPRESENTATIVE: Lee Lawson		LEAK			
	TELEPHONE: (337) 769-4064		UPSET H2O TREATING			
3.	LEASE: 00263		OVERBOARD DRILLING FLUID			
	AREA: ST LATITUDE: 29.0226738		X OTHER trapped gas			
	BLOCK: 21 LONGITUDE: -90.257612	9.	WATER DEPTH: 36 FT.			
4.	PLATFORM: 80	10.	DISTANCE FROM SHORE: 15 MI.			
	RIG NAME	11.	WIND DIRECTION: NNE			
	RIG NAME		SPEED: 5 M.P.H.			
5.	ACTIVITY: EXPLORATION(POE)	12.	CURRENT DIRECTION: E			
	X DEVELOPMENT/PRODUCTION		SPEED: 1 M.P.H.			
_	(DOCD/POD)	13.	SEA STATE: 2 FT.			
6.	TYPE: X FIRE					
	EXPLOSION					
	BLOWOUT  COLLISION  INJURY NO1  FATALITY NO0		OPERATOR REPRESENTATIVE/			
			SUPERVISOR ON SITE AT TIME OF INCIDENT:			
			Bob Hoffpauir			
			CITY: Lafayette STATE: LA			
	POLLUTION		_			
	OTHER		TELEPHONE: (337) 235-9112			
7.	OPERATION: PRODUCTION		CONTRACTOR: Superior Energy Services, Inc.			
	DRILLING					
	WORKOVER  COMPLETION  MOTOR VESSEL		CONTRACTOR REPRESENTATIVE/			
			SUPERVISOR ON SITE AT TIME OF INCIDENT:			
			Will Sanchez			
	☐ PIPELINE SEGMENT NO.		CITY: Harvey STATE: LA			
			TELEPHONE: (800) 259-7774			
	OTHER					

MMS - FORM 2010 PAGE: 1 OF 5

#### 17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

At the time of the incident, the crew was preparing the well for a sidetrack. Eight nuts and bolts were removed from the tubing hanger flange. The hanger pins were backed out and one was removed. The bleed port was opened and an allen screw was removed. Four nuts and bolts were left that could not be removed by a hammer wrench or impact wrench. A hot work permit was completed, a gas detector was used indicating no signs of hydrocarbons, and a fire watch was stationed. While cutting with a torch on the first of the four nuts that remained, a flash fire occurred. Every precaution was taken to prevent a fire, but moving the flange around allowed gas that was trapped in the hanger to migrate and catch fire. The fire flared up and caught the injured party's neck area causing a red rash. They put burn cream on the rash area and the injured party returned to work. The fire flashed up and went out, so no fire fighting equipment was used.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Trapped gas in the hanger that was released when the nut was cut.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

Nuts that were unable to be unscrewed.

MMS - FORM 2010 PAGE: 2 OF 5

10-JAN-2006

EV2010R

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

none

n/a

ESTIMATED AMOUNT (TOTAL):

\$

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

Due to the specific nature of this incident, the Houma District has no recommendations to report to the Regional Office.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

none

- 25. DATE OF ONSITE INVESTIGATION:
- 26. ONSITE TEAM MEMBERS:

Amy Gresham /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Michael J. Saucier

APPROVED

DATE: 21-DEC-2005

MMS - FORM 2010 PAGE: 3 OF 5

### **FIRE/EXPLOSION ATTACHMENT**

1.	SOURCE OF IGNITIO	ON: C	utting torch		
2.	TYPE OF FUEL:	<b>x</b>	GAS OIL DIESEL CONDENSATE		
			HYDRAULIC OTHER		
3.	FUEL SOURCE: Tr	apped	gas		
4.			CTIONS TAKEN TO IS		
5.	TYPE OF FIREFIGHT	FING E	EQUIPMENT UTILIZED	:	WHEELED UNIT FIXED CHEMICAL FIXED WATER NONE
				Ш	OTHER

MMS - FORM 2010 PAGE: 4 OF 5

## INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPRESE		x	INJURY			
OTHER			WITNESS			
NAME: HOME ADDRESS:						
CITY: STATE:						
WORK PHONE:	TOTAL OF	FSHOF	RE EXPERIENCE:	YEARS		
	erior Energy Services,	Inc	. / 21461			
BUSINESS ADDRESS:	1615 Poydras Street					
CITY:	New Orleans		STATE: LA			
ZIP CODE:	70112					

MMS - FORM 2010 PAGE: 5 OF 5