UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

| | OCCURRED DATE: 06-SEP-2006 TIME: 0800 HOURS OPERATOR: Kerr-McGee Oil & Gas Corporation REPRESENTATIVE: Gerald Doega TELEPHONE: (281) 673-6705 CONTRACTOR: Baker Energy, Inc. REPRESENTATIVE: Mark Lemaire | STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE | | | |
|----|---|---|--|--|--|
| 3. | TELEPHONE: (337) 406-8300 OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT: | OTHER 6. OPERATION: | | | |
| | LEASE: 00336 AREA: SS LATITUDE: 29.093296 BLOCK: 33 LONGITUDE: -91.283085 PLATFORM: C-3(PRODUCTION) RIG NAME: | PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. OTHER | | | |
| 6. | ACTIVITY: | 8. CAUSE: | | | |
| 7. | DEVELOPMENT/PRODUCTION (DOCD/POD) TYPE: HISTORIC INJURY X REQUIRED EVACUATION 0 LTA (1-3 days) LTA (>3 days 1 RW/JT (1-3 days) RW/JT (>3 days) | EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE X SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER | | | |
| | Other Injury FATALITY | 9. WATER DEPTH: 20 FT. | | | |
| | POLLUTION FIRE | 10. DISTANCE FROM SHORE: 10 MI. | | | |
| | LWC HISTORIC BLOWOUT UNDERGROUND | 11. WIND DIRECTION: N SPEED: 20 M.P.H. | | | |
| | SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES | 12. CURRENT DIRECTION: SSE SPEED: 1 M.P.H. | | | |
| | COLLISION HISTORIC >\$25K <=\$25K | 13. SEA STATE: 4 FT. | | | |

MMS - FORM 2010 PAGE: 1 OF 5

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

The employee placed a 36-inch pipewrench and cheater pipe on the 13C Well Header valve to switch the well into test. The employee had his left foot on a padeye and his right foot on the main decking. The cheater pipe was about chest level. When he pulled the wrench towards him, the wrench slipped of the valve and the momentum carried him overboard. He climbed up on some piping and remained there until other crewmembers noticed he was missing. Finally a crew member noticed him in the water. They were able to put a body harness around him and pull him up to the main deck. He had a bump on his head, scratches on his right forearm, and a puncture in the center of his lower back. He was flown into the hospital. He was in the hospital for about a week fighting an infection. He has a broken tail bone and going through physical therapy. There is no indication of when he will return to work.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

The wrench slipped and the momentum caused him to fall overboard.

- 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:
 - 1. Improper footing may have been a contributing cause to this incident.
 - 2. Improper valve maintenance.
 - 3. Improper tool for the job. Valve has a tool specifcally manufactored for the valve. When it becomes difficult to operate valve needs mantenance.

MMS - FORM 2010 PAGE: 2 OF 5

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

None

n/a

ESTIMATED AMOUNT (TOTAL):

\$

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

Due to the specific nature of this incident, the Houma District has no recommendations to report to the Regional Office.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

none

- 25. DATE OF ONSITE INVESTIGATION:
- 26. ONSITE TEAM MEMBERS:

Amy Wilson /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Michael J. Saucier

APPROVED

DATE: 14-DEC-2006

MMS - FORM 2010 PAGE: 3 OF 5

EV2010R

INJURY/FATALITY/WITNESS ATTACHMENT

| OPERATOR REPR | RESENTATIVE EPRESENTATIVE | x INJURY FATALITY WITNESS | | | |
|---------------------------------------|--|---|------|--|--|
| NAME: HOME ADDRESS: CITY: WORK PHONE: | 1301 S. 1st St. | STATE: LA OFFSHORE EXPERIENCE: 24 | /EAF | | |
| | Baker Energy, Inc. / 2 S: 163 Park Ten Place Suite 320 Houston 77084 | | _ | | |
| | RESENTATIVE EPRESENTATIVE | INJURY FATALITY WITNESS | | | |
| NAME: HOME ADDRESS: CITY: WORK PHONE: | 5330 Hamilton Drive | STATE: TX OFFSHORE EXPERIENCE: Y | /EAF | | |
| | | | | | |
| | Baker Energy, Inc. / 2 S: 163 Park Ten Place Suite 320 | | | | |

MMS - FORM 2010 PAGE: 4 OF 5

INJURY/FATALITY/WITNESS ATTACHMENT

| | | | | Y | | | | | | |
|-----------------|---|----------------|--------|-------|-------|--|--|--|--|--|
| NAME: | Serald Fondel 1003 S. Division | | | | | | | | | |
| | Lake Charles | STATE | : LA | | | | | | | |
| WORK PHONE: | | TOTAL OFFSHORE | EXPERI | ENCE: | YEARS | | | | | |
| EMPLOYED BY: | EMPLOYED BY: Baker Energy, Inc. / 20290 | | | | | | | | | |
| BUSINESS ADDRES | BUSINESS ADDRESS: 163 Park Ten Place | | | | | | | | | |
| | Suite 320 | | | | | | | | | |
| CITY: | Houston | S | STATE: | TX | | | | | | |
| ZIP CODE: | 77084 | | | | | | | | | |

MMS - FORM 2010 PAGE: 5 OF 5 05-APR-2007