UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

| 1. | OCCURRED DATE: 24-JAN-2007 TIME: 1200 HOURS | STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE |
|----|---|---|
| 2. | OPERATOR: BP Exploration & Production Inc. REPRESENTATIVE: Greg Wiltz TELEPHONE: (281) 366-5647 CONTRACTOR: REPRESENTATIVE: TELEPHONE: | DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER |
| 3. | OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT: | 6. OPERATION: |
| | LEASE: G19925 AREA: MC LATITUDE: BLOCK: 127 LONGITUDE: | PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL |
| 5. | PLATFORM: A-Horn Mountain RIG NAME: | PIPELINE SEGMENT NO. OTHER |
| | ACTIVITY: EXPLORATION(POE) DEVELOPMENT/PRODUCTION (DOCD/POD) TYPE: HISTORIC INJURY | 8. CAUSE: EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL |
| | X REQUIRED EVACUATION 1 LTA (1-3 days) X LTA (>3 days 1 RW/JT (1-3 days) RW/JT (>3 days) Other Injury | WEATHER RELATED LEAK UPSET H2O TREATING OVERBOARD DRILLING FLUID OTHER |
| | FATALITY POLLUTION FIRE | 9. WATER DEPTH: 5400 FT. 10. DISTANCE FROM SHORE: 60 MI. |
| | EXPLOSION LWC HISTORIC BLOWOUT UNDERGROUND | 11. WIND DIRECTION: SPEED: M.P.H. |
| | SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES | 12. CURRENT DIRECTION: SPEED: M.P.H. |
| | COLLISION HISTORIC >\$25K <=\$25K | 13. SEA STATE: FT. |

MMS - FORM 2010 PAGE: 1 OF 3

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

While cleaning up after a job around the Methanol tank, Operations personnel started to remove tools from an elevated work platform. The crew was lowering a pry bar down to the work deck, attempting to tie a 1/2 inch rope around the pry bar when the pry bar slipped out of crew member's hand falling at an angle, striking the ladder cage causing the pry bar to deflect and strike the injured person (IP), who was standing approximately 5 feet from the caged ladder. The job was stopped and the IP immediately left the worksite and notified medic. HSSE Advisor and OIM was notified. IP was evacuated. The IP lost three teeth and received a laceration on his mouth/lower lip that required 25-30 stitches.

- 18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:
 - 1) Not staying alert of the task at hand.
 - 2) Employee on lower level not paying attention to surrounding and overhead hazards.
- 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

Poor planning or the lack of planning.

20. LIST THE ADDITIONAL INFORMATION:

MMS - FORM 2010 PAGE: 2 OF 3

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

None None

ESTIMATED AMOUNT (TOTAL):

Ġ

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

No Recommendations No Onsite Investigation

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:
- 25. DATE OF ONSITE INVESTIGATION:
- 26. ONSITE TEAM MEMBERS:

 29. ACCIDENT INVESTIGATION PANEL FORMED:

 NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Troy Trosclair

APPROVED

DATE: 20-APR-2007

MMS - FORM 2010 PAGE: 3 OF 3

EV2010R