UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

	OCCURRED DATE: 10-MAR-2007 TIME: 1525 HOURS OPERATOR: Chevron U.S.A. Inc.	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS.
	REPRESENTATIVE: Noel George TELEPHONE: (504) 592-6542 CONTRACTOR: REPRESENTATIVE: TELEPHONE:	INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
	LEASE: 00392 AREA: GI LATITUDE: BLOCK: 37 LONGITUDE:	X PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO.
5.	PLATFORM: R RIG NAME:	OTHER
6.	ACTIVITY: EXPLORATION(POE) DEVELOPMENT/PRODUCTION (DOCD/POD)	8. CAUSE:
7.	TYPE: HISTORIC INJURY X REQUIRED EVACUATION 1 LTA (1-3 days) LTA (>3 days RW/JT (1-3 days) X RW/JT (>3 days) 1	M HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H2O TREATING OVERBOARD DRILLING FLUID OTHER
	Other Injury FATALITY	9. WATER DEPTH: 60 FT.
	POLLUTION FIRE	10. DISTANCE FROM SHORE: 6 MI.
	LWC HISTORIC BLOWOUT UNDERGROUND SURFACE DEVERTER	11. WIND DIRECTION: SPEED: M.P.H. 12. CURRENT DIRECTION:
	SURFACE EQUIPMENT FAILURE OR PROCEDURES	SPEED: M.P.H.
	COLLISION ☐ HISTORIC ☐ >\$25K ☐ <=\$25K	13 SEA STATE: FT

MMS - FORM 2010 PAGE: 1 OF 3

EV2010R

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

Injured Person (IP) was flagging the crane while placing parts of another crane on deck. It is our findings that while the operator was walking backward, he was not observant of pinch points. After giving the signal to stop, the load continued to swing. The IP was able to avoid the load, but before he could his head was slightly pinned for a second. IP walked a few feet and collapsed. If he had taken the time to turn sideways while flagging the crane, he would have been aware of any obstacles and pinch points that he came in contact with. The IP was sent in for evaluation by his company doctor. He was placed on restricted duty.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Not alert to his surroundings.

Not paying attention to the load and his position.

- 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:
- 20. LIST THE ADDITIONAL INFORMATION:

MMS - FORM 2010 PAGE: 2 OF 3

05-SEP-2007

EV2010R

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

None

None

ESTIMATED AMOUNT (TOTAL):

Ġ

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The New Orleans District makes no recommendation to the Office of Safety Management.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:
- 25. DATE OF ONSITE INVESTIGATION:

28-MAY-2007

26. ONSITE TEAM MEMBERS:

Phil McLean /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Troy Trosclair

APPROVED

DATE: 28-AUG-2007

MMS - FORM 2010 PAGE: 3 OF 3