UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

	OCCURRED DATE: 19-JUN-2007 TIME: 1400 HOURS OPERATOR: Chevron U.S.A. Inc. REPRESENTATIVE: George, Noel TELEPHONE: (504) 592-6542 CONTRACTOR: REPRESENTATIVE: TELEPHONE:	STRUCTURAL DAMAGE X CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
	LEASE: G12119 AREA: VK LATITUDE: BLOCK: 786 LONGITUDE: PLATFORM:	PRODUCTION X DRILLING WORKOVER COMPLETION HELICOPTER X MOTOR VESSEL PIPELINE SEGMENT NO.
	RIG NAME: NABORS 87	OTHER
	ACTIVITY: EXPLORATION(POE) DEVELOPMENT/PRODUCTION (DOCD/POD) TYPE: HISTORIC INJURY X REQUIRED EVACUATION 1 LTA (1-3 days) LTA (>3 days RW/JT (1-3 days) X RW/JT (>3 days) 1	8. CAUSE: EQUIPMENT FAILURE X HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER
	Other Injury FATALITY	9. WATER DEPTH: 1754 FT.
	POLLUTION FIRE	10. DISTANCE FROM SHORE: 90 MI.
	LWC HISTORIC BLOWOUT UNDERGROUND	11. WIND DIRECTION: SW SPEED: 20 M.P.H.
	SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	12. CURRENT DIRECTION: SPEED: M.P.H.
	COLLISION HISTORIC >\$25K <=\$25K	13. SEA STATE: 5 FT.

MMS - FORM 2010 PAGE: 1 OF 3

EV2010R

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

On June 19, 2007, at 1400 hours, onboard the Nabors 87 rig, located at Chevron U.S.A. Inc's OCS-G 12119, Visoca Knoll (VK) 786, an employee was injured when a full cuttings box was set down on his right foot. The cuttings box was being lowered from the rig to the boat. The employee moved in too quickly to unhook a shackle and his two toes were caught under the cuttings box. Injured person was placed on 42 restricted work days.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Employee not following training/company policy on loading of equipment onto boat. He was suppose to be holding a tag line, and not approaching the cuttings box.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

Crane operator, other roustabouts should have seen his movements and stopped the operation.

20. LIST THE ADDITIONAL INFORMATION:

MMS - FORM 2010 PAGE: 2 OF 3

EV2010R 23-OCT-2007

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

None None

ESTIMATED AMOUNT (TOTAL):

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The District has no recommendations to MMS.

Insure employees are trained, and know their role in operation, along with possible hazards and consequences.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:
- 25. DATE OF ONSITE INVESTIGATION:
- 26. ONSITE TEAM MEMBERS:

No Onsite Investigation /

27. OPERATOR REPORT ON FILE: YES

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Troy Trosclair

APPROVED

DATE: 19-OCT-2007

MMS - FORM 2010 PAGE: 3 OF 3

EV2010R 23-OCT-2007