## UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

## **ACCIDENT INVESTIGATION REPORT**

|    | OCCURRED DATE: 07-NOV-2007 TIME: 0415 HOURS  OPERATOR: Energy XXI GOM, LLC REPRESENTATIVE: Verdun, Wayne TELEPHONE: (337) 296-4903  CONTRACTOR: Wood Group Production Services REPRESENTATIVE: Dronet, Scooter TELEPHONE: (800) 234-0100 | STRUCTURAL DAMAGE  CRANE  OTHER LIFTING DEVICE  DAMAGED/DISABLED SAFETY SYS.  INCIDENT >\$25K  H2S/15MIN./20PPM  REQUIRED MUSTER  SHUTDOWN FROM GAS RELEASE  OTHER |
|----|--|--|
| 3. | OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:   | 6. OPERATION:  |
|    | LEASE: G02947  AREA: MP LATITUDE: BLOCK: 73 LONGITUDE:  PLATFORM: A RIG NAME:  | X PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. OTHER   |
| 6. | ACTIVITY: EXPLORATION(POE)   | 8. CAUSE:  |
| 7. | TYPE:  HISTORIC INJURY  REQUIRED EVACUATION  LTA (1-3 days)  LTA (>3 days)  RW/JT (1-3 days)  X RW/JT (>3 days)  X RW/JT (>3 days)   | EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER                                |
|    | Other Injury  FATALITY   | 9. WATER DEPTH: <b>146</b> FT.   |
|    | POLLUTION<br>FIRE  | 10. DISTANCE FROM SHORE: 12 MI.  |
|    | EXPLOSION  LWC HISTORIC BLOWOUT  UNDERGROUND   | 11. WIND DIRECTION: SPEED: M.P.H.  |
|    | SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES   | 12. CURRENT DIRECTION: SPEED: M.P.H.   |
|    | COLLISION HISTORIC >\$25K <=\$25K  | 13. SEA STATE: FT.   |

MMS - FORM 2010 PAGE: 1 OF 3

EV2010R

## 17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

On November 7, 2007, at approximately 4:15, on Energy XXI GOM's, OCS-G 02947, Main Pass (MP) 73 A Platform, a contract employee tripped on a fire hose, twisted his leg and hip and struck his back on the corner of a tool box. Injured Person (IP) stayed offshore that morning and was sent to see a doctor later in the day. IP was put on restricted work duty and will have a follow-up visit on November 12, 2007.

## Sequence of Events:

Wood Group employee tripped over a fire hose twisting his leg and hip causing him to fall and strike his back on the corner of a tool box. He stayed offshore that morning and went in for crew change indicating that he was not in need of medical care. Wood Group contacted him later that day and decided to send him to a doctor. He was put on light duty and will return to see the doctor on November 12th for a follow-up visit.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Trip Hazard: Employee was not aware of trip hazard.

- 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:
- 20. LIST THE ADDITIONAL INFORMATION:

MMS - FORM 2010 PAGE: 2 OF 3

EV2010R 15-NOV-2007

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

None None

ESTIMATED AMOUNT (TOTAL):

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The New Orleans District makes no recommendations to MMS.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:
- 25. DATE OF ONSITE INVESTIGATION:
- 26. ONSITE TEAM MEMBERS:

No onsite investigations /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Troy Trosclair

APPROVED

DATE: 15-NOV-2007

MMS - FORM 2010 PAGE: 3 OF 3