UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

1.	OCCURRED DATE: 26-MAY-2008 TIME: 1045 HOURS	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE
2.	OPERATOR: Apache Corporation REPRESENTATIVE: Dugas, David TELEPHONE: (337) 354-8124 CONTRACTOR: REPRESENTATIVE: TELEPHONE:	DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
	LEASE: G04126 AREA: MP LATITUDE: BLOCK: 310 LONGITUDE: PLATFORM: A	PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO.
.	RIG NAME:	OTHER
	ACTIVITY: EXPLORATION(POE) DEVELOPMENT/PRODUCTION (DOCD/POD) TYPE: HISTORIC INJURY X REQUIRED EVACUATION 1 LTA (1-3 days) LTA (>3 days) RW/JT (1-3 days) X RW/JT (>3 days) X RW/JT (>3 days)	8. CAUSE: EQUIPMENT FAILURE X HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER
	Other Injury FATALITY POLLUTION	9. WATER DEPTH: 248 FT. 10. DISTANCE FROM SHORE: 41 MI.
	FIRE EXPLOSION LWC HISTORIC BLOWOUT UNDERGROUND	11. WIND DIRECTION: SPEED: M.P.H.
	SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	12. CURRENT DIRECTION: SPEED: M.P.H.
	COLLISION HISTORIC >\$25K <=\$25K	13. SEA STATE: FT.

MMS - FORM 2010 PAGE: 1 OF 3

EV2010R 12-JUN-2008

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

On May 26, 2008, at 1045 hours, on Apache Corporation's Lease OCS-G 4126, Main Pass (MP) Block 310, Platform A, an employee injured his right foot while moving a drum of degreaser. The drum fell on the Injured Person (IP) right foot fracturing two bones. IP was evacuated for evaluation. After examination by a physician, it was determined that the IP had fractured two small bones in his right foot. The IP was placed on restricted work duty.

Sequence of Events:

Employee was rolling a drum of degreaser off of a chemical skid onto a stack of boards in order to lay it down in a drum rack. While doing so, the drum slipped and fell about 6 inches onto his right foot. The drum hit his foot just behind the steel in his steel toed boot. After examination by a physician, it was determined that he had fractured two small bones in his right foot.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Human Error:

Inattention to job being performed.

- 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:
- 20. LIST THE ADDITIONAL INFORMATION:

MMS - FORM 2010 PAGE: 2 OF 3

EV2010R 12-JUN-2008

21. PROPERTY DAMAGED:

None None

ESTIMATED AMOUNT (TOTAL):

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The New Orleans District makes no recommendations to MMS.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:
- 25. DATE OF ONSITE INVESTIGATION:
- 26. ONSITE TEAM MEMBERS:

No onsite investigation /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

NATURE OF DAMAGE:

OCS REPORT:

30. DISTRICT SUPERVISOR:

Troy Trosclair

APPROVED

DATE: 11-JUN-2008

MMS - FORM 2010 PAGE: 3 OF 3

EV2010R 12-JUN-2008