UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION ACCIDENT INVESTIGATION REPORT

1. OCCURRED DATE: 05-JUN-2008 TIME: 1015 HOURS	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE
<pre>2. OPERATOR: GOM Shelf LLC REPRESENTATIVE: Garber, John TELEPHONE: (337) 354-8126 CONTRACTOR: Wood Group Production Services REPRESENTATIVE: Rogers, Jan TELEPHONE: (985) 868-4116</pre>	DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER
3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
 4. LEASE: 00129 AREA: GI LATITUDE: BLOCK: 41 LONGITUDE: 5. PLATFORM: A RIG NAME: 	X PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. OTHER
6. ACTIVITY: C EXPLORATION (POE)	8. CAUSE:
Image: Constraint of the second system of	EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER
<pre>Other Injury FATALITY</pre>	9. WATER DEPTH: FT.
POLLUTION FIRE	10. DISTANCE FROM SHORE: MI.
LWC HISTORIC BLOWOUT UNDERGROUND	11. WIND DIRECTION: W SPEED: 29 M.P.H.
SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	12. CURRENT DIRECTION: SPEED: M.P.H.
COLLISION HISTORIC >\$25K <- \$25K	13. SEA STATE: 7 FT.

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

On June 5, 2008, at 1000 hours on GOM Shelf LLC's Lease OCS 00129, Grand Isle (GI) Block 41, Platform A, an operator was injured during crew change, in unfavorable weather conditions, when he fell backwards out of the personnel basket causing his foot to be hung-up in the basket's webbing. Four employees were being lowered to the boat's stern deck in 5-7' seas with a 25 knot west wind. The personnel basket was being set on the stern deck when a wave's crest lifted the boat. Subsequently, the wave collapsed causing the employees to fall onto the stern deck as a result of the basket collapsing to the deck. Three of the employees fell forward bracing themselves to avoid any injury. The Injured Person (IP) fractured his ankle and fibula as a result of the weight of the IP's forward motion being restricted by the basket's webbing preventing ankle movement. The IP was evacuated for medical attention. Surgery was performed and the IP is currently resting at home.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Human Error:

The operator conducted a personnel basket crew change in unfavorable weather conditions. Both the sea state and winds were too strong to safely perform the operation.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

20. LIST THE ADDITIONAL INFORMATION:

MMS - FORM 2010

EV2010R

21.	PROPERTY	DAMAGED:
	TROTHREE	

None

None

\$

ESTIMATED AMOUNT (TOTAL):

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE: The New Orleans District makes no recommendations to MMS.

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

25. DATE OF ONSITE INVESTIGATION:

- 26. ONSITE TEAM MEMBERS: No onsite investigation. /
- 29. ACCIDENT INVESTIGATION PANEL FORMED: **NO** OCS REPORT:
 - 30. DISTRICT SUPERVISOR:

Troy Trosclair

APPROVED DATE: 07-OCT-2008