	UNITED STATES DEPARTMENT OF THE INTERIOR								
	MINERALS MANAGEMENT SERVICE								
	GULF OF MEXICO REGION								
	ACCIDENT INVESTIGATION REPORT								
1.	OCCURRED DATE: 10-JUN-2008 TIME: 2245 HOURS	STRUCTURAL DAMAGE							
2.	OPERATOR: Helis Oil & Gas Company, L.L.C. REPRESENTATIVE: Thornton, Cathy TELEPHONE: (281) 578-3388 CONTRACTOR: REPRESENTATIVE: TELEPHONE:	OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER							
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:							
4.	LEASE: G23857 AREA: EI LATITUDE: BLOCK: 56 LONGITUDE:	PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL							
5.	PLATFORM: G RIG NAME:	PIPELINE SEGMENT NO. X OTHER Facility Decommissioning							
	ACTIVITY: EXPLORATION(POE) DEVELOPMENT/PRODUCTION (DOCD/POD) TYPE: HISTORIC INJURY REQUIRED EVACUATION 1 LTA (1-3 days) 1 LTA (>3 days RW/JT (1-3 days) RW/JT (>3 days)	8. CAUSE: EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE X SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER							
	Other Injury	9. WATER DEPTH: 13 FT.							
	FATALITY POLLUTION FIRE	10. DISTANCE FROM SHORE: 22 MI.							
	LWC HISTORIC BLOWOUT UNDERGROUND	11. WIND DIRECTION: ENE SPEED: 8 M.P.H.							
	SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	12. CURRENT DIRECTION: E SPEED: 3 M.P.H.							
	COLLISION HISTORIC >\$25K <pre><=\$25K</pre>	13. SEA STATE: 1 FT.							

On June 10,2008, at approximately 2245 hrs, a rigger employed by International Offshore Services (IOS), on contract to Helis Oil and Gas Company, LLC, was injured while preparing the Eugene Island 56-G platform for routine platform/structural removal. Well No.3 is located adjacent to the "G "platform, and was connected by a catwalk that was later removed as part of the platform removal operation.

Activities at the time of the incident involved the transfer of a three (3) man rigger crew between the "G" platform and well jacket No.3. The personnel basket used to transfer the men was lifted from the jacket No.3 and placed on the top deck of the "G" platform using the "G" platform crane. After setting the personnel basket on the deck of the "G" platform, the IOS contractors exited the personnel basket toward the north side of the platform to a stairway leading down to a lower level of the platform. One of the IOS contractors was walking across the top deck of the platform when his left leg stepped into an open hatch way. The contractor's leg penetrated the hatch way to his shin just below the knee, receiving injuries to his left shin and the palm of his right hand. The injured contractor was treated by a medic onboard the barge that night, but the next day was sent in for further medical attention. The cut to his shin required two (2) stitches to close the wound. The contractor chose to go home instead of returning to work since he had only two (2) days remaining on his hitch before his regular scheduled time off.

At the time of the incident, the cover for the open hatch way was removed and being used to access the platform's main lifting pad eyes. The pad eyes had large slings attached in preparation for the platform facility to be lifted for removal, which was to occur at 0400 hours on June 11,2008. Due to delays the actual lifting and removal of the platform did not commence until 2330 hours on June 11th. The hatch way opening was not barricaded to protect personnel during that time frame. The only personnel access to the platform was by way of personnel basket. A job safety analysis (JSA) was performed prior to the operation, but did not include personnel transfer.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Lessee failed to properly barricade an access hatch way on the top deck of the "G" platform while preparing the platform for removal. Slings that were to be used to lift the platform were attached to the structural pad eyes in preparation of lifting the platform. Also, lighting was at a minimal since the only lights were the ones installed on the crane boom of the derrick barge. The crane had to be repositioned and while doing so the lights were directed away from the platform.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

Failure to properly communicate the work activities to all contractors prior to lifting and transferring personnel.

20. LIST THE ADDITIONAL INFORMATION:

MMS - FORM 2010

PAGE: 2 OF 5 19-AUG-2008

MMS - FORM 2010

PAGE: 3 OF 5 19-AUG-2008

EV2010R

NATURE OF DAMAGE:

None

None

ESTIMATED AMOUNT (TOTAL):

\$

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

MMS recommendations to Helis Oil & Gas Company L.L.C.

Communicate to all personnel during safety meetings and JSAs that extra precautions must be employed when working in areas with high risk of falling through unguarded opening.

MMS makes no recommendations to the Office of Safety Management (OSM).

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: YES
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

A G-110, Incident of Noncompliance was issued as an "After the Fact INC" to document that Helis Oil & Gas failed to protect health, safety and the environment by not performing operations in a safe and workmanlike manner as follows: Helis Oil & Gas failed to properly supervise and enforce proper safe work practices and procedures while performing job duties around unguarded open holes.

25. DATE OF ONSITE INVESTIGATION:

26. ONSITE TEAM MEMBERS: 29. ACCIDENT INVESTIGATION Jason A. Abshire / Tom Basey / PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Elliott S. Smith

APPROVED

DATE: **19-AUG-2008**

INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPRE CONTRACTOR REP X OTHER Deck F	PRESENTATIVE		INJURY FATALITY WITNESS	
NAME: HOME ADDRESS:				
CITY:		STATE	:	
WORK PHONE:	TOTA	L OFFSHORE	E EXPERIENCE:	YEARS
EMPLOYED BY:				
BUSINESS ADDRESS:				
CITY:		:	STATE:	
ZIP CODE:				

OPERATOR REPRESENTATIVE	INJURY FATALITY	
x OTHER Contract Welder	X WITNESS	
NAME :		
HOME ADDRESS:		
CITY:	STATE:	
WORK PHONE:	TOTAL OFFSHORE EXPERIENCE:	YEARS
EMPLOYED BY:		
BUSINESS ADDRESS:		
CITY:	STATE:	
ZIP CODE:		

EV2010R