

UNITED STATES DEPARTMENT OF THE INTERIOR
 MINERALS MANAGEMENT SERVICE
 GULF OF MEXICO REGION
ACCIDENT INVESTIGATION REPORT

1. OCCURRED

DATE: **23-OCT-2007** TIME: **0700** HOURS

2. OPERATOR:

Chevron U.S.A. Inc.

REPRESENTATIVE: **George, Noel**

TELEPHONE: **(504) 592-2670**

CONTRACTOR: **Quality Energy Services, LLC**

REPRESENTATIVE: **M.J. Plaisance**

TELEPHONE:

- STRUCTURAL DAMAGE
- CRANE
- OTHER LIFTING DEVICE
- DAMAGED/DISABLED SAFETY SYS.
- INCIDENT >\$25K
- H2S/15MIN./20PPM
- REQUIRED MUSTER
- SHUTDOWN FROM GAS RELEASE
- OTHER

3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR
ON SITE AT TIME OF INCIDENT:

6. OPERATION:

4. LEASE: **G05753**

AREA: **MO** LATITUDE:

BLOCK: **916** LONGITUDE:

- PRODUCTION
- DRILLING
- WORKOVER
- COMPLETION
- HELICOPTER
- MOTOR VESSEL
- PIPELINE SEGMENT NO.
- OTHER

5. PLATFORM:

RIG NAME:

6. ACTIVITY:

- EXPLORATION(POE)
- DEVELOPMENT/PRODUCTION
(DOCD/POD)

8. CAUSE:

- EQUIPMENT FAILURE
- HUMAN ERROR
- EXTERNAL DAMAGE
- SLIP/TRIP/FALL
- WEATHER RELATED
- LEAK
- UPSET H2O TREATING
- OVERBOARD DRILLING FLUID
- OTHER _____

7. TYPE:

- HISTORIC INJURY
- REQUIRED EVACUATION 1
- LTA (1-3 days)
- LTA (>3 days)
- RW/JT (1-3 days)
- RW/JT (>3 days) 1
- Other Injury 1 **Medical Treatment**

- FATALITY
- POLLUTION
- FIRE
- EXPLOSION

- LWC
- HISTORIC BLOWOUT
 - UNDERGROUND
 - SURFACE
 - DEVERTER
 - SURFACE EQUIPMENT FAILURE OR PROCEDURES

COLLISION HISTORIC >\$25K <=\$25K

- 9. WATER DEPTH: **61** FT.
- 10. DISTANCE FROM SHORE: **8** MI.
- 11. WIND DIRECTION:
SPEED: M.P.H.
- 12. CURRENT DIRECTION:
SPEED: M.P.H.
- 13. SEA STATE: FT.

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

On October 23, 2007, at approximately 7:00, at Chevron U.S.A. Inc.'s OCS-G 05753, Mobile (MO) 916 A Platform, an employee was injured when he smashed his own index finger on his left hand with a hammer and a hammer wrench, as a result of human error. Injured Person (IP) received stitches, no break or fracture. IP was placed on light duty.

Sequence of Events:

Employee was tightening up a flange and smashed his own left index finger with a hammer and hammer wrench. IP was sent in to seek medical attention. The Safety Supervisor with Quality Energy Services reported that the IP did not have a break or a fracture, however did receive stitches to the open cut on his finger. IP has been on light duty since the accident and is expected to be fully released once he has his follow up visit this week.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Human Error:

- 1) Placing hand near striking point.
- 2) Inattention to work being performed.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

20. LIST THE ADDITIONAL INFORMATION:

21. PROPERTY DAMAGED:

None

NATURE OF DAMAGE:

None

ESTIMATED AMOUNT (TOTAL):

\$

22. RECOMMENDATIONS TO PREVENT RECURRENCE NARRATIVE:

The New Orleans District makes no recommendations to MMS.

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: **NO**

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

25. DATE OF ONSITE INVESTIGATION:

26. ONSITE TEAM MEMBERS:

No onsite Investigation /

29. ACCIDENT INVESTIGATION

PANEL FORMED: **NO**

OCS REPORT:

30. DISTRICT SUPERVISOR:

Troy Trosclair

APPROVED

DATE: **07-NOV-2007**