

Appendix A



Photographs 1 and 2: View of the Delaware River along the western portion of the Crown Vantage Landfill site, August 11, 2005



Photograph 3: Riprap on the western portion of the Crown Vantage Landfill site, October 26, 2004



Photograph 4: Flyash on the Crown Vantage Landfill site, October 26, 2004



Photograph 5: View of fallen fence posts on the western portion of the Crown Vantage Landfill site, August 11, 2005



Photograph 6: Fence with flood debris on the western portion of the Crown Vantage Landfill site, August 11, 2005



Photographs 7 and 8: Half-buried disintegrated drums on the Crown Vantage Landfill site, October 26, 2005



Photographs 9 and 10: Warning signs posted along the western portion of the Crown Vantage Landfill site, August 11, 2005



Photograph 11: Flood debris on the Crown Vantage Landfill site, October 26, 2004



Photograph 12: Fence with flood debris on the western portion of the Crown Vantage Landfill site, August 11, 2005



Photographs 13 and 14: Evidence of adult and child shoe washed ashore on the Crown Vantage Landfill site, August 11, 2005



Photograph 15: NJDHSS staff member's steel-toed safety shoes following the site visit to the Crown Vantage Landfill, August 11, 2005