



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
612 EAST LAMAR BLVD, SUITE 400
ARLINGTON, TEXAS 76011-4125

September 2, 2008

Rick A. Muench, President and
Chief Executive Officer
Wolf Creek Nuclear Operating Corporation
P.O. Box 411
Burlington, KS 66839

SUBJECT: MIDCYCLE PERFORMANCE REVIEW AND INSPECTION PLAN -
WOLF CREEK GENERATING STATION

Dear. Mr. Muench:

On August 5, 2008, the NRC staff completed its performance review of Wolf Creek Generating Station for the first half of the calendar year 2008 assessment cycle. Our technical staff reviewed performance indicators for the most recent quarter and inspection results over the previous 12 months. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility.

This performance review and enclosed inspection plan do not include security information. A separate letter designated and marked as "Official Use Only - Security-Related Information" will include the security cornerstone review and resultant inspection plan.

Plant performance for the most recent quarter at Wolf Creek Generating Station was within the Licensee Response Column of the NRC's Action Matrix, based on all inspection findings being classified as having very low safety significance (Green) and all performance indicators indicating performance at a level requiring no additional NRC oversight (Green).

In our annual performance assessment letter dated March 3, 2008, a substantive crosscutting issue in the area of human performance was identified based on a number of findings associated with the work practices component of the human performance area specifically related to the failure to use and/or communicate human error prevention techniques and the failure to communicate expectations regarding procedural compliance. The crosscutting theme associated with the failure to use and/or communicate human error prevention techniques was also discussed during the 2006 annual assessment and the 2007 midcycle assessment. During this current assessment period, we noted that the effectiveness of your corrective actions appeared adequate to address this issue as evidenced by the identification of only one finding in the last 6 months of the assessment period involving either theme. Your corrective action included implementation of a human performance initiative to address the adverse trend, development of a coaching handbook on human performance, more management observations and initiating human performance indicators. Based on your corrective actions and the apparent effectiveness as demonstrated by the observed improvement, the substantive crosscutting issue associated with the work practices component is closed.

While it appears that the actions you implemented to address the theme associated with the work practices component were effective, we have concerns about your overall effectiveness in resolving human performance issues at Wolf Creek, as demonstrated by our identification of 14 additional findings related to other human performance components. Seven findings were related to the resources component of the human performance area. Five of these findings had a common theme related to failure to have complete, accurate, and up-to-date documentation, procedures, and/or work packages. While we have seen some effectiveness from your corrective actions, the overall trend with human performance and the identification of a new theme are of concern. Based on these findings with the common theme, the NRC staff has identified a new substantive crosscutting issue in the human performance area associated with resources at Wolf Creek. These findings occurred in the mitigating systems and initiating events cornerstones. Examples include an inadequate surveillance procedure that did not include all emergency core cooling system vent valves, a procedure that did not include an acceptance criteria for gaps in the containment sump, an inadequate procedure that resulted in the loss of all condensate pumps and a subsequent reactor trip, and an inadequate switchyard maintenance procedure that lead to a loss of offsite power. This new substantive crosscutting issue will remain open until we determine, through implementation of focused baseline inspections, that corrective actions have been effective.

In the 2007 annual assessment letter, dated March 3, 2008, the NRC identified a crosscutting theme associated with the corrective action program component of the problem identification and resolution area related to the failure to implement corrective action with a low threshold to allow for the complete, accurate, and timely resolution of issues. At that time, the NRC did not identify a substantive crosscutting issue because this theme represented a recent performance trend. Once identified, you placed the issue into your corrective action program and began developing action to address this issue. However, because of the number of findings, the presence of three common themes, and the ineffectiveness of your corrective actions during the current performance period, the NRC staff identified a substantive crosscutting issue in the problem identification and resolution area at Wolf Creek. The NRC staff identified 19 findings associated with the corrective action program component of the problem identification and resolution area. Five of these findings repeated the common theme discussed in the 2007 assessment letter associated with implementing a program with a low enough threshold for identifying problems. Seven had a common theme associated with the thoroughness of problem evaluations. The remaining seven had a common theme associated with the appropriateness of corrective actions. All of these findings were associated with the Mitigating System Cornerstone. These deficiencies resulted in failure to properly translating vortexing parameters into calculations, failure to adequately demonstrate no common cause failure mechanism existed between emergency diesel generators, an inadequate root cause assessment for emergency core cooling system voiding issues, sole reliance on engineering judgment to determine that a void stream would have no affect on pump performance, and several examples of failing to implement adequate corrective action for NRC identified issues.

Although your staff was informed of our concerns related to this adverse trend of failing to implement a program with a low enough threshold for identifying problems in our March 3, 2008, annual assessment letter, your immediate actions to address this adverse trend in problem identification and resolution were not effective since we continued to identify findings associated with this and two additional common themes. We noted that your improvement initiative, which collectively manages your overall plans for improvement, was not developed until July 2008. We understand that actions associated with this plan are in the early stage of implementation and have not yet proven effective. As a result, this substantive crosscutting issue will remain open until we determine, through implementation of the focused baseline inspections, that

corrective action implemented in accordance with your improvement initiative have been effective.

The enclosed inspection plan details the inspections, less those related to physical protection scheduled through December 31, 2009. The inspection plan is provided to allow for the resolution of any scheduling conflicts and personnel availability issues well in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last 9 months of the inspection plan are tentative and may be revised at the end-of-cycle review.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

If circumstances arise which cause us to change the inspection plan, we will contact you to discuss the change as soon as possible. Please contact Vincent Gaddy of my staff at 817-860-8141 with any questions you may have regarding this letter or the inspection plan.

Sincerely,



Dwight D. Chamberlain, Director
Division of Reactor Projects

Docket: 50-482
License: NPF-42

Enclosure: Wolf Creek Inspection/ Activity Plan

cc w/Enclosure
Vice President Operations/Plant Manager
Wolf Creek Nuclear Operating Corporation
P.O. Box 411
Burlington, KS 66839

Jay Silberg, Esq.
Pillsbury Winthrop Shaw Pittman LLP
2300 N Street, NW
Washington, DC 20037

Supervisor Licensing
Wolf Creek Nuclear Operating Corporation
P.O. Box 411
Burlington, KS 66839

Chief Engineer
Utilities Division
Kansas Corporation Commission
1500 SW Arrowhead Road
Topeka, KS 66604-4027

Office of the Governor
State of Kansas
Topeka, KS 66612

Attorney General
120 S.W. 10th Avenue, 2nd Floor
Topeka, KS 66612-1597

County Clerk
Coffey County Courthouse
110 South 6th Street
Burlington, KS 66839

Chief, Radiation and Asbestos
Control Section
Kansas Department of Health and
Environment
Bureau of Air and Radiation
1000 SW Jackson, Suite 310
Topeka, KS 66612-1366

Wolf Creek
Inspection / Activity Plan
09/01/2008 - 12/31/2009

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates Start	Planned Dates End	Inspection Type
	EB2-05T - TRIENNIAL FIRE PROTECTION		6			
1	IP 7111105T	Fire Protection [Triennial]		09/08/2008	09/12/2008	Baseline Inspections
1	IP 7111105T	Fire Protection [Triennial]		09/29/2008	10/03/2008	Baseline Inspections
1	IP 7111105T	Fire Protection [Triennial]		10/20/2008	10/24/2008	Baseline Inspections
	RP TEAM - RADIATION SAFETY TEAM INSPECTION		4			
1	IP 2515173	Review of the Implementation of the Industry Ground Water Protection Voluntary Initiative		09/08/2008	09/12/2008	Generic Safety Inspecti
1	IP 7112103	Radiation Monitoring Instrumentation and Protective Equipment		09/08/2008	09/12/2008	Baseline Inspections
1	IP 7112201	Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems		09/08/2008	09/12/2008	Baseline Inspections
1	IP 7112202	Radioactive Material Processing and Transportation		09/08/2008	09/12/2008	Baseline Inspections
1	IP 7112203	Radiological Environmental Monitoring Program (REMPP) And Radioactive Material Control Program		09/08/2008	09/12/2008	Baseline Inspections
	RP-ORS2 - OCCUPATIONAL RADIATION SAFETY - ALARA		1			
1	IP 7112101	Access Control to Radiologically Significant Areas		10/06/2008	10/10/2008	Baseline Inspections
1	IP 7112102	ALARA Planning and Controls		10/06/2008	10/10/2008	Baseline Inspections
1	IP 71151-OR01	Occupational Exposure Control Effectiveness		10/06/2008	10/10/2008	Baseline Inspections
1	IP 71151-PR01	RETS/ODCM Radiological Effluent		10/06/2008	10/10/2008	Baseline Inspections
	REQVAL - BIENNIAL REQUALIFICATION		3			
1	IP 7111111B	Licensed Operator Requalification Program		10/20/2008	10/24/2008	Baseline Inspections
	EP2 - EP PROGRAM		1			
1	IP 7111402	Alert and Notification System Testing		12/15/2008	12/19/2008	EP Baseline Inspection
1	IP 7111403	Emergency Response Organization Augmentation Testing		12/15/2008	12/19/2008	EP Baseline Inspection
1	IP 7111404	Emergency Action Level and Emergency Plan Changes		12/15/2008	12/19/2008	EP Baseline Inspection
1	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies		12/15/2008	12/19/2008	EP Baseline Inspection
1	IP 71151-EP01	Drill/Exercise Performance		12/15/2008	12/19/2008	Baseline Inspections
1	IP 71151-EP02	ERO Drill Participation		12/15/2008	12/19/2008	Baseline Inspections
1	IP 71151-EP03	Alert & Notification System		12/15/2008	12/19/2008	Baseline Inspections
	EP1 - EP EXERCISE INSPECTION		3			
1	IP 7111401	Exercise Evaluation		06/01/2009	06/05/2009	EP Baseline Inspection
1	IP 7111404	Emergency Action Level and Emergency Plan Changes		06/01/2009	06/05/2009	EP Baseline Inspection
1	IP 71151	Performance Indicator Verification		06/01/2009	06/05/2009	Baseline Inspections
	EB1-17 - 50.59 & MODS		2			
1	IP 7111117	Evaluations of Changes, Tests, or Experiments and Permanent Plant Modifications		07/20/2009	07/31/2009	Baseline Inspections
	EXAM - INITIAL EXAM		6			
1	X02419	INITIAL EXAM-WC (8/2009)		07/13/2009	07/17/2009	Not Applicable
1	X02419	INITIAL EXAM-WC (8/2009)		08/17/2009	08/21/2009	Not Applicable

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.

Wolf Creek

Inspection / Activity Plan
 09/01/2008 - 12/31/2009

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates Start End	Inspection Type
	EB1-08 - INSERVICE INSPECTION		2		
1	IP 2515172	Reactor Coolant System Dissimilar Metal Butt Welds		11/06/2009	Generic Safety Inspecti
1	IP 7111108P	Inservice Inspection Activities - PWR		11/06/2009	Baseline Inspections
	RP-ORS3 - OCCUPATIONAL RADIATION SAFETY - ALARA		1		
1	IP 7112101	Access Control to Radiologically Significant Areas		10/05/2009	Baseline Inspections
1	IP 7112102	ALARA Planning and Controls		10/09/2009	Baseline Inspections
1	IP 71151	Performance Indicator Verification		10/05/2009	Baseline Inspections
	RP-ORS4 - OCCUPATIONAL RADIATION SAFETY - ACCESS		1		
1	IP 7112101	Access Control to Radiologically Significant Areas		10/26/2009	Baseline Inspections
1	IP 7112102	ALARA Planning and Controls		10/26/2009	Baseline Inspections
1	IP 71151	Performance Indicator Verification		10/26/2009	Baseline Inspections
	RP-ORS5 - OCCUPATIONAL RADIATION SAFETY - ALARA		1		
1	IP 7112101	Access Control to Radiologically Significant Areas		12/07/2009	Baseline Inspections
1	IP 7112102	ALARA Planning and Controls		12/11/2009	Baseline Inspections
1	IP 71151	Performance Indicator Verification		12/07/2009	Baseline Inspections

This report does not include INPO and OUTAGE activities.
 This report shows only on-site and announced inspection procedures.