

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

March 4, 2002

Mr. J. V. Parrish Chief Executive Officer Energy Northwest P.O. Box 968; MD 1023 Richland, Washington 99352-0968

SUBJECT: ANNUAL ASSESSMENT - COLUMBIA GENERATING STATION

(REPORT 50-397/02-01)

Dear Mr. Parrish:

On February 12, 2002, the NRC staff completed its end-of-cycle plant performance assessment of Columbia Generating Station. The end-of-cycle review for Columbia Generating Station involved the participation of all technical divisions in evaluating performance indicators for the most recent quarter and inspection results for the period from April 1 through December 31, 2001. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility. This will provide you an opportunity to prepare for these inspections and to inform us of any planned inspections which may conflict with your plant activities.

As discussed in our previous annual assessment letter, dated May 29, 2001, this inspection and assessment cycle consisted of three quarters (i.e., the second, third, and fourth quarters of Calendar Year 2001) instead of the usual four quarters. This change was implemented in order to align the inspection and assessment cycle with the calender year beginning on January 1, 2002.

Overall, Columbia Generating Station operated in a manner that preserved public health and safety, and met all cornerstone objectives with moderate degradation in safety performance. Plant performance for the first quarter of the assessment cycle was within the Licensee Response Column of the NRC's Action Matrix. Performance for the final two quarters, however, was within the Degraded Cornerstone Column of the NRC's Action matrix. This is based on a substantially safety significant (Yellow) inspection finding in the Emergency Preparedness Cornerstone. This Yellow inspection finding involved a failure to develop and maintain plans and procedures that included a range of protective actions for members of the public located in the exclusion area. Specifically, for members of the public located inside the exclusion area during an emergency, Columbia Generating Station personnel failed to:

(1) adequately develop a reliable means of notification, (2) adequately develop a means for evacuation, and (3) adequately develop means for performing the radiological monitoring and decontamination of people evacuated from the site assessments.

Additionally, the staff has identified a potential adverse trend in the crosscutting area of human performance. This substantive crosscutting issue has been identified as a result of the multiple findings related to a lack of procedural adherence by numerous Columbia personnel. The NRC

found that, over the course of the assessment period, a number of Green findings and the Yellow finding included examples of poor human performance, specifically with regard to procedural adherence. These deficiencies were noted in several areas of Columbia's organization and affected multiple cornerstones.

Immediately following the terrorist attacks on the World Trade Center and the Pentagon, the NRC issued safeguards advisories recommending that nuclear power plant licensees go to the highest level of security, and all promptly did so. With continued uncertainty about the possibility of additional terrorist activities, the Nation's nuclear power plants, including Columbia Generating Station, remain at a high level of security. On February 25, 2002, the NRC issued an Order to all nuclear power plant licensees, requiring them to take certain additional interim compensatory measures to address the generalized high-level threat environment. These additional compensatory requirements will provide the NRC with reasonable assurance that public health and safety and the common defense and security continue to be adequately protected in the current generalized high-level threat environment. These requirements will remain in effect pending notification from the Commission that a significant change in the threat environment occurs or until the Commission determines that other changes are needed following a more comprehensive re-evaluation of current safeguards and security programs. To date we have monitored Energy Northwest's actions in response to the terrorist attacks through a series of audits. With the issuance of the Order, we will evaluate Energy Northwest's compliance with these interim requirements.

The enclosed inspection plan details the inspections scheduled through March 31, 2003. The plan includes a Supplemental Inspection during the week of May 13, 2002, to assess the causes associated with the corrective actions for the degraded cornerstone in emergency preparedness. In addition, inspection focus will be applied to the substantive crosscutting area of human performance. A Problem Identification and Resolution inspection has been scheduled for the fourth quarter of 2002 to follow up on the issues related to human performance. The inspection plan is provided to minimize the resource impact on your staff and to allow for scheduling conflicts and personnel availability to be resolved in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The last 6 months of the inspection plan is tentative and may be revised at the Midcycle Review meeting.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

If circumstances arise which cause us to change this inspection plan, we will contact you to discuss the change as soon as possible. Please contact William B. Jones at (817) 860-8147 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

/RA/

Ellis W. Merschoff Regional Administrator

Docket: 50-397 License: NPF-21

Enclosure:

Columbia Generating Station Inspection/ Activity Plan

cc w/enclosure: Chairman Energy Facility Site Evaluation Council P.O. Box 43172 Olympia, Washington 98504-3172

Rodney L. Webring (Mail Drop PE08) Vice President, Operations Support/PIO Energy Northwest P.O. Box 968 Richland, Washington 99352-0968

Greg O. Smith (Mail Drop 927M) Vice President, Generation Energy Northwest P.O. Box 968 Richland, Washington 99352-0968

D. W. Coleman (Mail Drop PE20) Manager, Regulatory Affairs Energy Northwest P.O. Box 968 Richland, Washington 99352-0968

Albert E. Mouncer (Mail Drop 1396) General Counsel Energy Northwest P.O. Box 968 Richland, Washington 99352-0968 Paul Inserra (Mail Drop PE20) Manager, Licensing Energy Northwest P.O. Box 968 Richland, Washington 99352-0968

Thomas C. Poindexter, Esq. Winston & Strawn 1400 L Street, N.W. Washington, D.C. 20005-3502

Bob Nichols
State Liaison Officer
Executive Policy Division
Office of the Governor
P.O. Box 43113
Olympia, Washington 98504-3113

Lynn Albin Washington State Department of Health P.O. Box 7827 Olympia, WA 98504-7827

John L. Erickson, Director Division of Radiation Protection Department of Health Airdustrial Center Building #5 P.O. Box 47827 Olympia, Washington 98504-7827

Max E. Benitz, Jr., Chairman Board of Benton County Commissioners P.O. Box 190 Prosser, Washington 99350

Sue Miller, Chair Board of Franklin County Commissioners 1016 North 4th Street Pasco, Washington 99301

Federal Emergency Management Agency Federal Regional Center John Pennington, Regional Director 130 228th Street, SW Bathell, Washington 98021-9796 Electronic distribution from ADAMS by RIV:

Regional Administrator (EWM)

DRP Director (KEB)

DRS Director (ATH)

Senior Resident Inspector (GDR)

Branch Chief, DRP/E (WBJ)

Senior Project Engineer, DRP/E (GAP)

Staff Chief, DRP/TSS (PHH)

RITS Coordinator (NBH)

B. Henderson, PAO (BWH)

W. A. Maier, RSLO (WAM)

C. J. Gordon (CJG)

DRS Branch Chiefs (GMG, ATG, CSM)

W. D. Travers, EDO (WDT)

M. Johnson, Chief, NRR/DIPM/IIPB (MRJ1)

R. K. Frahm, PPR Program Manager, NRR/DIPM/IIPB (RKF)

B. A. Boger, Associate Dir. for Inspection and Programs (BAB2)

B. W. Sheron, Associate Dir. for Project Licensing and Technical Analysis (BWS)

J. Shea, Chief, Regional Operations Staff, OEDO (JWS1)

S. Richards, NRR Project Director (SAR)

S. Dembek, Chief, Section 2, NRR/DLPM (SXD)

J. Cushing, NRR Project Manager (JXC9)

RidsNrrDipmlipb

Hard Copy:

Records Center, INPO

S:\DRP\DRPDIR\EOC 2002\Assessment Letters\COL.wpd

RIV:C:DRP/E	D:DRS	D:DRP	DRA	RA
WBJones;df	ATHowell	KEBrockman	TPGwynn	EWMerschoff
/RA/	/RA/	/RA/		/RA/
2/21/02	2/27/02	3/4/02	NA	3/4/02

Page 1 of 1 03/04/2002 13:15:09 Columbia Generating Station Inspection / Activity Plan

03/01/2002 - 03/30/2003

Report 22

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planne Start	d Dates End	Inspection Type
		LEMENTAL INSPECTION EP 95002	3	-		
2	IP 95002	Inspection For One Degraded Cornerstone Or Any Three White Inputs In A Strategic Performar A AND PIV	1	05/13/2002	05/17/2002	Supplemental Progran
2	IP 7112101	Access Control to Radiologically Significant Areas		06/24/2002	06/28/2002	Baseline Inspections
2	IP 71151	Performance Indicator Verification		06/24/2002	06/28/2002	Baseline Inspections
	EMB - BIENN	NAL MODS	2			
2	IP 7111117B PSB-EP1 - EP EX	Permanent Plant Modifications (ERCISE BASELINE INSPECTION	3	09/09/2002	09/13/2002	Baseline Inspections
2	IP 7111401	Exercise Evaluation		09/16/2002	09/20/2002	Baseline Inspections
2	IP 7111404	Emergency Action Level and Emergency Plan Changes		09/16/2002	09/20/2002	Baseline Inspections
2	IP 71151	Performance Indicator Verification		09/16/2002	09/20/2002	Baseline Inspections
	OB-IN - INTIAL	L EXAM PREP WEEK	2			
2	X02226	COLUMBIA INITIAL EXAM (09/02)		09/23/2002	09/27/2002	Not Applicable
	OB-IN - INITIA	L EXAMINATION	5			
2	X02226	COLUMBIA INITIAL EXAM (09/02)		10/07/2002	10/11/2002	Not Applicable
	RP-3 - ALARA	A	1			
2	IP 7112102	ALARA Planning and Controls		10/07/2002	10/11/2002	Baseline Inspections
	PSB-S1 - ACCE	SS AUTH/CONTROL, SEC PLAN, AND PIV	1			
2	IP 7113001	Access Authorization Program (Behavior Observation Only)		11/04/2002	11/08/2002	Baseline Inspections
2	IP 7113002	Access Control (Search of Personnel, Packages, and Vehicles: Identification and Authorization		11/04/2002	11/08/2002	Baseline Inspections
2	IP 7113004	Security Plan Changes		11/04/2002	11/08/2002	Baseline Inspections
2	IP 71151	Performance Indicator Verification		11/04/2002	11/08/2002	Baseline Inspections
	PBE-PIR - PROB	SLEM ID INSP	3			
2	IP 71152	Identification and Resolution of Problems		11/25/2002	11/29/2002	Baseline Inspections
	OB-RQ - REQU	AL INSPECTION	2			
2	IP 7111111B	Licensed Operator Requalification		12/09/2002	12/13/2002	Baseline Inspections
	EMB - TRIEN	INIAL FP	5			
2	IP 7111105T	Fire Protection		03/03/2003	03/07/2003	Baseline Inspections
2	IP 7111105T	Fire Protection		03/17/2003	03/21/2003	Baseline Inspections