



U.S. Department of Energy
Office of Civilian Radioactive Waste Management



Examination of Corrosion Products and the Alloy Surface after Crevice Corrosion of C-22 Alloy

Presented to:
210th Meeting of The Electrochemical Society

Presented by:
Xi Shan, Joe H. Payer
Case Western Reserve University
Cleveland, OH
USA

October 29-November 3, 2006
Cancún, Mexico

Acknowledgement and Disclaimer

- Support of the Science and Technology Program of the Office of the Chief Scientist (OCS), Office of Civilian Radioactive Waste Management (OCRWM), U.S. Department of Energy (DOE) is gratefully acknowledged. The work was performed under the Corrosion and Materials Performance Cooperative, DOE Cooperative Agreement Number: DE-FC28-04RW12252
- The views, opinions, findings, and conclusions or recommendations of authors expressed herein do not necessarily state or reflect those of the DOE/OCRWM/OCS



Key Acronyms

- PTFE – Polytetrafluoroethylene
- SEM – Scanning Electro Microscopy
- EDS – Energy Dispersive X-ray Spectroscopy
- AES – Auger Electron Spectroscopy
- XPS – X-ray Photoelectron Spectroscopy
- XRD – X-ray Diffraction
- ASTM – American Society for Testing and Materials



Objective

- An overall objective is to determine the evolution of corrosion damage, i.e. the severity, shape, location/distribution and damage profile
- Study is part of a program to analyze the evolution of localized corrosion damage over long periods of time
 - A set of coordinated projects is under way, and this study focuses on the post initiation stages of crevice corrosion, i.e. crevice propagation, stifling and arrest processes
- Results are presented here on the composition of corrosion products and the composition of the metal surface after localized corrosion



Approach

- The approach is to force the initiation of crevice corrosion by applying anodic polarization to a multiple crevice assembly (MCA)
- Results are reported here for alloy C-22, a Ni-Cr-Mo alloy, exposed to a high temperature, concentrated chloride solution



Materials and Test Condition

- **Materials: alloy C-22**

Composition of alloy C-22, wt%

Cr	Mo	Fe	W	Co	Mn	V	Si	S	P	C	Ni
21	13.1	3.8	2.8	2.1	0.25	0.011	0.024	0.005	0.006	0.0052	BAL

- **Test Conditions**

- 4M NaCl, open to air, 100°C
- Anodic polarization to $E = -0.150$ V-SCE, a potential above the repassivation potential of alloy C-22 for these test conditions
- The metal specimen and crevice formers are wetted with test solution prior to tightening the test assemblies
- PTFE tape covered ceramic was the crevice former




Experimental Methods

- Cyclic potentiodynamic polarization
 - with MCA specimens
- Crevice corrosion tests at constant potential
 - with MCA specimens
 - Polarize at potential more positive than the repassivation potential
 - Monitor corrosion by current vs. time measurement
- Post test exam-optical/macroscopic to 50x in binocular microscope
- Damage profile and 3-D reconstruction
 - InfiniteFocus microscope (IFM), an optical 3D measurement device
- Analyses of corroded alloy surfaces and corrosion products
 - SEM/EDS, AES, XPS, XRD
- Solution analysis
 - Inductively Coupled Plasma (ICP)



Test Cell and Specimen

Test Cell





MCA



- Two segmented washers
- Grade 2 Ti bolt and nuts
- Applied Torque: 70 in-lb


Crevice formers: after ASTM G48-03



- 12 contact plateaus (feet)
- ID: 9.9 mm OD: 15.9 mm Thickness: 6.3 mm
- Contact area: about 6 mm²/foot



Cyclic Potentiodynamic Polarization




- **Used as basis for applied potential during crevice corrosion tests**
- **Aggressive corrosion solution**
 - 4M NaCl (20wt%)
 - 100°C
- **Severe crevice former**
 - PTFE tape covered ceramic
 - Create tight crevice, 70 in-lb
- **Select E_{test} at 30 to 50mV above E_{repass}**
 - $E_{re-pass} = -0.182 \text{ V-SCE}$
 - $E_{test} = -0.150 \text{ V-SCE}$
- **Criteria for crevice corrosion during MCA test**
 - Hysteresis loop on reverse scan
 - Determination of repassivation potential
 - Visible damage under crevice former after test

E_{rp} : the potential where the reverse scan of the polarization curve intersects the forward scan

E_{br} : the potential at which a permanent rise in current density from the passive region is commenced



Initiation, Propagation and Arrest of Crevice Corrosion



- 4M NaCl, 100°C, $E = -0.150\text{ V-SCE}$, PTFE tape covered ceramic
- Three stages: incubation, propagation, repassivation
 - Incubation, $I \approx 0.5\ \mu\text{A}$ and less
 - Propagation, I increase up to 200 μA with many serrations (stifle/arrest events)
 - Repassivation, $I \approx 0.5\ \mu\text{A}$ and less
- Multiple initiation sites beneath crevice feet
- Stifling/arrest events during propagation
- Repassivation of entire specimen






Corrosion Depth Profile




$Q_{total} = 0.25$ coulomb/3 feet



$Q_{total} = 10$ coulomb/10 feet



$Q_{total} = 51$ coulomb/10 feet







$Q_{total} = 118$ coulomb/9 feet

- With increasing amount of corrosion, the corrosion profile became wider and deeper
- Corrosion initiated near edges under crevice former
- Multiple initiation sites found under the crevice feet
- Corrosion products in crevice at corroded areas and outside the crevice on uncorroded surface



AES Analysis Locations on Alloy C-22 Surface





Tested for 268.3 hours, total flow of charge 51 coulomb, 5.1 coulomb/foot on average

Position	Description
A	80 μ m penetration
B	30 μ m penetration
C	10 μ m penetration
D	on the island, no corrosion
E	stained area, border of corroded region
F	area exposed to test solution





AES Depth Profile in Deeper Corrosion Region



- Crevice corrosion penetration is about 80 μ m at position A
- Sample was ultrasonically cleaned with methanol before measurement
- AES depth profile of metal surface after loose corrosion products removed; shiny, metallic metal surface
- Passive film on the alloy surface (chromium-rich oxide) of approximately 2 - 8 nm
- Overall congruent dissolution of the alloy in active regions within the crevice
 - No preferential dissolution of elements on microscopic/macroscale
 - Formation of soluble and insoluble corrosion products
 - On nanoscale, Ni enrichment and Cr depletion at metal surface beneath the passive film





AES Depth Profile of Transition Area between Corroded and Uncorroded Regions



- At transition zone, a thin layer of corrosion products remained on surface
- Corrosion products contain high amounts of Mo and O and are depleted in Ni and Cr
- Ratio of Mo:O is approximately 1:3 (MoO_3)
- Composition is in agreement with the composition of corrosion products in the crevice measured by EDS





XPS Depth Profile of Freely Exposed Surface



- Measured on freely exposed area, position F
- Passive film on metal surface
- The depth profile is in agreement with the result measured by AES




XPS Depth Profile of Freely Exposed Surface



- For the top several nm, Cr exists as oxides
 - Cr2p^{3/2} 576.2 eV, Cr2p^{1/2} 585.8 eV, (Cr₂O₃)
- After about 10nm, Cr exists as metallic Cr
 - Cr2p^{3/2} 573.8 eV, Cr2p^{1/2} 583 eV, metallic Cr
- The amount of Ni on the surface is very small
- Except the top several nm, the binding energy of Ni does not change with depth,
 - Ni2p^{1/2} 869.6eV, Ni2p^{3/2} 852.4 eV, metallic Ni



XPS Depth Profile of Freely Exposed Surface




- Small amount of Mo exists on the top surface as oxide
 - Mo3d^{5/2} 231.8 eV
- Mo exists as metallic when depth is more than 10nm
 - Mo3d^{5/2} 230.6 eV, Mo3d^{3/2} 227.4 eV
- No W found on the top surface
- W exists as metallic when depth is more than 10nm
 - W4d^{5/2} 255.6 eV, W4d^{3/2} 241.6 eV



Corrosion Products of Alloy C-22



corrosion products on uncorroded metal surface




corrosion products with crevice

- 4M NaCl, 100°C, E=-0.150 V-SCE, PTFE tape covered ceramic crevice former
- Loose, black corrosion products were found in the crevice after test
- Green corrosion products were found around the crevice on the uncorroded metal after test
- Green corrosion precipitation was found in test solution after test
- Solution color changed to light green during test




EDS Analysis of Alloy C-22 Crevice Corrosion



Composition at different locations, at%


Location	O	Cr	Fe	Ni	Co	Mo	W	Na	Cl	Ni/Cr	Mo/Cr	W/Cr
A	21.4	20.7	3.4	43.9	1.8	7.0	1.0	0.5	0.3	2.1	0.3	0.05
B	67.9	7.8	0.2	0.9	0.03	16.2	1.8	1.0	3.7	0.1	2.1	0.2
C	60.1	11.0	0.6	6.2	0.3	16.5	1.6	0	2.4	0.6	1.5	0.15
D	11.7	22.7	3.8	51.1	2.3	7.4	0.7	0	0.3	2.3	0.3	0.03




- 4M NaCl, 100°C, E=-0.150 V-SCE, PTFE tape covered ceramic crevice former
- Tested for 251.6 hours, total flow of charge 59.8 coulomb to the whole specimen
- Loose, black corrosion products found under the crevice former after test
- Compare thick corrosion products layer (B) with composition of alloy C-22
 - Corrosion products are high in O
 - Depleted in Ni, Cr and Fe, and enriched in Mo and W




Corrosion Products in Crevice



corroded metal side



crevice former side






	O	Cr	Fe	Ni	Co	Mo	W
corroded metal side, at%	69.6	4.5	0.2	0.3	0	20.7	4.0
crevice former side, at%	70.0	3.4	0.1	0.3	0	21.6	3.6

- 4M NaCl, 100°C, E=-0.150 V-SCE, PTFE tape covered ceramic crevice former
- The corrosion products in the crevice show different morphologies on the side contacting the crevice former and on the side contacting the metal
 - Smooth surface on the crevice former side
 - Surface with fine micro structures were found on the side contacting the corroded metal
- EDS results show no composition difference between the two morphologies



EDS Analysis of Alloy C-22 Corrosion Products outside of Crevice on Uncorroded Metal



sample	O	Cr	Fe	Ni	Mo	W	Co
Site A, at%	52.3	16.7	1.4	17	5.5	0.5	0.6
exposed un-tarnished area, at%	10.8	22.5	4	51.8	7.2	0.9	1.8

- 4M NaCl, 100°C, E=-0.15V-SCE, PTFE tape covered ceramic crevice former
- Corrosion products deposited on uncorroded metal outside of crevice
- Tested for 462.7 hours, total flow of charge 118 coulomb, 13.1 coulomb/foot on average
- Green corrosion products found outside the crevice former after test
- Corrosion products contain high amount of oxygen
- High in Cr/Ni, Mo/Ni ratio compared to alloy C-22



XRD Results on Corrosion Products

- **XRD on the black corrosion products in the crevices**
 - Only NaCl and C-22 was identified
 - Work in process
- **XRD on green precipitation in solution**
 - Only NaCl was identified
 - Others peaks were broadened
 - Work in process



Solution Composition after Crevice Test

Sample	Q, coulomb	Ni	Cr	Mo	W	Fe	Co
A265 solution	94.2	10.8	0.117 (92)	0.456 (24)	ND	0.13 (83)	0.374 (29)
		10.4	0.137 (76)	0.434 (24)	ND	0.127 (82)	0.361 (29)
A266 solution	59.8	4.18	ND	0.739 (5.7)	ND	ND	0.12 (35)
		4.28	ND	0.722 (5.9)	ND	ND	0.110 (39)
4M NaCl	n/a	ND	ND	0.06	ND	ND	ND
C-22	n/a	57	21 (2.7)	13.1 (4.4)	2.8 (20)	3.8 (15)	2.1 (27)

Note:

1. The numbers in parenthesis are the ratio of nickel to the element: Ni:Metal
2. Concentration for A265, A266 solution is mg/L, for C-22 is wt%

- 4M NaCl, 100°C, E=-0.150 V-SCE, PTFE tape covered ceramic crevice former
- Inductively Coupled Plasma (ICP) method
- Ni is the main element dissolved into the solution
 - Ni > Co > Mo > Fe > Cr > W
- Preliminary results, work in progress



Conclusion

- Loose, black corrosion products found under the crevice former after test
 - Depleted in Ni, Cr and Fe,
 - Enriched in Mo and W
 - Contains high amount of oxygen
- Passive film (chromium oxide) formed on the alloy surface in the repassivated crevice corrosion region
- After 10's μm of crevice corrosion penetration, a thin (several nm) zone of Ni enrichment and Cr depletion within the metal was observed; however, on the micro/macro scales, the alloy dissolution occurred by a uniform, non-selective dissolution
- Corrosion products outside the crevice on uncorroded metal has high Cr/Ni, Mo/Ni ratio and high amounts of oxygen
- Analysis of the test solution shows Ni as the main species (Ni^{++})

