

Appendix K

**Appendix K**  
**Asbestos Survey Field Data**

***Asbestos Survey Field Data Sheet-Navigation Bridge Deck  
NS-Savannah  
Fort Eustis, VA***

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSS-NBD-FT-1A, -1B, -1C	Green ,9"x9" floor tile with white lines and associated mastics	Throughout Navigation Bridge Deck	Fair		x
NSS-NBD-MM-2A, -2B, -2C	White wall board with pinhole pattern	Navigation Bridge Deck-Gyro Radar Room	Good		x
NSS-NBD-TSI-3A, -3B, -3C	Straight run pipe insulation associated with piping above ceilings	Navigation Bridge Deck above ceiling	Good	x	
NSS-NBD-TSI-4A, -4B, -4C	Elbow pipe insulation associated with piping above ceiling	Navigation Bridge Deck above ceiling	Good	x	
NSS-NBD-MM-5A, -5B, -5C	White, drywall associated with walls (1' thickness)	Navigation Bridge Deck Staterooms	Good	x	
NSS-NBD-MM-6A, -6B, -6C	White, drywall associated with ceiling	Navigation Bridge Deck Staterooms	Good	x	
NSS-NBD-MM-7A, -7B, -7C	Brown mastic associated with baseboard molding	Throughout Navigation Bridge Deck	Good		x

*Asbestos Survey Field Data Sheet-Navigation Bridge Deck  
 NS-Savannah  
 Fort Eustis, VA*

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSS-NBD-MM-8A, -8B, -8C	White sub-floor (baseboard)	Throughout Navigation Bridge Deck	Good	x	
NSS-NBD-TSI-9A, -9B, -9C	Straight run pipe insulation associated with generator	Navigation Bridge Deck-Generator Room	Good	x	
NSS-NBD-TSI-10A, -10B, -10C	Elbow pipe insulation associated with generator	Navigation Bridge Deck-Generator Room	Good	x	

Due to time limitations, physical samples were not taken of this deck. The materials that were observed are similar to materials that are located on other decks of the ship. The table identifies samples that ERM would have sampled had time permitted.

Note: All pipes are recorded as total diameter of the pipe and the associated insulation.

***Asbestos Survey Field Data Sheet-Boat Deck  
NS-Savannah  
Fort Eustis, VA***

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSS-BoatDeck-FT-1A, -1B, -1C	Black 18"x18" floor tile with white specks and associated mastic	Boat Deck stairwell	Good		x
NSS-BoatDeck-MM-2A, -2B, -2C	White, drywall associated with the wall (1' thickness)	Boat Deck Cabins	Good	x	
NSS-BoatDeck-MM-3A, -3B, -3C	White, drywall associated with ceiling (1/2" thickness)	Boat Deck Staterooms	Good	x	
NSS-BoatDeck-MM-4A, -4B, -4C	White sub-floor (baseboard)	Throughout Boat Deck	Good		x
NSS-BoatDeck-FT-5A, -5B, -5C	Green, 9x9 floor tile with white lines and associated mastic	Throughout Boat Deck	Poor		x
NSS-BoatDeck-MM-6A, -6B, -6C	Brown mastic associated with baseboard molding	Throughout Boat Deck	Good		x
NSS-BoatDeck-TSI-7A, -7B, -7C	Straight run pipe insulation above ceiling	Boat Deck above ceiling	Good	x	

*Asbestos Survey Field Data Sheet-Boat Deck  
NS-Savannah  
Fort Eustis, VA*

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSS-BoatDeck-TSI-8A, -8B, -8C	Elbow pipe insulation	Boat Deck above ceiling	Good	x	

Note: All pipes are recorded as total diameter of the pipe and the associated insulation.

***Asbestos Survey Field Data Sheet-Promenade Deck  
NS-Savannah  
Fort Eustis, VA***

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSS-PromDeck-FT-1A, -1B, -1C	Dark green, 18" x18" floor tile with white lines and associated mastics	Promenade Deck-Veranda	Good		x
NSS-PromDeck-FT-2A, -2B, -2C	White, 18"x18" floor tile with white lines and associated mastics	Promenade Deck-Veranda	Good		x
NSS-PromDeck-MM-3A, -3B, -3C	Black sub-floor (baseboard)	Promenade Deck-Throughout floor	Good		x
NSS-PromDeck-MM-4A, -4B, -4C	White, 4'x4' ceiling panels with pinholes	Promenade Deck-Veranda and Main Lounge	Good		x
NSS-PromDeck-MM-5A, -5B, -5C	White drywall (1/2" thickness) associated with walls	Promenade Deck-Veranda	Good	x	
NSS-PromDeck-MM-6A, -6B, -6C	White drywall (1" thickness) associated with ceilings	Promenade Deck-Veranda	Good	x	
NSS-PromDeck-MM-7A, -7B, -7C	Brown mastic associated with baseboard molding	Promenade Deck-Veranda and Main Lounge	Good		x

Note: All pipes are recorded as total diameter of the pipe and the associated insulation.

*Asbestos Survey Field Data Sheet-Surface Deck  
NS-Savannah  
Fort Eustis, VA*

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSSSurfaceDeck-MM-1A, -1B, -1C	Black asphalt sealant associated with cargo hold doors	Surface Deck	Good		x

***Asbestos Survey Field Data Sheet-Deck A  
NS-Savannah  
Fort Eustis, VA***

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSSDeckA-FT-1A, -1B, -1C	Green, 9"x9" floor tile with white lines and associated mastic	Deck A- Throughout infirmary	Good		x
NSSDeckA-TSI-2A, -2B, -2C	Straight run pipe insulation	Deck A- Piping located above ceiling	Good	x	
NSSDeckA-TSI-3A, -3B, -3C	Elbow pipe insulation	Deck A- Piping located above ceiling	Good	x	
NSSDeckA-FT-4A, -4B, -4C	Brown, 9"x9" floor tile with white specks and associated mastic	Deck A-Throughout hallways adjacent to staterooms	Good		x
NSSDeckA-FT-5A, -5B, -5C	Black, 9"x9" floor tile with white specks and associated mastic	Deck A-Throughout hallways adjacent to staterooms	Good		x
NSSDeckA-FT-6A, -6B, -6C	Light brown, 9"x9" floor tile with white specks and associated mastic	Deck A-Throughout hallways adjacent to staterooms	Good		x
NSSDeckA-FT-7A, -7B, -7C	Tan, "9x9" floor tile with white brown specks and associated mastic	Deck A-Throughout hallways adjacent to staterooms	Good		x



*Asbestos Survey Field Data Sheet-Deck A  
 NS-Savannah  
 Fort Eustis, VA*

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSSDeckA-MM-8A, -8B, -8C	White drywall (1/2" thickness) associated with ceilings	Deck A	Good	x	
NSSDeckA-MM-9A, -9B, -9C	White drywall (1" thickness) associated with walls	Deck A	Good	x	
NSSDeckA-FT-10A, -10B, -10C	White, 9"x9" floor tile and associated mastic	Deck A- Main Lobby	Good		x
NSSDeckA-FT-11A, -11B, -11C	Gray, 18"x18" floor tile and associated mastic	Deck A -Main Lobby	Good		x
NSSDeckA-FT-12A, -12B, -12C	Black, 9"x9" floor tile and associated mastic	Deck A- Main Lobby	Good		x
NSSDeckA-CT-13A, -13B, -13C	White, 2'x3' ceiling panel with pinholes	Deck A- Main Lobby	Good		x
NSSDeckA-MM14A, -14B, -14C	Black sub-floor (baseboard)	Deck A - Main Lobby and forward areas	Good		x

**Asbestos Survey Field Data Sheet-Deck A**  
**NS-Savannah**  
**Fort Eustis, VA**

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSSDeckA-FT-15A, -15B, -15C	Tan, 9"x9" floor tile and associated mastic	Deck A- Lab Assistant Office	Poor		x
NSSDeckA-FT-16A, -16B, -16C	Orange, 9"x9" floor tile and associated mastic	Deck A- Barber Shop	Good		x
NSSDeckA-FT-17A, -17B, -17C	Brown, 9" x9" floor tile with black and white specks and associated mastic	Deck A- Port and starboard side stairwells	Fair		x
NSSDeckA-FT-18A, -18B, -18C	Tan, 9" x9" floor tile with brown specks and associated mastic	Deck A- Port and starboard side stairwells	Fair		x
NSSDeckA-FT-19A, -19B, -19C	Tan, 9" x9" floor tile with brown specks and associated mastic	Deck A- Staterooms rear of Main Lobby and Pursers Office	Fair		x
NSSDeckA-MM-20A, -20B, -20C	Brown mastic associated with baseboard molding	Deck A	Good		x
NSSDeckA-MM-21A, -21B, -21C	White sub-floor (baseboard)	Deck A- Area rear of Main Lobby	Good	x	
NSSDeckA-FT-22A, -22B, -22C	Red, 9"x9" floor tile with white lines and associated mastic	Deck A- Forward port side stairwell	Good		x

Note: All pipes are recorded as total diameter of the pipe and the associated insulation.

***Asbestos Survey Field Data Sheet-Deck B  
 NS-Savannah  
 Fort Eustis, VA***

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSS-B Deck-FT-1A, -1B, -1C	Blue, 9"x9" floor tile with white lines	Deck B- Dining Room	Fair		x
NSS-B Deck-Mastic-2A, -2B, -2C	Mastic associated with blue 9"x9" floor tile with white lines	Deck B-Dining Room	Fair		x
NSS-B Deck-FT-3A, -3B, -3C	White, 18" x18" floor tile	Deck B-Dining Room	Fair		x
NSS-B Deck-Mastic-4A, -4B, -4C	Mastic associated with 18" x18" floor tile	Deck B-Dining Room	Fair		x
NSS-B Deck-Mastic-5A, -5B, -5C	Brown mastic associated with baseboard molding	Deck B-Dining Room	Fair		x
NSS-B Deck- FT-6A, -6B, -6C	Light green, 9" x9" floor tile with white specks	Deck B- Stateroom hallway rear of Cargo Loading Passage	Fair		x
NSS-B Deck-Mastic-7A, -7B, -7C	Mastic associated with light green 9x9 floor tile with white specks	Deck B- Stateroom hallway rear of Cargo Loading Passage	Fair		x

**Asbestos Survey Field Data Sheet-Deck B**  
**NS-Savannah**  
**Fort Eustis, VA**

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSS-B Deck-MM-8A, -8B, -8C	Brown mastic associated with stair treads	Deck-B Dining Room	Good		x
NSS-B Deck-Fiberboard-9A, -9B, -9C	White fiberboard padding beneath floor tile	Deck B- Area rear of Cargo Loading Passage	Fair	x	
NSS-B Deck-FT-10A, -10B, -10C	Dark green, 9" x9" floor tile with white lines	Deck B- Area rear of Cargo Loading Passage	Fair		x
NSS-B Deck-Mastic-11A, -11B, -11C	Mastic associated with 9" x9" floor tile with white lines	Deck B- Area rear of Cargo Loading Passage	Fair		x
NSS-B Deck-FT-12A, -12B, -12C	Gray, 9"x9" floor tiles with specks	Deck B- Throughout area forward of Cargo Loading Passage	Fair		x
NSS-B Deck-Mastic-13A, -13B, -13C	Mastic associated with gray 9" x9" floor tile with specks	Deck B- Throughout area forward of Cargo Loading Passage	Fair		x
NSS-B Deck-Subfloor-14A, -14B, -14C	Gray sub-floor (baseboard)	Deck B- Forward of Cargo Loading Passage	Fair		x

**Asbestos Survey Field Data Sheet-Deck B**  
**NS-Savannah**  
**Fort Eustis, VA**

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSS-B Deck-MM-15A, -15B, -15C	White drywall (1/2" thickness) associated with ceiling	Deck B-Throughout staterooms and hallways	Fair	x	
NSS-B Deck-FT-16A, -16B, -16C	Tan, 9" x9" floor tile with brown lines and associated mastic	Deck B- Starboard side stateroom forward of the Cargo Loading Passage	Fair		x
NSS-B Deck-MM-17A, -17B, -17C	White, 18"x18" ceiling panels with pinholes	Deck B- Dining room and office rear of Cargo Loading Passage	Good		x
NSS-B Deck-TSI-18A, -18B, -18C	Straight run pipe insulation	Deck B- Piping that is located above ceiling	Good	x	
NSS-B Deck-TSI-19A, -19B, -19C	Elbow pipe insulation	Deck B- Piping that Is located above ceiling	Good	x	
NSS-B Deck-MM-20A, -20B, -20C	White drywall (1" thickness) associated with walls	Deck B - Throughout staterooms and hallways	Good	x	

Note: All pipes are recorded as total diameter of the pipe and the associated insulation.

*Asbestos Survey Field Data Sheet-Deck C*  
*NS-Savannah*  
*Fort Eustis, VA*

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSSDeckC-FT-1A, -1B, -1C	Tan, 9"x9" floor tiles with white lines and associated mastics	Deck C-Staterooms	Good		x
NSSDeckC-MM-2A, -2B, -2C	White drywall (1/2" thickness) associated with state room ceiling	Deck C-Staterooms	Good	x	
NSSDeckC-MM-3A, -3B, -3C	White drywall (1" thickness) associated with state room walls	Deck C-Staterooms and Hallways	Good	x	
NSSDeckC-TSI-4A, -4B, -4C	Straight run pipe insulation associated with pipes above ceiling	Deck C	Good	x	
NSSDeckC-TSI-5A, -5B, -5C	Elbow pipe insulation associated with pipes above ceiling	Deck C	Good	x	
NSSDeckC-FT-6A, -6B, -6C	Brown, 9" x9" floor tile with black specks and associated mastic	Deck C- Hallways	Good		x
NSSDeckC-FT-7A, -7B, -7C	Tan, 9" x9" floor tile with black and white specks and associated mastic	Deck C- Hallways	Good		x

*Asbestos Survey Field Data Sheet-Deck C*  
*NSS-Savannah*  
*Fort Eustis, VA*

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSSDeckC-TSI-8A, -8B, -8C	Straight run pipe insulation associated with piping	Deck C - Carpenters workshop	Good	x	
NSSDeckC-TSI-9A, -9B, -9C	Elbow pipe insulation associated with piping	Deck C- Carpenters workshop	Good	x	

Note: All pipes are recorded as total diameter of the pipe and the associated insulation.

**Asbestos Survey Field Data Sheet-14 Flat and Deck D**  
**NS-Savannah**  
**Fort Eustis, VA**

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSS14Flat-TSI-1A, -1B, -1C	Straight run pipe insulation associated with heating system	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-2A, -2B, -2C	Elbow pipe insulation associated with heating system drain	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-3A, -3B, -3C	Straight run pipe insulation associated with heating system drain	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-4A, -4B, -4C	Elbow pipe insulation associated with heating system drain	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-5A, -5B, -5C	Straight run pipe insulation associated with auxiliary exhaust	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-6A, -6B, -6C	Elbow pipe insulation associated with auxiliary exhaust	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-7A, -7B, -7C	Straight run pipe insulation associated with fire station 37 (4" diameter)	Deck 14 Flat-Engine Room	Good	x	



**Asbestos Survey Field Data Sheet-14 Flat and Deck D**  
**NS-Savannah**  
**Fort Eustis, VA**

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSS14Flat-TSI-8A, -8B, -8C	Elbow pipe insulation associated with fire station 37 (4" diameter)	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-9A, -9B, -9C	Insulation (body) associated with HP/LP crossover system (60" diameter)	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-10A, -10B, -10C	Insulation (body) associated with HP/LP crossover system (36" diameter)	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-11A, -11B, -11C	Elbow pipe insulation associated with HP/LP crossover system (36" diameter)	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-12A, -12B, -12C	Elbow pipe insulation associated with steam dump pipe (24" diameter)	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-13A, -13B, -13C	Straight run pipe insulation associated with steam dump pipe (24" diameter)	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-14A, -14B, -14C	Straight run pipe insulation (4" diameter)	Deck 14 Flat-Shaft Alley	Good	x	

**Asbestos Survey Field Data Sheet-14 Flat and Deck D**  
**NS-Savannah**  
**Fort Eustis, VA**

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSS14Flat-TSI-15A, -15B, -15C	Elbow pipe insulation (4" diameter)	Deck 14 Flat-Shaft Alley	Good	x	
NSS14Flat-TSI-16A, -16B, -16C	Straight run pipe insulation associated with main feed pump	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-17A, -17B, -17C	Elbow pipe insulation associated with main feed pump	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-18A, -18B, -18C	Insulation associated with first stage water heater (body)	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-19A, -19B, -19C	Straight run pipe insulation associated with solenoid valve	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-20A, -20B, -20C	Elbow pipe insulation associated with solenoid valve	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-21A, -21B, -21C	Straight run pipe insulation associated with shell coil system	Deck 14 Flat-Engine Room	Good	x	

**Asbestos Survey Field Data Sheet-14 Flat and Deck D**  
**NS-Savannah**  
**Fort Eustis, VA**

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSS14Flat-TSI-22A, -22B, -22C	Elbow pipe insulation associated with shell coil system	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-23A, -23B, -23C	Straight run pipe insulation associated with crossover drain	Deck 14 Flat-Engine Room	Good	x	
NSS14Flat-TSI-24A, -24B, -24C	Elbow pipe insulation associated with crossover drain	Deck 14 Flat-Engine Room	Fair	x	
NSSDeckD-FT-25A, -25B, -25C	White, 9"x9" floor tile and associated mastics	Deck D-Control Room	Good		x
NSSDeckD-FT-26A, -26B, -26C	Green, 9"x9" floor tile and associated mastics	Deck D-Control Room	Good		x
NSSDeckD-TSI-27A, -27B, -27C	Straight run pipe insulation associated with cooling system (green)	Deck D-Engine Room	Good	x	
NSSDeckD-TSI-28A, -28B, -28C	Elbow pipe insulation associated with cooling system (green)	Deck D-Engine Room	Good	x	

**Asbestos Survey Field Data Sheet-14 Flat and Deck D  
 NS-Savannah  
 Fort Eustis, VA**

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSSDeckD-TSI-29A, -29B, -29C	Insulation associated with cooling system tank (green)	Deck D-Engine Room	Poor	x	
NSSDeckD-TSI-30A, -30B, -30C	Straight run pipe insulation associated with diesel engine exhaust	Deck D-Engine Room	Good	x	
NSSDeckD-TSI-31A, -31B, -31C	Elbow pipe insulation associated with diesel engine exhaust	Deck D-Engine Room	Good	x	
NSSDeckD-MM-32A, -32B, -32C	Gaskets associated with boiler	Deck D-Engine Room	Good	x	
NSSDeckD-TSI-33A, -33B, -33C	Insulation associated with steam generator (pink)	Deck D-Engine Room	Good	x	
NSSDeckD-TSI-34A, -34B, -34C	Straight run pipe insulation associated with steam generator	Deck D-Engine Room	Good	x	
NSSDeckD-TSI-35A, -35B, -35C	Elbow pipe insulation associated with steam generator	Deck D-Engine Room	Good	x	

**Asbestos Survey Field Data Sheet-14 Flat and Deck D**  
**NS-Savannah**  
**Fort Eustis, VA**

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSSDeckD-TSI-36A, -36B, -36C	Straight run pipe insulation associated with compressors	Deck D-Engine Room	Good	x	
NSSDeckD-TSI-37A, -37, -37C	Elbow pipe insulation associated with compressors	Deck D-Engine Room	Good	x	
NSSDeckD-TSI-38A, -38B, -38C	Pipe insulation associated with boiler duct	Deck D-Engine Room	Good	x	
NSSDeckD-TSI-39A, -39B, -39C	Elbow pipe insulation associated with ADT pipe system (green)	Deck D-Engine Room	Good	x	
NSSDeckD-TSI-40A, -40B, -40C	Straight run pipe insulation associated with ADT pipe system (green)	Deck D-Engine Room	Poor	x	
NSSDeckD-TSI-41A, -41B, -41C	Straight run pipe insulation associated with steam valve system	Deck D-Engine Room	Fair	x	
NSSDeckD-TSI-42A, -42B, -42C	Straight run pipe insulation associated with engine (red)	Deck D-Engine Room	Good	x	

**Asbestos Survey Field Data Sheet-14 Flat and Deck D  
 NS-Savannah  
 Fort Eustis, VA**

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSSDeckD-TSI-43A, -43B, -43C	Elbow pipe insulation associated with engine (red)	Deck D-Engine Room	Good	x	
NSSDeckD-TSI-44A, -44B, -44C	Straight run pipe insulation associated with evaporators	Deck D-Engine Room	Good	x	
NSSDeckD-TSI-45A, -45B, -45C	Elbow pipe insulation associated with evaporators	Deck D-Engine Room	Good	x	
NSSDeckD-TSI-46A, -46B, -46C	Straight run pipe insulation associated with generators	Deck D-Engine Room	Fair	x	
NSSDeckD-TSI-47A, -47B, -47C	Elbow pipe insulation associated with generators	Deck D-Engine Room	Poor	x	
NSSDeckD-TSI-48A, -48B, -48C	Straight run pipe insulation associated with steam valves	Deck D-Engine Room	Good	x	
NSSDeckD-TSI-49A, -49B, -49C	Elbow pipe insulation associated with steam valves	Deck D-Engine Room	Fair	x	

**Asbestos Survey Field Data Sheet-14 Flat and Deck D  
 NS-Savannah  
 Fort Eustis, VA**

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSSDeckD-TSI-50A, -50B, -50C	Straight run pipe insulation associated with boiler water treatment system	Deck D-Engine Room	Fair	x	
NSSDeckD-TSI-51A, -51B, -51C	Insulation associated with vent to first stage heater (body)	Deck D-Engine Room	Good	x	
NSSDeckD-TSI-52A, -52B, -52C	Straight run pipe insulation associated with condensate line	Deck D-Engine Room	Good	x	
NSSDeckD-TSI-53A, -53B, -53C	Straight run pipe insulation associated with diesel engine exhaust (upper section)	Deck D-Engine Room	Good	x	
NSSDeckD-FT-54A, -54B, -54C	Tan, 9"x9" floor tile with black specks and associated mastic	Deck D- Food Storage Area	Poor		x
NSSDeckD-FT-55A, -55B, -55C	Brown 9" x9" floor tile with black and white specks and associated mastic	Deck D- Food Storage Area	Poor		x
NSSDeckD-TSI-56A, -56B, -56C	Straight run pipe insulation	Deck D-Food Storage Area	Good	x	
NSSDeckD-TSI-57A, -57B, -57C	Elbow pipe insulation	Deck D- Food Storage Area	Good	x	

Note: All pipes are recorded as total diameter of the pipe and the associated insulation.

***Asbestos Survey Field Data Sheet-Reactor Containment  
 NS-Savannah  
 Fort Eustis, VA***

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSS-RC-TSI-1A, -1B, -1C	Straight run pipe insulation associated with electrical cord	Secondary Containment- Deck A Level	Good	x	
NSS-RC-TSI-2A, -2B, -2C	Straight run pipe insulation associated with UV tanks (12" diameter)	Secondary Containment	Good	x	
NSS-RC-TSI-3A, -3B, -3C	Elbow pipe insulation associated with UV tanks (12" diameter)	Secondary Containment	Good	x	
NSS-RC-TSI-4A, -4B, -4C	Straight run pipe insulation associated with 4" diameter pipes	Primary and Secondary Containment	Good	x	
NSS-RC-TSI-5A, -5B, -5C	Elbow pipe insulation associated with 4" diameter pipes	Primary and Secondary Containment	Good	x	
NSS-RC-TSI-6A, -6B, -6C	Straight run pipe insulation associated with 2" diameter pipes	Primary and Secondary Containment	Good	x	
NSS-RC-TSI-7A, -7B, -7C	Elbow pipe insulation associated with 2" diameter pipes	Primary and Secondary Containment	Good	x	



*Asbestos Survey Field Data Sheet-Reactor Containment  
 NS-Savannah  
 Fort Eustis, VA*

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NSS-RC-TSI-8A, -8B, -8C	Straight run pipe insulation associated with 10" diameter pipes	Primary and Secondary Containment	Good	x	
NSS-RC-TSI-9A, -9B, -9C	Elbow pipe insulation associated with 10" diameter pipes	Primary and Secondary Containment	Good	x	
NSS-RC-TSI-10A, -10B, -10C	Straight run pipe insulation associated with waste tanks	Lower Secondary Containment	Good	x	
NSS-RC-TSI-11A, -11B, -11C	Elbow pipe insulation associated with waste tanks	Lower Secondary Containment	Good	x	
NSS-RC-TSI-12A, -12B, -12C	Insulation associated with the secondary heat exchanger (purple in color)	Primary Containment	Good	x	
NSS-RC-TSI-13A, -13B, -13C	Straight run pipe insulation associated with pressurizer system (red in color)	Primary Containment	Good	x	
NSS-RC-TSI-14A, -14B, -14C	Elbows insulation associated with pressurizer system (red in color)	Primary Containment	Good	x	

**Asbestos Survey Field Data Sheet-Reactor Containment  
 NS-Savannah  
 Fort Eustis, VA**

Sample ID	Material Description	Location	Condition	Friable?	
				Yes	No
NS-RC-TSI-15A, -15B, -15C	Insulation associated with pressurizer system tank (red in color)	Primary Containment	Good	x	
NSS-RC-TSI-16A, -16B, -16C	Straight run pipe insulation associated with secondary heat exchanger (purple in color)	Primary Containment	Good	x	
NSS-RC-TSI-17A, -17B, -17C	Elbow insulation associated with secondary heat exchanger (purple in color)	Primary Containment	Good	x	
NSS-RC-TSI-18A, -18B, -18C	Straight run pipe insulation associated with primary heat exchanger system ( 24" in diameter and red in color)	Primary Containment	Good	x	
NSS-RC-TSI-19A, -19B, -19C	Elbow pipe insulation associated with primary heat exchanger system ( 24" in diameter and red in color)	Primary Containment	Good	x	
NSS-RC-TSI-20A, -20B, -20C	Canvas wrap associated with fiberglass insulation	Primary and Secondary Containment	Good	x	

Note: All pipes are recorded as total diameter of the pipe and the associated insulation.