

# Petro Processors of Louisiana Brooklawn Site Evolution



1979




1993



1997

## Brooklawn Site - 1979



This is the Brooklawn Site before any remediation was implemented. It was described to consist of "four generally identifiable areas of waste disposal and contamination". These included lagoons, contaminated sediments and soils.

## Brooklawn Site - 1993





By 1993, over 60 recovery wells and 98 French drain sumps were in place. Recovered water from these wells was piped to a carbon treatment facility. These remedial actions were implemented in response to a "Supplemental Remedial Action Plan" approved by the Court in 1989. Only two open lagoons remained at this point.

### **Brooklawn Site - 1997**



By 1997, over 160 recovery wells were in operation at the site. The carbon adsorption system has been enhanced with an air stripping and incineration system. Remediation is in full swing. Today, July 1998, over 170 recovery wells are in service.