




Structurally Deficient Bridges on the National Highway System Michigan - Congressional District 15



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 251 structurally deficient NHS bridges in Michigan, 15 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	814021200016S01	STADIUM BOULEVARD	0.5 MI E OF MAIN ST
2	81181103000S091	23 BR N TO US-23 N	@ W JCT US-23 (TOP LEVL)
3	81181076000S060	US-12	@ US-12
4	58158034000R012	US-23 SB	3.0 MI S OF DUNDEE
5	58158091000R010	I-75 CONN	3.0 MI N OF OHIO ST LINE
6	82182292000S010	HANNAN RD.	IN ROMULUS
7	82182291000S148	I-94 WB COLLECTOR	IN ROMULUS
8	82182291000S144	I-94 WB	IN ROMULUS
9	82182291000S110	I-94 EB	IN ROMULUS
10	58158151000R020	I-75	IN MONROE
11	58158151000R040	I-75	IN MONROE
12	58158152000R010	I-75	0.7 MI N OF M-50
13	58158171000S110	I-275 NB	5 MI SW OF FLATROCK
14	58158171000S010	I-275 SB	5 MI N OF MONROE
15	82182191000S010	I-75	IN ROCKWOOD
16	82182191000S100	I-75 CONN SB	@US-25 N OF WOODHAVEN
17	82182191000S090	I-75 CONN NB	N OF WOODHAVEN
18	82182191000S142	I-75 SB	IN TAYLOR OVER EUREKA RD
19	82182062000B020	US-12EB	IN DEARBORN