

Express Shuttle II

Coast Guard PSIX File

Seventeen (17) pages total including this cover

Vessel Information

Vessel Name: EXPRESS SHUTTLE II
 VIN: 1053146
 Hull Number: AYH6511DF797
 Flag: USA
 Call-Sign: WCX 6094
 Year Built: 1997

Vessel Particulars

Service: Passenger (More Than 6)
 Length: 65.0 ft
 Breadth: 22.0 ft
 Depth: 4.5 ft
 Alternate VINs: CG455982
 IMO Number

Service Information

Service Status: In Service
 Out of Service Date:
 Last removed from service by: COMMANDANT (G-MOA)

Tonnage Information

Deadweight: 43
 Gross Tonnage (GRT): 43
 Net Tonnage (NRT): 34
 Gross Tonnage (GT ITC)

Cargo Authority:

Vessel Documents and Certifications

Document	Agency	Date Issued	Expiration Date
CERTIFICATE OF DOCUMENTATION	USCG	June 21, 2004	July 31, 2005
Certificate of Inspection - Amended	USCG	July 17, 2000	July 17, 2005
Stability Letter	USCG	July 16, 1997	

Summary of Coast Guard Contacts

Activity Number	USCG Zone/Port	Date	Activity Type	Enforcement Description	Incident Description
1996809	TAMPA, FL	October 5, 2004	Vessel Inspection/PSC		

Deficiency Information

System
Lifesaving

SubSystem
Lifefloat

Cause
Improper/Lack of Maintenance

Description of Deficiency

Replace tag lines on all L/F's as needed.

Due Date
11/5/2004

Resolved
Yes

Resolved Date
10/17/2004

Resolution Description

CLEARED DUE TO TOTAL LOSS OF VSL

Deficiency Information

System
Navigation

SubSystem
Collision/Grounding Avoidance

Cause
Improper/Lack of Maintenance

Description of Deficiency

Prior to night time operation. repair stern light.

Due Date
10/5/2004

Resolved
Yes

Resolved Date
10/5/2004

Resolution Description

Deficiency Information

System
Engineering

SubSystem
Diesel Engine (propulsion-reduction gear)

Cause
Improper/Lack of Maintenance

Description of Deficiency

Prior to the carriage of passengers, repair water leak from STBD engine, outboard, and PORT engine inboard water cooled

exhaust pipe.

Due Date
10/5/2004

Resolved
Yes

Resolved Date
10/5/2004

Resolution Description

Deficiency Information

System
Electrical

SubSystem
Lighting (service)

Cause

Improper/Lack of Maintenance

Description of Deficiency

Provide a light cover for light in E/R.

Due Date
10/12/2004

Resolved
Yes

Resolved Date
10/17/2004

Resolution Description

CLEARED DUE TO TOTAL LOSS OF VSL

Deficiency Information

System
Accommodation/Occupational Safety

SubSystem
Other Accommodation Spaces

Cause

Improper/Lack of Maintenance

Description of Deficiency

Provide a placard with the max passenger amount for second deck IWO aft ladder.

Due Date
10/12/2004

Resolved
Yes

Resolved Date
10/17/2004

Resolution Description

CLEARED DUE TO TOTAL LOSS OF VSL

Deficiency Information

System

Lifesaving

SubSystem

Lifejacket/PFD (General)

Cause

Improper/Lack of Maintenance

Description of Deficiency

Label life preserver location with the size and amount.

Due Date

10/12/2004

Resolved

Yes

Resolved Date

10/17/2004

Resolution Description

CLEARED DUE TO TOTAL LOSS OF VSL

Deficiency Information

System

Accommodation/Occupational Safety

SubSystem

Other Accommodation Spaces

Cause

Improper/Lack of Maintenance

Description of Deficiency

Provide a support beam or repair 2nd deck overhead.

Due Date

10/12/2004

Resolved

Yes

Resolved Date

10/17/2004

Resolution Description

CLEARED DUE TO TOTAL LOST OF VSL.

Deficiency Information

System

SubSystem

Cause

Accommodation/Occupational Safety Occupational Safety

Improper/Lack of Maintenance

Description of Deficiency

Provide safety shields for both PORT and STBD PTO's.

Due Date
10/12/2004

Resolved
Yes

Resolved Date
10/17/2004

Resolution Description

CLEARED DUE TO TOTAL LOSS OF VSL

Deficiency Information

System
Engineering

SubSystem
Bilge Water Management System

Cause
Improper/Lack of Maintenance

Description of Deficiency

Provide strainers for bilge pick-up lines as per 46CFR182.25.5(b).

Due Date
11/5/2004

Resolved
Yes

Resolved Date
10/17/2004

Resolution Description

CLEARED DUE TO TOTAL LOSS OF VSL

Deficiency Information

System
Lifesaving

SubSystem
Lifejacket/PFD (General)

Cause
Improper/Lack of Maintenance

Description of Deficiency

Remove all child (16total) life preservers, w/labels from vessel. Vsl COI states no children allowed. Vsl rep will remove.

Due Date
10/12/2004

Resolved
Yes

Resolved Date
10/17/2004

Resolution Description
CLEARED DUE TO TOTAL LOSS OF VSL

Deficiency Information
System
Electrical

SubSystem
Electric Supply System (service)

Cause
Placed in Improper Service

Description of Deficiency
Repair and properly mount engine battery switches.

Resolved
Yes

Due Date
10/12/2004

Resolved Date
10/17/2004

Resolution Description
CLEARED DUE TO TOTAL LOSS OF VSL

Deficiency Information
System
Lifesaving

SubSystem
Lifefloat

Cause
Improper/Lack of Maintenance

Description of Deficiency
Replace or repair 03 L/F's as discussed.

Resolved
Yes

Due Date
11/5/2004

Resolved Date
10/17/2004

Resolution Description
 CLEARED DUE TO TOTAL LOSS OF VESSEL

Deficiency Information
System Construction/Loadline
SubSystem Penetrations

Description of Deficiency
 Reseal cleat backing plates in store room and fuel oil room.

Due Date 10/12/2004
Resolved Yes

Resolved Date
 10/17/2004

Cause
 Improper Installation

Resolution Description
 CLEARED DUE TO TOTAL LOSS OF VSL

Deficiency Information
System Electrical
SubSystem Electric Supply System (service)

Description of Deficiency
 Secure wires and remove dead-ended wires as needed throughout vessel.

Due Date 11/5/2004
Resolved Yes

Resolved Date
 10/17/2004

Cause
 Improper/Lack of Maintenance

Activity Number **USCG Zone/Port** **Date** **Activity Type**

Enforcement Description **Incident Description**

2042643 TAMPA, FL April 12, 2004 Vessel Inspection/PSC
 2021948 TAMPA, FL March 9, 2004 Vessel Inspection/PSC
 1866300 TAMPA, FL August 11, 2003 Vessel Inspection/PSC

Deficiency Information

System Fire Fighting
SubSystem Fixed CO2 Fire Extinguishing System

Cause

Description of Deficiency

PROVIDE 3RD PARTY CO2 INSPECTION REPORT. LEGACY COMPONENT DESC: Inspection

Due Date 8/18/2003
Resolved Yes

Resolved Date
 8/21/2003

Resolution Description
 REPORT PROVIDED.

Deficiency Information

System Lifesaving
SubSystem Lifejacket/PFD (Type I)

Cause

Improper Installation

Description of Deficiency

PROPERLY LABEL LIFEJACKET STOWAGE AREA. LEGACY COMPONENT DESC: Storage

Due Date 8/18/2003
Resolved Yes

Resolved Date
 8/21/2003

Resolution Description

SAT

Deficiency Information

System Lifesaving
SubSystem Buoyant Apparatus

Cause Improper/Lack of Maintenance

Description of Deficiency

PROPERLY STENCIL VESSEL NAME AND PASSENGER CAPACITY ON LIFEFLOATS. LEGACY COMPONENT
 DESC: Marking

Due Date 8/18/2003
Resolved Yes

Resolved Date 8/21/2003

Resolution Description

SAT

Deficiency Information

System Fire Fighting
SubSystem Fixed Fire Detection System

Cause

Description of Deficiency

PROVIDE 3RD PARTY INSPECTION REPORT ATTESTING TO THE PROPER OPERATION OF HEAT DETECTOR
 IN ENGINE ROOM. LEGACY COMPONENT DESC: Heat Detectors

Due Date 8/18/2003
Resolved Yes

Resolved Date 8/21/2003

Resolution Description

PHONCON W/MIKE FROM SUNCOAST FIRE.

Deficiency Information

System SubSystem

Cause

Electrical Electrical Distribution System (service)

Description of Deficiency

REMOVE ALL DEAD END WIRING THROUGHOUT ENGINE ROOM. LEGACY COMPONENT DESC: Wiring

Due Date 9/11/2003 **Resolved** Yes

Resolved Date
8/21/2003

Resolution Description
SAT

Deficiency Information

System Engineering **SubSystem** Fuel Oil Storage/Transfer System

Cause
Improper Installation

Description of Deficiency

REPLACE LIQUID LEVEL INDICATING GAUGES WITH HEAT RESISTANT MATERIAL AND INSTALL IAW 46 CFR 182.20-25 9 (a)(5). LEGACY COMPONENT DESC: Gauge

Due Date 9/11/2003 **Resolved** Yes

Resolved Date
3/9/2004

Resolution Description

WITNESSED INSTALLATION.

Activity Number	USCG Zone/Port	Date	Activity Type	Enforcement Description	Incident Description
1833075	TAMPA, FL	July 8, 2003	Vessel Inspection/PSC		
1739402	TAMPA, FL	February 6, 2003	Vessel Inspection/PSC		
1721694	TAMPA, FL	December 23, 2002	Vessel Inspection/PSC		

Deficiency Information System
Documentation

SubSystem
Certificates/Documents

Cause

Description of Deficiency

Provide an FCC Safety Certificate. LEGACY COMPONENT DESC: FCC SSL

Due Date
9/27/2002

Resolved
Yes

Resolved Date
2/6/2003

Resolution Description
SAT

Deficiency Information System
Engineering

SubSystem

Cause

Description of Deficiency

Demonstrate the proper operation of the installed bilge suction system. LEGACY COMPONENT DESC: Bilge system

Due Date
9/4/2002

Resolved
Yes

Resolved Date
2/6/2003

Resolution Description
SAT

Deficiency Information System
Accommodation/Occupational Safety

SubSystem
Medical/First Aid

Cause

Description of Deficiency

Replace first-aid kit.

Due Date

9/4/2002

Resolved

Yes

Resolved Date

2/6/2003

Resolution Description

SAT

Deficiency Information**System**

Lifesaving

SubSystem

Lifejacket/PFD (General)

Cause**Description of Deficiency**

Rename all life preservers to match vessel name.

Due Date

9/27/2002

Resolved

Yes

Resolved Date

2/6/2003

Resolution Description

SAT

Deficiency Information**System**

Engineering

SubSystem

Diesel Engine (propulsion-electric)

Cause**Description of Deficiency**

Repair exhaust and oil leak on PORT GENSET.

Due Date**Resolved****Resolved Date**

9/27/2002

Yes

2/6/2003

Resolution Description

SAT

Deficiency Information System

Pollution Prevention/Response

SubSystem

Cause

Description of Deficiency

Clean oil from bilge water. LEGACY COMPONENT DESC: Oil in bilge

Due Date

8/28/2002

Resolved

Yes

Resolved Date

2/6/2003

Resolution Description

SAT

Deficiency Information System

Fire Fighting

SubSystem

Fixed Fire Detection System

Cause

Description of Deficiency

Demonstrate the proper operation of the fire and smoke protection system.

Due Date

9/4/2002

Resolved

Yes

Resolved Date

2/13/2003

Resolution Description

3RD PARTY REPORT.

Activity Number
1492267

USCG Zone/Port
TAMPA, FL

Date
May 8, 2002

Activity Type
Vessel Inspection/PSC

Enforcement Description

Incident Description

Activity Number
1477046

USCG Zone/Port
TAMPA, FL

Date
December 18, 2001

Activity Type
Vessel Inspection/PSC

Enforcement Description

Incident Description

Deficiency Information
System
Fire Fighting

SubSystem

Cause
Unknown

Resolved
Yes

Resolved Date
12/18/2001

Cause
Unknown

Description of Deficiency
PROVIDE BRACKET FOR STOWAGE OF FIRE HOSE.

Resolution Description
MOUNTED.

Deficiency Information
System
Lifesaving

SubSystem

Resolved
Yes

Resolved Date
12/18/2001

Description of Deficiency
CHECK ALL LIFEFLOATS FOR ROTTED LINES AND REPLACE AS NEEDED.

Resolution Description

Deficiency Information
System
Lifesaving

SubSystem

Resolved
Yes

Resolved Date
12/18/2001

Due Date
9/28/2001

Due Date
9/28/2001

Resolution Description

Resolved
Yes

Resolved Date
12/18/2001

Due Date
9/28/2001

Due Date
9/28/2001

Resolution Description

Resolved
Yes

Resolved Date
12/18/2001

REPAIR SATISFACTORY.

Deficiency Information System
Construction/Loadline

SubSystem

Cause
Unknown

Description of Deficiency
INSTALL METALLIC THRU-HULL FITTING ON ALL OVERBOARD PIPING.

Due Date
9/28/2001

Resolved
Yes

Resolved Date
12/18/2001

Resolution Description
RE-EVALUATED CURRENT FITTINGS AS EXISTING AND SATISFACTORY.

Deficiency Information System
Lifesaving

SubSystem

Cause
Unknown

Description of Deficiency
REPLACE RETROFLECTIVE MATERIAL ON LIFEFLOAT BOTTOMS.

Due Date
9/28/2001

Resolved
Yes

Resolved Date
12/18/2001

Resolution Description

Deficiency Information System
Lifesaving

SubSystem

Cause
Unknown

Description of Deficiency
INSTALL PUBLIC ADDRESS SYSTEM.

Due Date
9/28/2001

Resolved
Yes

Resolved Date
12/18/2001

Resolution Description
INSTALLED AND TESTED.

Deficiency Information
System
Engineering

SubSystem

Cause
Unknown

Description of Deficiency
PROPERLY STENCIL FUEL SHUT OFFS.

Due Date
9/28/2001

Resolved
Yes

Resolved Date
12/18/2001

Resolution Description
STENCILED.