

USCG Vessel Critical Profile

Six (6) pages total including this cover

Vessel Critical Profile

Name/ EXPRESS SHUTTLE II Primary VIN/ 1053146 Call/ WCX 6094 Flag/ US

Alt VIN's	Type
1053146	Official Number (U.S.)
CG455982	Coast Guard Number
AYH6511DF797	Hull Number

---Involved Parties---

Role	Name	Party Id
Flag State	UNITED STATES	833031
Managing Owner	PARADISE OF PORT RICHEY INC	694139
Owner	PARADISE OF PORT RICHEY INC	694139
Operator	PARADISE OF PORT RICHEY INC	694139
Operator	PORT RICHEY CASINO, INC.	958093
Managing Owner (Trustee)	PARADISE OF PORT RICHEY INC	694139

---Vessel Specifics---

Service/ Passenger (More Than 6)	Gross Tons(GT ITC)/	Hailing Port/ PORT RICHEY FL,
Propulsion/ Diesel Reduction	Gross Tons(GRT)/ 43	Date Keel Laid/
Route/ LC: Lakes, Bays, and Sounds plus Limited Coastwise	Deadweight Ton/	Date Delivered/ 18Jul1997
Ahead HorsePower/ 1600	Length/ 65 (ITC)/	Hull Material/ FRP (Fiberglass)
Astern HorsePower/	Super Structure Color/	Hull Color/
Class/ Passenger Ship	Type/ Water Taxi	SubType/ General (More Than 6)

---VDS Documents---

Document	Activity #	Agency	Port	Issued	Expires	Status
CERTIFICATE OF DOCUMENTATION		USCG	RE2VD	21Jun2004	31Jul2005	VALID

---Certificate/Document Status---

Document	Activity #	Agency	Port	Issued	Expires	Status
SAFETY RADIO TELEPHONE		FCC	NONCG	04Sep2002	04Sep2007	VALID
Certificate of Inspection - Amended	2042643	USCG	MSO TAMPA	17Jul2000	17Jul2005	Issued/Effective
Stability Letter		USCG	PORMS	16Jul1997		VALID

Role Type/ Transiting Vicinity of Primary Subject Activity Type/ Incident Investigation
 Status/ Open - Submitted for Review Date Status Last Changed/ 09Sep2002
 Notes (Truncated)/

---All Closed Activities (W/in 18 months)---

Total Closed Activities/ 5

1. Activity #/ 2042643 Orig Port/ MSO Tampa Owner Port/ MSO Tampa Start Dt/ 12Apr2004
 Role Type/ Subject to Marine Inspection Activity Type/ Vessel Inspection/PSC
 Activity Subtypes/ ADMIN
 Status/ Closed - Approved Inspection Date Status Last Changed/ 23Apr2004
 Notes (Truncated)/ EXPRESS SHUTTLE II - OPERATOR CHANGE Changed operator name and address on COI as per fax dated 12APR04, from the company executive secretary, a Beth Henson. //s//CWO3 R. Lawrence, MSO Tampa
2. Activity #/ 2021948 Orig Port/ MSO Tampa Owner Port/ MSO Tampa Start Dt/ 09Mar2004
 Role Type/ Subject to Marine Inspection Activity Type/ Vessel Inspection/PSC
 Activity Subtypes/ DEFICIENCY CK
 Status/ Closed - Approved Inspection Date Status Last Changed/ 21Apr2004
 Notes (Truncated)/ VISITED VESSEL PIER SIDE IN PRESENCE OF OWNER REP TO CONDUCT DEFICIENCY CHECK. CLEARED 01 OF 01 DEFICIENCIES FROM ACTIVITY 1866300 FOR INSTALLATION OF HEAT RESISTANT LIQUID LEVEL SIGHT GAUGES. NO DEFICIENCIES REMAIN OUTSTANDING. INSPECTION COMPLETE. //s// B. K. SHINE, CWO, MARINE INSPECTOR
3. Activity #/ 1866300 Orig Port/ MSO Tampa Owner Port/ MSO Tampa Start Dt/ 11Aug2003
 Role Type/ Subject to Marine Inspection Activity Type/ Vessel Inspection/PSC
 Activity Subtypes/ AIN
 Status/ Closed - Approved Inspection Date Status Last Changed/ 23Apr2004
 Notes (Truncated)/ T- BOAT ANNUAL INSPECTION. 06 CG-835's ISSUED. 00 CG-835's OUTSTANDING FROM ACTIVITY NUMBER 050 CG-835's CLEARED FROM THIS ACTIVITY NUMBER 01 CG-835'S REMAIN OUTSTANDING. Vsl type: () Dinner Cruise () Dive Boat () Parasail Boat (X) Excursion Boat () Charter () Fish Boat () Aux. Sail, night sail (Y/N) () Other = () Hull: () STL (X) FRP
4. Activity #/ 1833075 Orig Port/ MSO Tampa Owner Port/ MSO Tampa Start Dt/ 08Jul2003
 Role Type/ Subject to Marine Inspection Activity Type/ Vessel Inspection/PSC
 Activity Subtypes/ HULL EXAM
 Status/ Closed - Approved Inspection Date Status Last Changed/ 18Jul2003
 Notes (Truncated)/ T- BOAT HULL INSPECTION. ISSUED 07 WORKLIST ITEMS. 00 CG-835'S OUTSTANDING FROM CASE. 07 CG-835'S WORKLIST ITEMS CLEARED FROM THIS CASE. 00 WORKLIST ITEMS REMAIN OUTSTANDING. Vsl type: () Dinner Cruise () Dive Boat () Parasail Boat () Excursion Boat () Charter () Fish Boat () Aux. Sail, night sail (Y/N) (X) Other = (CASINO TAXI) Hull: () STL
5. Activity #/ 1664844 Orig Port/ MSO Tampa Owner Port/ MSO Tampa Start Dt/ 27Aug2002
 Role Type/ Subject to Marine Inspection Activity Type/ Vessel Inspection/PSC
 Activity Subtypes/ AIN
 Status/ Closed - Approved Inspection Date Status Last Changed/ 08Aug2003
 Notes (Truncated)/ EXPRESS SHUTTLE II RE-INSPECTION 08 CG-835's ISSUED. 00 CG-835's OUTSTANDING FROM ACTIVITY NUMBER. 00 CG-835's CLEARED FROM ACTIVITY NUMBER. 08 CG-835'S REMAIN OUTSTANDING. Vsl type: () Dinner Cruise () Dive Boat () Parasail Boat () Excursion Boat () Charter () Fish Boat () Aux. Sail, night sail (Y/N) Other = (Casino water taxi) Hull: () STL (X) FRP

---Hazardous Cargo Authority---

Vessel is NOT Authorized to carry Hazardous Cargo

---Special Notes---

1. Activity #/ 1407007 Last Revised/ 31Aug2004 Unit/ MSO Tampa
Description/ CONDUCTED COMPANY DAPI AUDIT. CONSORTIUM = COLUMBIA LABORATORIES.
2. Activity #/ 1407007 Last Revised/ 04Sep2001 Unit/ MSO Tampa
Description/ PASSENGER COUNT LEFT AT VESSEL OFFICE AT HOMEPORT PIER.
3. Activity #/ Last Revised/ 22Oct1997 Unit/ MSO Tampa
Description/ SIMPLIFIED STABILITY TEST CONDUCTED FOR PARTIALLY PROTECTED WATERS ON 14JUL97 FOR 150 PASS, 154 TOTAL PERS. 64 PASS MAX ON UPPER DECK.

---Outstanding Deficiencies---

1. Activity #/ 1996809 Issue Date/ 05Oct2004 Issue Port/ MSO Tampa
Resolution/ Due/ 10/12/2004
System/ Accommodation/Occupational Safety Subsystem/
Condition/ Missing
Deficiency Cause/ Improper/Lack of Maintenance
Deficiency Description/ Provide a placard with the max passenger amount for second deck IWO aft ladder.
2. Activity #/ 1996809 Issue Date/ 05Oct2004 Issue Port/ MSO Tampa
Resolution/ Due/ 11/05/2004
System/ Lifesaving Subsystem/
Condition/ Wasted
Deficiency Cause/ Improper/Lack of Maintenance
Deficiency Description/ Replace or repair 03 L/F's as discussed.
3. Activity #/ 1996809 Issue Date/ 05Oct2004 Issue Port/ MSO Tampa
Resolution/ Due/ 11/05/2004
System/ Lifesaving Subsystem/
Condition/ Wasted
Deficiency Cause/ Improper/Lack of Maintenance
Deficiency Description/ Replace tag lines on all L/F's as needed.
4. Activity #/ 1996809 Issue Date/ 05Oct2004 Issue Port/ MSO Tampa
Resolution/ Due/ 10/12/2004
System/ Construction/Loadline Subsystem/
Condition/ Fractured
Deficiency Cause/ Improper Installation
Deficiency Description/ Reseal cleat backing plates in store room and fuel oil room.
5. Activity #/ 1996809 Issue Date/ 05Oct2004 Issue Port/ MSO Tampa
Resolution/ Due/ 10/12/2004
System/ Accommodation/Occupational Safety Subsystem/
Condition/ Fractured
Deficiency Cause/ Improper/Lack of Maintenance
Deficiency Description/ Provide a support beam or repair 2nd deck overhead.
6. Activity #/ 1996809 Issue Date/ 05Oct2004 Issue Port/ MSO Tampa
Resolution/ Due/ 10/12/2004
System/ Electrical Subsystem/
Condition/ Loose
Deficiency Cause/ Placed in Improper Service
Deficiency Description/ Repair and properly mount engine battery switches.
7. Activity #/ 1996809 Issue Date/ 05Oct2004 Issue Port/ MSO Tampa
Resolution/ Due/ 10/12/2004
System/ Accommodation/Occupational Safety Subsystem/
Condition/ Missing

- Deficiency Cause/ Improper/Lack of Maintenance
 Deficiency Description/ Provide safety shields for both PORT and STBD PTO's.
8. Activity #/ 1996809 Issue Date/ 05Oct2004 Issue Port/ MSO Tampa
 Resolution/ Due/ 10/12/2004
 System/ Electrical Subsystem/
 Condition/ Missing
 Deficiency Cause/ Improper/Lack of Maintenance
 Deficiency Description/ Provide a light cover for light in E/R.
9. Activity #/ 1996809 Issue Date/ 05Oct2004 Issue Port/ MSO Tampa
 Resolution/ Due/ 10/12/2004
 System/ Lifesaving Subsystem/
 Condition/ Missing
 Deficiency Cause/ Improper/Lack of Maintenance
 Deficiency Description/ Label life preserver location with the size and amount.
10. Activity #/ 1996809 Issue Date/ 05Oct2004 Issue Port/ MSO Tampa
 Resolution/ Due/ 10/12/2004
 System/ Lifesaving Subsystem/
 Condition/ Blocked Event
 Deficiency Cause/ Improper/Lack of Maintenance
 Deficiency Description/ Remove all child (16total) life preservers, w/labels from vessel. Vsl COI states no children allowed. Vsl rep will remove.
11. Activity #/ 1996809 Issue Date/ 05Oct2004 Issue Port/ MSO Tampa
 Resolution/ Due/ 11/05/2004
 System/ Engineering Subsystem/
 Condition/ Missing
 Deficiency Cause/ Improper/Lack of Maintenance
 Deficiency Description/ Provide strainers for bilge pick-up lines as per 46CFR182.25.5(b).
12. Activity #/ 1996809 Issue Date/ 05Oct2004 Issue Port/ MSO Tampa
 Resolution/ Due/ 11/05/2004
 System/ Electrical Subsystem/
 Condition/ Blocked Event
 Deficiency Cause/ Improper/Lack of Maintenance
 Deficiency Description/ Secure wires and remove dead-ended wires as needed throughout vessel.

---Casualty Summary---

Since/ 18Oct1999

1. Activity #/ 1793975 Port/ MSO Tampa Start Date/ 16Mar2003
 Location/
 2. Activity #/ 1662364 Port/ MSO Tampa Start Date/ 16Aug2002
 Location/

END