

Figure 8
Dining Hall (Building 207)
4/2/03

Suspected Asbestos Containing Materials

MDH
Staff
Asbestos
Inspector

PCA
Staff
Asbestos Inspector

Drifting Snow





Figure 9 Building 107 (9/4/03)

Partially
Deconstructed
Radar Dome
↓



↑
Drums containing unknown
materials



Building 107
Suspected
Asbestos
Containing
Floor Tiles

Figure 10

Building 107
PCB Leaking Transformers
(6/14/03)




Figure 11
Building 303
Smoked Fish Business



Trash Piles



Fish Carcasses

