

# LOWER RIO GRANDE PRIORITIES - 2008

LOWER RIO GRANDE CITIZENS' FORUM

Carlos Marin, Commissioner

International Boundary and Water Commission, United States and Mexico, United States Section January 16, 2008

# LOWER RIO GRANDE FLOOD CONTROL PROJECT

- USIBWC studies have detected levee deficiencies; main concern is height, not structural
- FEMA will be updating Flood Insurance Rate Maps
- Property owners where levees are deficient may have to purchase flood insurance
- USIBWC is working to raise and rehabilitate deficient levees
- Recent funding has been \$2-3 million/year
- FY 08 appropriation of \$10 million for Rio Grande Flood Control Project

#### LOWER RIO GRANDE FLOOD CONTROL PROJECT – HIDALGO CO.

- USIBWC preparing for construction contract for Hidalgo Phase I
- 3.3 miles from Banker Floodway to Hidalgo-Reynosa Bridge
- 180 days estimated for construction
- Phase II design is underway
- Phase II entails floodwall construction at the bridges, a new levee east of the Hidalgo-San Juan pump house, and connection to the western terminus of the Hidalgo Hike & Bike Trail levee raising

#### HIDALGO PHASE I & II



#### 6+ feet overtop

2-4 ft.


0-2 ft.

freeboard

overtop

- + 6ft overtop
- 5 to 6 ft overtop
- 4 to 5 ft overtop
- 3 to 4 ft overtop
- 2 to 3 ft overtop
- 1 to 2 ft overtop
- 0 to 1 ft overtop
- 0 to 1 ft freeboard
- 1 to 2 ft freeboard
- 2 to 3 ft freeboard
- 3 to 4 ft freeboard
- 4 to 5 ft freeboard

4-5 ft. freeboard



## LOWER RIO GRANDE FLOOD CONTROL PROJECT – HIDALGO CO.



Levee was raised as part of the Hidalgo Hike & Bike Trail



#### LOWER RIO GRANDE FLOOD CONTROL PROJECT – HIDALGO CO.

- MOU signed with Hidalgo County Drainage District #1(HCDD#1) in July 2007
- Cooperative agreement for both agencies to do levee work in Hidalgo County
- HCDD #1 will rehab levees from Peñitas to Banker Inlet south of Mission in 3 phases totaling 17 miles
- HCDD#1 will use funding from local bond issue
- Schedule pending discussion with DHS on wall construction integral with levee; currently three phases planned for completion by August 2009

#### LOWER RIO GRANDE FLOOD CONTROL PROJECT – CAMERON CO.

- USIBWC has initiated levee-raising in Cameron County using our own personnel
- Will raise all deficient segments from Donna Pump to 26 miles downstream of Gateway Bridge
- Preliminary estimated cost of \$1.5 million
- Levee will be raised by up to 30 inches to ensure adequate freeboard
- Expected completion by summer 2008
- Additional work needed on interior floodways



### LOWER RIO GRANDE FLOOD CONTROL PROJECT – CAMERON CO.



Preparatory work on levee near Sabal Palm



#### LOWER RIO GRANDE FLOOD CONTROL PROJECT

- All Environmental Assessments have been completed for Rio Grande levee work in Hidalgo and Cameron Counties
- Design and construction undertaken as funding becomes available




- USIBWC has been coordinating with DHS on proposed border fencing
- Per 1970 Boundary Treaty, IBWC may not permit structures in the floodplain that obstruct or deflect normal or flood flows of the Rio Grande
- USIBWC flood control activities, including levee maintenance, must not be impeded



- USIBWC goal is to work with U.S. Department of Homeland Security (DHS) on a project compatible with the missions of both agencies
- USIBWC has proposed a fence design to DHS
- Discussions with DHS still underway with regard to fencing on or near USIBWC levee









DHS fence along a canal in Arizona



- USIBWC submitted comment letter to DHS on border fence Draft EIS
  - Ourges coordination with USIBWC on planned levee-raising
  - Notes that DHS references fencing on USIBWC right-of-way but does not indicate specific locations
  - Mentions USIBWC permitting requirements
  - Ourges consideration of fence impact on USIBWC wildlife corridor

- Routine dam safety inspection done in 2007
- Conducted by IBWC and technical advisors from U.S. Army Corps of Engineers and Mexico
- Dams are ranked per Corps of Engineers Dam Safety Action Classes:
  - DSAC I Urgent and Compelling (unsafe)
  - ○DSAC II Urgent (potentially unsafe)
  - DSAC III High Priority (conditionally unsafe)
  - DSAC IV Priority (marginally safe)
  - ○DSAC V Normal (safe)



#### INTERNATIONAL STORAGE DAMS

- Amistad Dam, Del Rio, TX Cd. Acuña, Coah.
  - Flood control, water storage, recreation, hydro power
  - Total capacity 4.9 maf (including flood storage)

- Falcon Dam, Falcon Heights, TX Nueva Cd. Guerrero, Tamps.
  - Flood control, water storage, recreation, hydro power
  - Total capacity 3.16 maf (including flood storage)
  - Provides water and flood control for Lower Rio Grande





#### AMISTAD DAM



**FALCON DAM** 

# ANZALDUAS DAM

- Located near McAllen, TX –
   Reynosa, Tamps.
- Diverts U.S. share of floodwaters to U.S. interior floodway
- Diverts irrigation water for Mexico





# RETAMAL DAM

- Built to limit flood flows at Brownsville, TX-Matamoros, Tamps.
- Diversion of Mexico's share of floodwaters to its interior floodway





 Report found all dams to be generally wellmaintained and able to operate under normal conditions

- Amistad Dam
  - DSAC II Urgent (potentially unsafe)
  - Concerns about impact of naturally-occurring sinkholes
  - Report recommends that a panel of geotechnical consultants be convened starting in the next funding request cycle

- Falcon Dam
  - ODSAC III High Priority (conditionally unsafe)
  - Concern about foundation seepage
  - Report recommends a comprehensive seepage analysis and evaluation of dam stability using current analytical methods to confirm or change the DSAC



- Anzalduas Dam
  - DSAC IV Priority (marginally safe)
  - Report recommends that IBWC continue to update electrical and mechanical systems, remove sediment near the dam
- Retamal Dam
  - DSAC III High Priority (conditionally unsafe)
  - Concern about central gate oscillation during floods
  - Recommends modifying flood operations to reduce use of central gate and replacing the gate lifting system



- IBWC conducts weekly monitoring as part of an early warning system
- USIBWC has \$225,000 in FY 08 for dam safety
- Will convene technical experts to initiate needed studies this year
- Additional investigations and possible repairs in subsequent fiscal years, subject to funding
- Dam safety reports available on USIBWC web page:
  - http://www.ibwc.state.gov/PAO/CURPRESS/2005/Dams.



#### MEXICO'S RIO GRANDE DELIVERIES

- Per 1944 Water Treaty, Mexico delivers water to U.S. from 6 Mexican tributaries
- USIBWC will continue to track Mexico's Rio Grande water deliveries to the U.S.
- 2002-2007 five-year water delivery cycle ended without a deficit
- Mexico has delivered 31,000 acre-feet so far during the 2007-2012 cycle



### MORILLO DRAIN

- Project to encase a portion of the drain was completed last summer
- The section was subject to erosion and other maintenance problems
- No plans for additional improvements in the near future
- Interest in piping additional sections as a long-term project



# INTERNATIONAL BOUNDARY AND WATER COMMISSION, UNITED STATES AND MEXICO UNITED STATES SECTION



www.ibwc.state.gov

(915) 832-4100