

Table of Contents

Section	Page No.
1.0 INTRODUCTION.....	1
2.0 BACKGROUND.....	1
2.1 <u>Significance of the Problem</u>	1
2.2 <u>Methods of Inspection</u>	2
2.2.1 Visual Testing (VT).....	2
2.2.2 Eddy Current Testing (ET).....	3
2.2.3 Ultrasonic Testing (UT).....	3
3.0 TEST PROCEDURE.....	6
3.1 <u>Nondestructive Testing</u>	6
3.2 <u>Destructive Analysis</u>	8
4.0 RESULTS.....	18
4.1 <u>Detectability</u>	18
4.2 <u>Flaw Sizing (Comparison with Etching Procedure)</u>	19
4.3 <u>EDM Results</u>	31
5.0 CONCLUSIONS AND RECOMMENDATIONS.....	34
Appendix A Glossary of Terms	
Appendix B: Bryant-Lee Associates Data Report on EDM and Measurement of Cracks on Aluminum Cylinder Samples	
Appendix C: Data Sheets	

List of Figures

Figure No.	Page No.
2-1 Illustration of the Site of Crack Initiation and its Propagation through the Cylinder.....	2
2-2 VT Equipment used to Visually Inspect the Compressed Gas Cylinders for this Project.....	2
2-3 Orientation of the Flaw with Respect to the Eddy Currents has a Direct Bearing on the Detection of the Flaw.....	3
2-4 Eddy Current Equipment used in the Project.....	4
2-5 Closeup of an Eddy Current Probe.....	4

2-6	UT Inspection System, Consisting of One Pitch and One Catch Probe Inside a Fluid-Filled Wheel.....	5
2-7	Example of a UT Inspection In Progress.....	5
3-1	Illustration of the Test Progression Used in the Project.....	7
3-2	Each Cylinder Head was Cut to Isolate the Cracks of Interest	9
3-3	The Apparatus used to Break Open the Cracks in a Cylinder Head.....	10
3-4	Close up View of the Crack Opening Procedure	10
3-5	Screen Shot of the Java Application ImageJ Produced by NIH, being used to Find the Cross-sectional Area of a Crack in a SCUBA Cylinder	11
3-6	Measuring the Extent of a Crack. The highlighted region shows the approximate extent of the crack along the line in the upper left image.	12
3-7	Photographs of the Red-Dye Penetrant Indication for (A) Cylinder Samples T94863 and (B) P4205. Arrows indicate cracks.....	14
3-8	Sketch Showing how the EM Wafers were Taken	15
3-9	Photographs of Cylinder Sample T94863 and P4205 Showing (a) the OD Surface and (b) the ID Surface	16
3-10	EDM Set-Up for Cylinder Sample.....	17
4-1	Reported Flaw Size for the Crack in SCUBA Cylinder P157756 for Each Inspection.....	22
4-2	Average Flaw Sizes for the Crack in P157756 for Technique and Skill Level	22
4-3	Reported Flaw Size for the Crack in SCUBA Cylinder P16297 for Each Inspection.....	23
4-4	Average Flaw Sizes for the Crack in P16297 for Technique and Skill Level	23
4-5	Reported Flaw Size for the First Crack in SCUBA Cylinder P101050 for Each Inspection.....	24
4-6	Average Flaw Sizes for the First Crack in P101050 for Technique and Skill Level	24

4-7 Reported Flaw Size for the Second Crack in SCUBA Cylinder P101050 For Each Inspection..... 25

4-8 Average Flaw Sizes for the Second Crack in P101050 for Technique and Skill Level..... 25

4-9 Reported Flaw Size for the First Crack in SCBA Cylinder T58636 for Each Inspection..... 26

4-10 Average Flaw Sizes for the First Crack in T58636 for Technique and Skill Level 26

4-11 Reported Flaw Size for the Second Crack in SCBA Cylinder T58636 for Each Inspection..... 27

4-12 Average Flaw Sizes for the Second Crack in T58636 for Technique and Skill Level..... 27

4-13 Mean Absolute Discrepancy (MAD) Results by Inspection..... 28

4-14 Mean Absolute Discrepancy (MAD) Results by Technique and Skill Level..... 28

4-15 Production of the UT Calibration Curve 30

4-16 Photomicrographs of the (a) apparent Crack Tip at 0.490-inch from Bore ID and (b) Crack Tip Region at 0.665-inch from Bore ID for Wafer A5..... 33

5-1 Summary of the Test Results, Plotting Each Technique’s Mean Absolute Discrepancy (MAD) Against it’s Reliability Index (RI). An ideal technique would be plotted at the origin (0,0), representing a technique that has no false calls and that perfectly sizes every flaw it detects. 36

5-2 Average Performances Across Technique and Skill Level. As in Figure 5-1 the ideal case is to be at the origin (0,0). 36

List of Tables

Table No.	Page No.
3-1 Nine Different NDT Inspections were Conducted for each of the 51 Cylinders.....	6
4-1 Summary of Results Using an Angular Width of $\pm 20^\circ$	18
4-2 Summary of Results Using an Angular Width of $\pm 30^\circ$	19

4-3	Cylinders Chosen for the Flaw Sizing Analysis	20
4-4	Summary of the Flaw Sizing Study	21
4-5	Example of the Aspect Ratios Seen During the Flaw Sizing Study	30
4-6	Wafer Location and Crack Depth for T94863	31
4-7	Wafer Location and Crack Depth for P4205	32
4-8	Reported Flaw Size for the Flaw in SCBA Cylinder T94863, for Which the Actual Flaw Size is Approximately 14 Threads	34
4-9	Reported Flaw Size for the Flaw in SCBA Cylinder T94863, for Which the Actual Flaw Size is Approximately 14 Threads	34