

(1) The information specified in paragraphs (b)(1) through (b)(3) of this section;

(2) The methods used for and results obtained from the radiation surveys required to demonstrate compliance with the radiological criteria for unrestricted use specified in 10 CFR 20.1402; and

(3) A supplement to the environmental report, under § 51.53, describing any new information or significant environmental change associated with the licensee's proposed release of the property.

(e) After receiving a license amendment application from the licensee for the release of an impacted area, the NRC shall—

(1) Determine whether the licensee has adequately evaluated the effect of releasing the property as required by paragraph (a)(1) of this section;

(2) Determine whether the licensee's classification of any release areas as non-impacted is adequately justified;

(3) Determine whether the licensee's radiation survey for an impacted area is adequate; and

(4) Upon determining that the licensee's submittal is adequate, approve the licensee's amendment application.

(f) The NRC shall notice receipt of the release approval request or license amendment application and make the approval request or license amendment application available for public comment. Before acting on an approval request or license amendment application submitted in accordance with this section, the NRC shall conduct a public meeting in the vicinity of the licensee's facility for the purpose of obtaining public comments on the proposed release of part of the facility or site. The NRC shall publish a document in the **Federal Register** and in a forum, such as local newspapers, which is readily accessible to individuals in the vicinity of the site, announcing the date, time, and location of the meeting, along with a brief description of the purpose of the meeting.

Dated in Rockville, Maryland, this 14th day of April, 2003.

For the Nuclear Regulatory Commission.

Annette L. Vietti-Cook,

Secretary of the Commission.

[FR Doc. 03-9866 Filed 4-21-03; 8:45 am]

BILLING CODE 7590-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-NM-23-AD; Amendment 39-13126; AD 2003-08-13]

RIN 2120-AA64

Airworthiness Directives; Various Surplus Military Airplanes Manufactured by Consolidated, Consolidated Vultee, and Convair

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to various surplus military airplanes manufactured by Consolidated, Consolidated Vultee, and Convair. This action requires repetitive inspections to find fatigue cracks in the lower rear cap of the wing front spar, front spar web, and lower skin of the wings; repair or replacement of any cracked part with a new part; and follow-on inspections at new intervals. This action is necessary to find and fix fatigue cracking, which could result in structural failure of the wings and consequent loss of control of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective May 7, 2003.

Comments for inclusion in the Rules Docket must be received on or before June 23, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2003-NM-23-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2003-NM-23-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

Information pertaining to this AD may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft

Certification Office, 3960 Paramount Boulevard, Lakewood, California.

FOR FURTHER INFORMATION CONTACT: John Cecil, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5228; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: On July 18, 2002, while dropping retardant on a fire near Lyons, Colorado, a United States Department of Agriculture (USDA) Forest Service Model P4Y-2 airplane was involved in an accident, resulting from the structural failure of the center wing. Investigation revealed fatigue cracking in the lower rear cap of the wing front spar, front spar web, and lower skin of the wings. The fatigue cracking has been attributed to the age, time-in-service, and flight cycles of the airplane. Such fatigue cracking, if not found and fixed in a timely manner, could result in structural failure of the wings and consequent loss of control of the airplane.

FAA's Determination

We have determined that high-cycle fatigue cracks in the area of the lower rear cap of the wing front spar, front spar web, and lower skin of the wings are likely to occur on various surplus military airplanes. Repetitive inspections of these areas are necessary to ensure that fatigue cracks will be found in a timely manner, and corrective action taken, to preclude crack growth to a size that would create an unacceptable risk of structural failure. While inspection methodologies exist that can be used to find cracks, we are currently unaware of any for the subject airplanes. Therefore, owners and operators must submit inspection procedures and repetitive inspection intervals to the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, for approval. The inspection procedures must be sufficiently reliable to determine the location, size, and orientation of cracks that are very small, so that the crack will not grow to a critical length at limit load before the next scheduled inspection.

If any crack is found during any inspection, operators must replace the cracked part with a new part; or repair and inspect at new intervals per a method approved by the FAA.

Explanation of the Requirements of the Rule

Since an unsafe condition has been identified that is likely to exist or develop on other surplus military airplanes of the same type design, this

AD is being issued to find and fix fatigue cracking of the wings, which could result in structural failure of the wings and consequent loss of control of the airplane. This AD requires repetitive inspections to find cracks in the lower rear cap of the wing front spar, front spar web, and lower skin of the wings; and repair or replacement of any cracked part with a new part; and follow-on inspections at new intervals.

Determination of Rule's Effective Date

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2003-NM-23-AD." The postcard will be date stamped and returned to the commenter.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

2003-08-13 Various surplus military airplanes manufactured by Consolidated, Consolidated Vultee, and Convair: Amendment 39-13126. Docket 2003-NM-23-AD.

Applicability: Including, but not limited to, all of the following surplus military airplanes, certificated in any category:

Consolidated Vultee Model PB4Y-1, P4Y-2, and LB-30 airplanes;
Consolidated and Convair Model B-24 airplanes; and
Consolidated Model C-109 and C-87 airplanes.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To find and fix fatigue cracking in the lower rear cap of the wing front spar, front spar web, and lower skin of the wings, which could result in structural failure of the wings and consequent loss of control of the airplane, accomplish the following:

Initial & Repetitive Inspections

(a) Within 30 days after the effective date of this AD, do the actions specified in paragraphs (a)(1) and (a)(2) of this AD per a method approved by the Manager, Los Angeles Certification Office (ACO), FAA.

(1) Do an inspection (between 39 and 63 inches outboard of the airplane center line on both the left and right sides of the wings) to find cracks in the lower rear cap of the wing front spar, front spar web, and lower skin of the wings localized under the front spar lower cap. Special detailed inspection procedures must be sufficiently reliable to determine the location, size, and orientation of the cracks.

(2) Develop repetitive inspection intervals that prevent crack growth from exceeding the minimum residual strength required to support limit load on the affected structure. The repetitive inspection intervals must be approved by the Manager, Los Angeles ACO. Thereafter, do the inspection approved per paragraph (a)(1) of this AD at the intervals approved per this paragraph.

(b) If any crack is found during any inspection required by this AD, before further flight, do the action(s) specified in paragraphs (b)(1) and (b)(2) of this AD per a method approved by the Manager, Los Angeles ACO.

(1) Repair or replace the cracked part or structure.

(2) Repeat the inspection required by paragraph (a)(1) of this AD at reduced intervals approved by the Manager, Los Angeles ACO to find cracks before the growth is critical and exceeds the minimum residual strength required to support limit load on the affected structure.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Effective Date

(e) This amendment becomes effective on May 7, 2003.

Issued in Renton, Washington, on April 16, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-9861 Filed 4-21-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 77

[Docket No. FAA-2003-14973; Special Federal Aviation Regulation No. 98]

RIN 2120-AH83

Construction or Alteration in the Vicinity of the Private Residence of the President of the United States

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Interim final rule; request for comments.

SUMMARY: This action requires that notice be filed with the FAA for the construction or alteration of any object that exceeds 50 feet above ground level (AGL) and is within the existing prohibited airspace surrounding the private residence of the President of the United States (P-49). Due to national security interests and the unique operating requirements of the United States Marine Corps (USMC) and the Secret Service Presidential Protective Division (SSPPD), this rule provides that any object within the designated area that exceeds the obstruction standard will be deemed a hazard to air navigation unless the FAA concludes,

based upon submitted information and in consultation with the USMC and the SSPPD, that the construction or alteration will not adversely affect safety and would not result in a hazard to air navigation. This rule is adopted for purposes of national defense and will assist in protecting the President of the United States. This rule does not apply to prior construction or alteration of objects and will terminate at the end of the President's term in office.

DATES: This final rule is effective April 22, 2003. Comments must be submitted on or before June 23, 2003.

ADDRESSES: Address your comments to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket number FAA-2003-14973 at the beginning of your comments, and you should submit two copies of your comments.

You may also submit comments through the Internet to <http://dms.dot.gov>. You may review the public docket containing comments to these proposed regulations in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Dockets Office is on the plaza level of the NASSIF Building at the Department of Transportation at the above address. Also, you may review public dockets on the Internet at <http://dms.dot.gov>.

FOR FURTHER INFORMATION CONTACT: Sheri Edgett-Baron, Airspace and Rules Division, ATA-400, Office of Air Traffic Airspace Management, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA is adopting this final rule without prior notice and prior public comment. The Regulatory Policies and Procedures of the Department of Transportation (DOT) (44 FR 1134; February 26, 1979), however, provide that, to the maximum extent possible, operating administrations for the DOT should provide an opportunity for public comment on regulations issued without prior notice. Accordingly, we invite interested persons to participate in this rulemaking by submitting such written data, views, or arguments, as they may desire. We also invite comments relating to environmental, energy, federalism, or international trade impacts that might result from this amendment. Please include the regulatory docket or amendment number and send two copies to the

address above. We will file all comments received, as well as a report summarizing each substantive public contact with FAA personnel on this rulemaking, in the public docket. The docket is available for public inspection before and after the comment closing date.

Anyone is able to search the electronic form of all comments received into any of our dockets by the name of the individual submitting the comment (or signing the comment, if submitted on behalf of an association, business, labor union, etc.). You may review DOT's complete Privacy Act statement in the **Federal Register** published on April 11, 2000 (Volume 65, Number 70; Pages 19477-78) or you may visit <http://dms.dot.gov>.

The FAA will consider all comments received on or before the closing date for comments. We will consider late comments to the extent practicable. We may amend this final rule in light of the comments received.

Commenters who want the FAA to acknowledge receipt of their comments submitted in response to this final rule must include a preaddressed, stamped postcard with those comments on which the following statement is made: "Comments to Docket No. FAA-2003-14973." The postcard will be date-stamped by the FAA and mailed to the commenter.

Availability of Final Rule

You can get an electronic copy using the Internet by:

- (1) Searching the Department of Transportation's electronic Docket Management System (DMS) Web page (<http://dms.dot.gov/search>)
- (2) Visiting the Office of Rulemaking's Web page at <http://www.faa.gov/avr/arm/index.cfm>; or
- (3) Accessing the Government Printing Office's Web page at http://www.access.gpo.gov/su_docs/aces/aces140.html.

You can also get a copy by submitting a request to the Federal Aviation Administration, Office of Rulemaking, ARM-1, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-9680. Make sure to identify the docket number, notice number, or amendment number of this rulemaking.

Small Business Regulatory Enforcement Fairness Act

The Small Business Regulatory Enforcement Fairness Act (SBREFA) of 1996 requires FAA to comply with small entity requests for information or advice about compliance with statutes and regulations within its jurisdiction.