


PA Monitoring Program

Checkdam Photographs from
March 2005 River Trip

A:15:005

No maintenance completed, checkdams have the aid of additional sediment and grasses to help stabilize the gully.



C:02:101

Grasses outline the gully with the checkdams.



C:13:069

Close up and overview of gully with checkdams.



Photo noting approximately 30cm of sediment deposited behind the check.



Grasses fill the gully with the checks.

C:13:099

Note approximately 30 cm of deposition behind the checkdam
(checkdams were placed here in FY95)



C:13:348

Brush structures with sediment and grasses



G:03:003

Additional vegetation and sediment in the gully

