

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 29

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 29

Facility Name: Peach Bottom 3 Docket (050- 00278)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	O - Operations	O - Control Room Ops	050-00278/2006-003
Number of Items for this Docket: 1			
Percent of Total for this Docket: 3			
<hr/>			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	G - Engineering	G - Design	050-00278/2006-004
140 - Problem not completely or accurately identified	Q - Quality assurance / oversight	D - Emergency Drill	050-00278/2006-003
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00278/2006-003
146 - Evaluation LTA	G - Engineering	G - Design	050-00278/2006-003
146 - Evaluation LTA	G - Engineering	G - Design	050-00278/2006-003
146 - Evaluation LTA	G - Engineering	G - Design	050-00278/2006-004
147 - Individual corrective action LTA	G - Engineering	G - Design	050-00278/2005-005
148 - Action not yet started or untimely	G - Engineering	G - Design	050-00278/2006-004
150 - Programmatic deficiency	G - Engineering	G - Design	050-00278/2006-004
Number of Items for this Docket: 9			
Percent of Total for this Docket: 31			
<hr/>			
Training / IR			
101 - Training process problem	O - Operations	O - Control Room Ops	050-00278/2006-003
Number of Items for this Docket: 1			
Percent of Total for this Docket: 3			
<hr/>			
Work Planning & Practices / IR			
183 - Pre-job activities LTA	M - Mechanical	M - Maintenance / Repair	050-00278/2006-004
183 - Pre-job activities LTA	O - Operations	O - Control Room Ops	050-00278/2006-004
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00278/2006-004
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00278/2006-004
186 - Failure to take action / meet requirements	D - Emergency Planning	D - Emergency Drill	050-00278/2006-003
186 - Failure to take action / meet requirements	T - Training	N - Training	050-00278/2006-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00278/2006-009
188 - Work practice or craft skill LTA	G - Engineering	G - Design	050-00278/2005-005
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00278/2005-005
188 - Work practice or craft skill LTA	I - Instrumentation & Control	T - Testing	050-00278/2006-002
188 - Work practice or craft skill LTA	M - Mechanical	T - Testing	050-00278/2005-005
188 - Work practice or craft skill LTA	Z - Other / Unknown	Z - Other / Unknown	050-00278/2005-005

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 29

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 29

Facility Name: Peach Bottom 3 Docket (050- 00278)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00278/2006-002
190 - Failure to stop work / non-conservative decision making	I - Instrumentation & Control	S - Surveillance	050-00278/2006-009
190 - Failure to stop work / non-conservative decision making	M - Mechanical	M - Maintenance / Repair	050-00278/2006-003
190 - Failure to stop work / non-conservative decision making	M - Mechanical	M - Maintenance / Repair	050-00278/2006-003
192 - Work untimely	I - Instrumentation & Control	S - Surveillance	050-00278/2006-002
194 - Housekeeping LTA	M - Mechanical	M - Maintenance / Repair	050-00278/2006-003
Number of Items for this Docket: 18			
Percent of Total for this Docket: 62			

Total Items for this Docket: 29
