

NTSB National Transportation Safety Board

Office of Railroad, Pipeline & Hazardous Materials Investigations

Human Performance

Amtrak's Engineer Training Program

Classroom

On-the-job training (OJT)

Testing



Accident Engineer's Exam Results

Initially failed two signals tests (NORAC and Amtrak)

Attempt	<u>NORAC</u>	<u>Amtrak</u>
1	*F	F
2	Р	F
3		Р

* Misidentified Restricting as a Slow Approach



Staff's Concerns

 Multiple failures suggest not proficient with signal recognition

Short term knowledge, not mastery

 Received engineer certification days later



Conclusion

The engineer did not show the signal recognition proficiency level necessary to operate on the territories where the accident occurred.





NTSB