

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Surry 2 Docket (050- 00281)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
173 - Physical conditions LTA	M - Mechanical	M - Maintenance / Repair	050-00281/2008-004
Number of Items for this Docket: 1 Percent of Total for this Docket: 4			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	E - Electrical	T - Testing	050-00281/2008-006
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00281/2007-005
111 - Procedure / reference document technical content	P - Procedure Writers	P - Procedure Dev	050-00281/2008-006
Number of Items for this Docket: 3 Percent of Total for this Docket: 12			
Problem Identification & Resolution / IR			
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00281/2008-002
147 - Individual corrective action LTA	E - Electrical	T - Testing	050-00281/2008-006
147 - Individual corrective action LTA	G - Engineering	G - Design	050-00281/2008-006
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00281/2008-004
Number of Items for this Docket: 4 Percent of Total for this Docket: 15			
Work Planning & Practices / IR			
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00281/2007-005
185 - Procedural adherence LTA	I - Instrumentation & Control	T - Testing	050-00281/2008-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00281/2007-005
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00281/2007-005
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00281/2007-005
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00281/2007-005
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00281/2008-002
186 - Failure to take action / meet requirements	G - Engineering	G - Design	050-00281/2007-005
186 - Failure to take action / meet requirements	G - Engineering	G - Design	050-00281/2008-006
186 - Failure to take action / meet requirements	G - Engineering	G - Design	050-00281/2008-006
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00281/2007-005
186 - Failure to take action / meet requirements	Q - Quality assurance / oversight	M - Maintenance / Repair	050-00281/2008-004
187 - Action implementation LTA	G - Engineering	G - Design	050-00281/2008-004
187 - Action implementation LTA	G - Engineering	G - Design	050-00281/2008-006
187 - Action implementation LTA	G - Engineering	G - Design	050-00281/2008-006

U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Surry 2 Docket (050- 00281)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
187 - Action implementation LTA	G - Engineering	G - Design	050-00281/2008-006
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00281/2007-005
190 - Failure to stop work / non-conservative decision making	M - Mechanical	M - Maintenance / Repair	050-00281/2007-005
Number of Items for this Docket: 18			
Percent of Total for this Docket: 69			

Total Items for this Docket: 26
