

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 25

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 25

---

**Facility Name: Peach Bottom 2 Docket (050- 00277)**

Details	Department	Work Type	Docket/Report
<b>Procedures &amp; Reference Document / IR</b>			
113 - Procedure / reference document development and maintenance L	G - Engineering	G - Design	050-00277/2005-008
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 4</b>			
<b>Problem Identification &amp; Resolution / IR</b>			
140 - Problem not completely or accurately identified	G - Engineering	G - Design	050-00277/2006-004
140 - Problem not completely or accurately identified	Q - Quality assurance / oversight	D - Emergency Drill	050-00277/2006-003
142 - Operating experience (OE) review LTA	G - Engineering	G - Design	050-00277/2005-008
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2005-008
146 - Evaluation LTA	G - Engineering	G - Design	050-00277/2006-003
146 - Evaluation LTA	G - Engineering	G - Design	050-00277/2006-004
148 - Action not yet started or untimely	G - Engineering	G - Design	050-00277/2006-004
148 - Action not yet started or untimely	M - Mechanical	T - Testing	050-00277/2005-005
150 - Programmatic deficiency	G - Engineering	G - Design	050-00277/2006-004
<b>Number of Items for this Docket: 9</b>			
<b>Percent of Total for this Docket: 36</b>			
<b>Training / IR</b>			
101 - Training process problem	O - Operations	O - Control Room Ops	050-00277/2006-003
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 4</b>			
<b>Work Planning &amp; Practices / IR</b>			
183 - Pre-job activities LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2006-004
183 - Pre-job activities LTA	O - Operations	O - Control Room Ops	050-00277/2006-004
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2006-004
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00277/2006-004
186 - Failure to take action / meet requirements	D - Emergency Planning	D - Emergency Drill	050-00277/2006-003
186 - Failure to take action / meet requirements	T - Training	N - Training	050-00277/2006-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00277/2006-009
188 - Work practice or craft skill LTA	G - Engineering	G - Design	050-00277/2005-005
188 - Work practice or craft skill LTA	I - Instrumentation & Control	T - Testing	050-00277/2006-002
188 - Work practice or craft skill LTA	Z - Other / Unknown	Z - Other / Unknown	050-00277/2005-005
190 - Failure to stop work / non-conservative decision making	I - Instrumentation & Control	S - Surveillance	050-00277/2006-009
190 - Failure to stop work / non-conservative decision making	M - Mechanical	M - Maintenance / Repair	050-00277/2006-003

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 25

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 25

---

**Facility Name: Peach Bottom 2 Docket (050- 00277)**

**Details**

**Work Planning & Practices / IR**

190 - Failure to stop work / non-conservative decision making

192 - Work untimely

**Department**

M - Mechanical

I - Instrumentation & Control

**Work Type**

M - Maintenance / Repair

S - Surveillance

**Docket/Report**

050-00277/2006-003

050-00277/2006-002

**Number of Items for this Docket: 14**

**Percent of Total for this Docket: 56**

---

**Total Items for this Docket: 25**

---