



1. View of site as seen from the north direction.



2. View of north area adjacent to the site, showing Overhead Door property.



3. Close-up view of north area adjacent to the site, showing Overhead Door property.



4. View of north area adjacent to the site, showing Palmetto Canal.



5. View of site as seen from the east direction.



6. View of east area adjacent to the site, with car dealership in background.



7. View of east area adjacent to the site, showing self carwash.



8. View of site as seen from the south direction.



9. View of south area adjacent to the site, showing residential and commercial buildings.



10. View of south area adjacent to the site, showing residential and commercial buildings.



11. View of south area adjacent to the site, showing closed auto parts shop.



12. View of site as seen from the west direction.



13. View of west area adjacent to the site, showing abandoned buildings.



14. View of west area adjacent to the site, showing abandoned buildings.



15. View of fifty gallon drums stored alongside pumps inside pump house.



16. View of power transformer inside pump house.



17. Battery banks inside pump house



18. Transformers on street - south side of building



19. Miscellaneous drums out side pump house on property.



20. Refuse piles on an adjacent parcel.



1. View of site as seen from the north direction, northeast half.



2. View of site as seen from the north direction, northwest half.



3. View of north area adjacent to the site, Delta Tire Company, in northwest corner.



4. View of north area adjacent to the site, road next to canal, in northeast corner.



5. View of north area adjacent to the site, observe abandoned buildings on road next to canal.



6. View of site as seen from the east direction.



7. View of east area adjacent to the site, in southeast side of North Broad, with fueling station in background.



8. View of east area adjacent to the site, northeast side of North Broad, with Delta gas station 2 blocks away.



9. View of site as seen from the south direction.



10. View of south area adjacent to the site, with Golden Express Market, and Santa's Auto Repair, in southwest area.



11. View of south area adjacent to the site, abandoned building in southeast corner.



12. View of site as seen from the west direction.



13. View of west area adjacent to the site, with abandoned Robert's Fresh Market, in southwest area.



14. View of west area adjacent to the site, with Calamari's Trim Shop and abandoned City's Cleaner's, in northwest area.



15. View of refurbished pump inside building.



16. View of miscellaneous 55 gallon drums alongside pump inside station building.



17. View of transformers located outside on west side of property. Several others were observed in the area.



18. View of 55 gallon drums stored outside the building, on the property.



1. View of site as seen from the north direction, northeast side.



2. View of site as seen from the north direction, in northwest area.



3. View of north area adjacent to the site, canal and railroad tracks.



4. View of fenced-in pit open to drainage canal and Real Wood Company, located in northwest area.



5. View of site as seen from the east direction, including buried fiber optic cable post.



6. View of east area adjacent to the site, observe railroad over pass.



7. View of east area adjacent to the site, across North Broad.



8. View of east area adjacent to the site, across North Broad, in southeast area.



9. View of site as seen from the south direction, in southwest area. Generator Building is located on left side.



10. View of site as seen from the south direction, in southeast area.



11. View of south area adjacent to the site, AP Tureau Street, in east area.



12. View of south area adjacent to the site, AP Tureau Street, in west area.



13. View of site as seen from the west direction, observe Generator Building to the right.



14. View of west area adjacent to the site, showing Real Wood Company and empty lot locations. Observe abandoned tires in north area.



15. View of west area adjacent to the site, showing the residential area across from Florida Avenue and AP Tureau Street, observe the transformers located at corner.



16. View of transformers located in southeast direction from building, across AP Tureau Street.



17. 55 gallon drums outside pump building on deck in southeast area.



18. View of pump lines in northeast corner.



19. Another view of fenced-in pit adjacent to railroad tracks in northwest area.



20. View of 55 gallon drums located inside pump building.



21. View of switches inside building.



22. View of fully enclosed pump.



23. View of breakers.



1. View of site as seen from the north direction. Observe abandoned chlorine AST's in foreground.



2. View of north area adjacent to the site, Warrington Drive, west side.



3. View of north area adjacent to the site, Warrington Drive, east side.



4. View of site as seen from the east direction.



5. View of east area adjacent to the site, Warrington Drive.



6. View of east area adjacent to the site, Prentiss Avenue.



7. View of site as seen from the south direction.



8. View of south area adjacent to the site, Warrington Drive, west side.



9. View of south area adjacent to the site, Warrington Drive, east side.



10. View of site as seen from the west direction, across canal.



11. View of west area adjacent to the site.



12. Abandoned chlorine storage tanks in northeast area.



13. Transformers and small building on property.



14. Transformers on Warrington Drive, north.



15. Transformers on Warrington Drive, south.



16. Electrical connections across canal, adjacent to Pratt Park.



17. Large man-hole, pump drain access, across canal.



18. 55 gallon drums and pipeline on property, transformers in rear.



1. View of site as seen from the north direction.



2. View of north area adjacent to the site, fuel tank, northeast corner on property.



3. View of north area adjacent to the site, railroad tracks



4. View of site as seen from the east direction.



5. View of east area adjacent to the site, railroad tracks follow power poles on left of picture.



6. View of site as seen from the south direction.



7. View of south area adjacent to the site.



8. View of south area adjacent to the site including transformer, southeast corner.



9. View of south area adjacent to the site including Southern Scrap, southwest corner.



10. View of site as seen from the west direction.



11. View of west area adjacent to the site, additional building and tower, northwest corner.



12. View of west area adjacent to the site, Florida Avenue Bridge, southwest corner.



13. 55 gallon drums next to screens, east side of building.



14. Tower, northwest corner.



15. Drums and pumps inside building.



1. View of site as seen from the north direction.



2. View of north area adjacent to the site, 17th Street canal.



3. View of north area adjacent to the site, west side of canal.



4. View of north area adjacent to the site, east side of canal.



5. Art studio across levee, northwest corner.



6. Electrical business, across levee, northwest corner.



7. View of site as seen from the east direction. Observe 55 gallon drums stored outside.



8. View of east area adjacent to the site, residential area over fence, southeast corner.



9. View of east area adjacent to the site, levee and flood wall, northeast corner.



10. View of site as seen from the south direction.



11. View of south area adjacent to the site, 17th Street canal.



12. View of south area adjacent to the site, parking lot and residential area behind fence, southwest corner.



13. View of south area adjacent to the site, canal screens.



14. View of site as seen from the west direction.



15. View of west area adjacent to the site, residential area, southwest corner.



16. View of west area adjacent to the site, railroad tracks, and residential area, northwest corner.



17. Oil and lubricant tanks, northwest corner of building.



18. Diesel tanks, northwest corner of property.



19. Transformer 'building', raised approximately two feet.



20. Transfer tower, electrical materials, southeast corner of property.



21. Example of 55 gallon drums outside building.



22. Refuse from the canal.



23. Pipelines and machinery, north side.



24. Example of 55 gallon drums inside building. Observe discoloration to concrete floor, some from transfer spillage.



25. Pumps inside building.



26. Switches inside building.



27. Electrical panels in the basement.



28. Battery banks near control center.



1. View of site as seen from the north direction.



2. View of north area adjacent to the site, canal.



3. View of north area adjacent to the site, pipes



4. View of site as seen from the east direction.



5. View of east area adjacent to the site, showing I-610.



6. View of east area adjacent to the site, railroad bridge.



7. View of site as seen from the south direction.



8. View of south area adjacent to the site, including air monitoring station in far center.



9. View of south area adjacent to the site, including empty chlorine tanks.



10. View of south area adjacent to the site, railroad bridge, southeast corner.



11. View of site as seen from the (south) west direction.



12. View of west area adjacent to the site, road over canal.



13. View of west area adjacent to the site, annex building and transfer building.



14. Underpass pumping station



15. Sewage pump across street, southeast corner.



16. Cell relay station and tower, southwest corner.



17. Example of transformer, northwest corner, showing I-10.



18. Transformers on property.



19. Insulated pipeline inside building.



20. 55 gallon drums inside building.



21. Battery bank inside building.



22. Large open hole filled with water.



23. Bottom of hole.



24. South side of station, showing tanks and air monitoring station.



1. View of site as seen from the north direction.



2. View of north area adjacent to the site, including gate indicator.



3. View of site as seen from the east direction.



4. View of east area adjacent to the site, southeast corner.



5. View of east area adjacent to the site, northeast corner.



6. View of site as seen from the south direction, including screens.



7. View of south area adjacent to the site, canal.



8. View of site as seen from the west direction.



9. View of west area adjacent to the site, northwest corner.



10. View of west area adjacent to the site, southwest corner.



11. 55 gallon drums outside building, southeast corner.



12. Entergy transformer, northeast corner.



13. Transformer west of building.



14. Leaky 55 gallon drums inside building.



15. Battery bank.



16. Antifreeze leak.



17. Pump motor.



18. Breakers.



1. View of north area of site as seen from the west direction.



2. View of north area adjacent to the site.



3. View of site as seen from the east direction. Observe leaking drums to right of picture.



4. View of east area adjacent to the site, where 2 - 30,000 diesel AST's are located.



5. View of east area adjacent to the site. Observe transformers in southeast corner past property fence lines.



6. View of site as seen from the south direction.



7. View of south area adjacent to the site, canal.



8. View of south area adjacent to the site, canal showing power lines.



9. View of site as seen from the west direction.



10. View of west area adjacent to the site, including Intracoastal Waterway.



11. View of leaking 55 gallon drums and 5 gallon containers stored in northeast corner of site.



12. View of 55 gallon drums of petroleum product stored inside building.



13. View of typical battery bank found at pump stations.



14. Air compressor tanks and mowers located inside building in southeast area.



15 Pipe with suspect insulation.



16. Oil leak from pump on floor. Observe oil pads used to soak up liquid.



1. View of site as seen from the north direction.



2. View of north area adjacent to the site, Russell's Marina Grill.



3. View of northwest area adjacent to the site, with apartments and restaurant. Observe transformers on poles in background across street.



4. View of site as seen from the east direction, showing bank next door.



5. View of southeast area adjacent to the site.



6. View of site as seen from the south direction. Observe transformers on poles located west of the site.



7. View of southwest area adjacent to the site.



8. View of south area adjacent to the site.



9. View of site as seen from the west direction. Observe transformer on pole west of Pontchartrain Boulevard.



10. View of west area adjacent to the site. Observe transformers on poles in northwest area.



11. View of west area adjacent to the site, two restaurants. Observe transformers on pole west of Pontchartrain Boulevard.



12. View of west area adjacent to the site, bed and breakfast. Observe pole transformer located southwest of site across Pontchartrain Boulevard.



13. Observe transformers northwest of site.



14. Partially demolished Rally's, in southwest area from site. Observe pole transformers in background.



15. View of rusting 55 gallon drums located on roof in northeast area.



16. Observe pumps and rusting 55 gallon drums located on roof in northeast area.



17. View of drums observed inside of building against west wall.



1. View of site as seen from the east direction. Observe two transformers at southeast corner of building.



2. View of east area adjacent to the site, showing barge traffic.



3. View of northeast area adjacent to the site.



4. View of east area adjacent to the site. Observe industrial buildings across Intracoastal Waterway from site.



5. View of site as seen from the north direction.



6. View of northwest area adjacent to the site. Reportedly, a septic tank is located near gate entrance.



7. View of northeast area adjacent to the site.



8. View of site as seen from the west direction.



9. View of west area adjacent to the site.



10. View of site as seen from the south direction.



11. View of south area adjacent to the site.



12. View of leaky dumpster observed in northwest corner of site.



13. View of 55 gallon drums stored outside of east side of building.



14. View of fuel tanks stored in southwest corner.



15. View of transformers and switchgear located southwest of site.



16. View of transformer north of property.



17. Empty propane storage tank observed in northeast area.



18. View of drums stored inside building.



19. Drums in use inside building.



20. Diesel engine.



1. View of site as seen from the north direction.



2. View of north area adjacent to the site with railroad tracks in foreground and Lake Pontchartrain in background.



3. View of site as seen from the east direction. Observe 55 gallon drums in southeast area and on roof.



4. View of east area adjacent to the site, north east corner.



5. View of east area adjacent to the site in southeast direction.



6. View of site as seen from the south direction.



7. View of south area adjacent to the site in southeast direction.



8. View of south area adjacent to the site in southwest direction.



9. View of site as seen from the west direction, showing 20,000 gallon diesel tanks.



10. View of west area adjacent to the site.



11. 55 gallon drums stored on top of the station building.



12. View of rusting, leaking 55 gallon drum located outside in southeast area.



1. View of site as seen from the north direction.



2. View of north area adjacent to the site, left of canal.



3. View of site as seen from the east direction.



4. View of east area adjacent to the site.



5. View of east area adjacent to the site.



6. View of site as seen from the south direction.



7. View of south area adjacent to the site.



8. View of site as seen from the west direction.



9. View of west area adjacent to the site, southwest corner.



10. View of west area adjacent to the site, northwest corner.



11. Partially buried UST diesel tanks in southwest area.



12. View of three transformers on stand located in northwest area from site.



13. View of empty, abandoned 55 gallon drum located north of site.



14. Drum and refuse at flood wall.



15. Various oils and lubricants inside building. Observe stains to concrete floor.



16. Various equipment inside building. Shows vertical pump that had been removed for repairs. Observe stains to concrete floor.



1. View of site as seen from the north direction.



2. View of north area adjacent to the site, in northeast direction.



3. View of north area adjacent to the site, in northwest corner.



4. View of site as seen from the east direction.



5. View of east area adjacent to the site.



6. View of site as seen from the south direction.



7. View of south area adjacent to the site, canal in southeast direction.



8. View of south area adjacent to the site, canal in southwest direction.



9. View of site as seen from the west direction.



10. View of west area adjacent to the site, showing transformers on property in northwest direction.



11. View of west area adjacent to the site, showing empty 55 gallon drums in southwest corner.



12. Additional transformer in northwest corner, owned by Entergy.



13. Observe drums of stored petroleum on second floor.



14. Loose electrical wiring from pump being repaired.



15. View of diesel fuel tanks in northwest area.



16. View of oil and lubricant containers stored near canal. Tires are part of debris removed from canal.



1. View of site as seen from the north direction.



2. View of north area adjacent to the site, from adjacent parking lot.



3. View of site as seen from the east direction.



4. View of east area adjacent to the site, northeast area.



5. View of east area adjacent to the site, southeast area.



6. View of site as seen from the south direction, southwest area.



7. View of site as seen from the south direction, southeast area.



8. View of south area adjacent to the site, showing rail traffic.



9. View of south area adjacent to the site, showing residential area.



10. View of site as seen from the west direction.



11. View of storage building, located in the west area adjacent to the site.



12. View of 55 gallon drums stored outside storage building.



13. View of transformers in east area.



14. View of transformers in west area.



15. Radio tower located on north side.



16. Fire proof storage room located in northwest area.



17. View of transformers located east of property.



18.

View of pump located inside building.



19. Drums and resistors located inside building.



20. Battery bank located against north wall.

****No photos from east side – inaccessible.**



1. View of site as seen from the north direction.



2. View of north area adjacent to the site, northwest corner.



3. View of north area adjacent to the site, northeast corner, including levee.



4. View of north area adjacent to the site, canal on other side of levee.



5. View of site as seen from the south direction.



6. View of south area adjacent to the site, canal.



7. View of south area adjacent to the site, west.



8. View of site as seen from the west direction, including transformers on the northeast corner.



9. View of west area adjacent to the site, southwest corner.



10. View of west area adjacent to the site.



11. Vertical pump motor



12. Transformers on the northeast corner.



13. Industrial area southeaset of station and canal.



14. Aquatic plants growing next to station.



1. View of site as seen from the north direction, left side.



2. View of site as seen from the north direction, right side.



3. View of site as seen from the north direction, building is located to left of picture.



4. View of Dolphin located in north area adjacent to the site.



5. View of north area adjacent to the site in southeast area.



6. View of site as seen from the east direction.



7. View of east area adjacent to the site, with Florida Avenue Bridge further east.



8. View of site as seen from the south direction.



9. View of south area adjacent to the site in southeast area.



10. View of south area adjacent to the site.



11. View of site as seen from the west direction.



12. View of west area adjacent to the site in northwest direction



13. View of west area adjacent to the site in northwest corner.



14. View of west area adjacent to the site, including generator building.



15. View of transformers, located on south side.



16. Tower south east of building.



17. Drums located outside OP-19 building in west area.



18. Generator building, east side.



19. Generator building, south side.



20. Generator building, west side.



21. Engines and drums inside generator building.



22. Underground storage tanks, for generator building located outside in west area.



23. Transformer observed on south of property.



24. Drums observed inside OP-19 building.



1. View of site as seen from the north direction.



2. View of north area adjacent to the site, showing railroad tracks.



3. View of north area adjacent to the site, showing railroad tracks, northeast corner.



4. View of site as seen from the east direction, southeast corner.



5. View of site as seen from the east direction, northeast corner.



6. View of east area adjacent to the site, railroad tracks.



7. View of east area adjacent to the site, southeast corner.



8. View of site as seen from the south direction.



9. View of south area adjacent to the site, new levee section.



10. View of south area adjacent to the site, pipelines over levee.



11. View of south area adjacent to the site, across levee.



12. View of site as seen from the west direction.



13. View of west area adjacent to the site.



14. Fuel tank, northeast corner.



15. Plants growing under fuel tank.



16. Industrial area over levee, southwest corner.



17. Refuse from canal.



18. 55 gallon drums under pipeline.



19. Tanks, drums, and switches inside building.



20. Antifreeze puddle near engine.



21. Oil stains by engine.



1. View of site as seen from the north direction.



2. View of north area adjacent to the site, canal.



3. View of north area adjacent to the site, road.



4. View of site as seen from the east direction.



5. View of east area adjacent to the site, including levee.



6. View of east area adjacent to the site, northeast corner.



7. View of site as seen from the south direction.



8. View of south area adjacent to the site, pipelines going over levee.



9. View of south area adjacent to the site, southwest corner.



10. View of site as seen from the west direction.



11. View of west area adjacent to the site, northwest corner.



12. View of west area adjacent to the site, southwest corner.



13. South view over levee



14. Pumps on canal



15. Drums inside levee



16. Pump motor inside building



1. View of site as seen from the north direction.



2. View of north side of site north from inside walls, showing pipelines.



3. View of north area adjacent to the site, northeast corner.



4. View of north area adjacent to the site.



5. View of site as seen from the east direction.



6. View of east area adjacent to the site.



7. View of site as seen from the south direction.



8. View of south area adjacent to the site along road.



9. View of site as seen from the west direction.



10. View of west area adjacent to the site.



11. View of west area adjacent to the site, southwest corner.



12. Transformers, southwest corner across road.



13. Fuel storage tank, northwest corner inside property.



14. Gas line, residential area, southwest corner.



15. Unknown pipeline and man hole, west side, across road.



16. Transformers on poles, southwest corner.



17. Diesel engine, pump motor and various drums inside building.



18. Battery bank and switch boxes inside building.



1. View of site as seen from the north direction.



2. View of north area adjacent to the site, along Live Oak Street.



3. View of site as seen from the east direction.



4. View of east area adjacent to the site, including right of way across street.



5. View of site as seen from the south direction.



6. View of south area adjacent to the site, southwest corner.



7. View of site as seen from the west direction.



8. View of west area adjacent to the site, across canal.



9. View of west area adjacent to the site, including Airline Highway.



10. Fuel storage tank under grating on north side of building.



11. Example of transformers in the area, North side.



12. Fuel transfer box, southwest corner.



13. Diesel engine, lubricants and fuel tank inside building.



14. 55 gallon drums and pump motor inside building.



15. Battery bank.



16. Batteries for diesel engine.




1. View of site as seen from the north direction.



2. View of north area adjacent to the site, showing bottom of radio tower.



3. View of north area adjacent to the site, showing top of radio tower.



4. View of site as seen from the east direction.



5. View of east area adjacent to the site, southeast corner.



6. View of east area adjacent to the site, northeast corner.



7. View of site as seen from the south direction.



8. View of south area adjacent to the site, along canal.



9. View of south area adjacent to the site, southeast corner, along canal.



10. View of site as seen from the west direction.



11. View of west area adjacent to the site, southwest corner, showing railroad and buried fiber optic cable.



12. View of west area adjacent to the site, southwest corner, showing railroad and Airline Highway.



13. Six transformers located east of property. Three of the six had rust, but containment was not compromised.



14. Pipes and railroad tracks across canal, northwest corner.



15. Unknown refuse along railroad tracks.



1. View of site as seen from the north direction, left side.



2. View of site as seen from the north direction, right side.



3. View of north area adjacent to the site, Earhart Boulevard, showing self carwash in background.



4. View of north area adjacent to the site, across Earhart Boulevard, showing school buses.



5. View of site as seen from the east direction, right side.



6. View of site as seen from the east direction, left side.



7. View of east area adjacent to the site, showing paint store and warehouse.



8. View of east area adjacent to the site



9. View of site as seen from the south direction, including transformers.



10. View of south area adjacent to the site.



11. View of south area adjacent to the site.



12. View of site as seen from the west direction.



13. View of west area adjacent to the site, adjacent warehouse.



14. View of west area adjacent to the site, transformers.



15. Transformers on property, and power lines in area.



16. Drums and equipment inside building.



17. Frequency changer.



1. View of site as seen from the north direction, left side.



2. View of north area adjacent to the site, boat yard.



3. View of north area adjacent to the site, boat yard, shopping area and levee.



4. View of north area adjacent to the site, boat yard and transformer.



5. View of site as seen from the east direction.



6. View of east area adjacent to the site, boat shop.



7. View of east area adjacent to the site, stables.



8. View of site as seen from the south direction, including transformers and pipeline.



9. View of south area adjacent to the site, showing pipeline and stacks.



10. View of south area adjacent to the site, top of levee, northwest.



11. View of south area adjacent to the site, top of levee, southwest, with radio tower.



12. View of site as seen from the west direction.



13. View of west area adjacent to the site, across wall residential.



14. View of west area adjacent to the site, across wall, shopping area.



15. Entrance to intake pier.



16. Screens around intake.



17. Office at end of pier.



18. Mississippi River at end of pier.



19. Switches on property south of building.



20. Switches inside building.



21. Intake pipe inside building.



22. Battery bank.



23. Pumps and piping inside building.



24. Drums outside building.



1. View of site as seen from the north direction, entrance on Eagle Street.



2. View of north area adjacent to the site, gas station on South Claiborne Avenue.



3. Water tanks in northwest corner of site.



4. South Claiborne Avenue looking east from north east corner of site.



5. View of east side of site as seen from the north east corner looking south.



6. View of center of site from east side.



7. View of east area adjacent to the site, hardware store on corner of Leonidas and Spruce Streets.



8. View of oil stained pavement and machine parts in south east corner of site at Spruce and Leonidas Streets.



10. View along Spruce street on south side of site looking west.



11. View of south side of low-lift building as seen from the south looking northwest.



12. View of leak from low-lift building onto Spruce Street.



13. Close up view of damage due to leak from low-lift building.



14. South entrance to plant on Eagle Street.



15. View of large diesel tank on General Ogden Street looking from north to south.



16. View of site and Cohn Street looking from east to west.



17. View of south of site from intersection of Cohn and Hollygrove Streets.



18. View of south of site from intersection of Cohn and Hamilton Streets.



19. View of south of site from end of Hamilton Street looking west.



20. View of south of site from end of Hamilton Street looking south.



21. View of Monticello Avenue from southwest corner of site looking southwest.



22. View of southwest corner of site looking north along Monticello Avenue.



23. View of water tanks and Monticello Avenue from northwest corner of site looking south.



24. View of northwest corner of site looking north.



25. Ammonia tanks behind main building at entrance.



26. Ammonia tanks behind main building at entrance.



27. Clarifloc tanks next to ammonia tanks.



28. Equipment inside ammonia building.



29. Chlorine railcars on Eagle Street in the middle of the site.



30. Power house and boiler room building on Eagle Street located in south area of site.



31. Looking in north direction along Eagle Street from middle of site.



32. West side of old filter gallery building.



33. Observed stains on transformers located on north side of power house.



34. South side of Sycamore substation building.



35. Switches and transformers located inside Sycamore substation.



36. West side of Panola Street pump station.



37. Pump located inside Panola Street station.



38. Breakers located inside Panola Street station.



39. Oil lubricants located inside Panola Street station, observed open container.



40. Observed standing water in large hole at corner of building.



41. Gas line and meter on Leonidas Street on S&WB property.



42. Transformer near gas line.



43. Meter building north of frequency changer building.



44. Frequency Changer located inside frequency changer building.



45. Breaker and switches inside frequency changer building.



46. North side of central control building, entrance located near truck in right of picture.



47. Controls inside central control building.



48. 40 Batteries located in central control battery room.



49. Vent and diesel AST located south of central control building.



50. Gas compression building adjacent to power house.



51. View of storage yard in south east corner where oil-stained pavement was observed.



52. East side of high-lift building.



53. Welding station in southeast area of site.



54. West side of Boiler room.



55. Boiler in boiler building.



56. New pump in boiler building.



57. Asbestos wrapped duct insulation located on roof.



58. Diesel pump room in boiler house.



59. Chemicals stored in barrels used for water treatment.



60. Basement of boiler house.



61. Diesel storage tank in basement.



62. Transformers in basement of boiler room.



63. Boiler insulation that may contain asbestos.



64. 55 gallon drums stored in basement of high-lift building.



65. Miscellaneous containers storing petroleum products.



66. Pumps in the low-lift building.



67. Drums containing petroleum products in low-lift building, observed open containers.



68. View south on Eagle Street.



69. East side of meter building.



70. Electric parts storage house.



71. Above ground storage tanks located north of meter building.



72. Location of underground storage tank with four vents.



73. Monitoring well for underground storage tank.



74. Old chlorine building, now used for pipe storage.



75. West side of 5 K. V. Building with breakers and switches located inside.



76. West entrance to power house.



77. Stored 55 gallon drums in building.



78. Pumps in power house.



79. East side of machine shop building.



80. View of 55 gallon drums, waste oil tanks, 5 gallon, acetylene tanks and oxygen tanks stored on west side of machine shop.



81. North and east side of electrical shop building.



82. 55 gallon drums inside electrical shop.



83. Flammable cabinet inside machine shop with flammables on top.



84. Southeast corner of chemical house.



85. Transformers on south side of chemical house.



86. Lime storage dumpster in the chemical house.



87. Oil drum storage in chemical house, observe standing liquid in spill tray, stains on concrete, open containers.



88. Two chlorine rail tanks, two ferric sulfate tanks and two clarifloc tanks southwest of chemical house.



89. Example of polymer and ferric pump room buildings.



90. Laborers' shack southwest of chemical house.



91. One and a half-million gallon diesel tanks on site in southwest area, one empty.



92. Sludge pump house southwest of chemical house visible in background.



93. Gas station on south side of Spruce Street Warehouse, includes gas dispensers.



94. Close up of UST cover plates.



95. Diesel pump observe stains on concrete and surrounding dirt.



96. Diesel AST behind diesel pump that is stored in berm enclosure for one and a half million gallon tanks.



97. Pumps in foreground for UST located north of meter shop, orange tank in background for fire suppression system and abandoned fiberglass tank.



98. Generator for the electrical shop and large blue diesel tank.



99. Waste storage tanks and transformer south of Spruce Street warehouse.




100. Gas station supply room.



101. Northeast corner of Spruce Street warehouse showing propane tank cage.



102. Welding tanks located at northwest corner of the welding and fabrication shop.



103. New garage and electric storage building, located north of welding shop.



104. Boat house located north of meter shop.



105. Guard house located at south gate on Eagle Street and Spruce Street.



106. East side of meter shop.



107. Carpenter building southwest area of site.



108. Empty tank southwest of carpenter building.



109. North side of Hamilton Street substation.



110. Breakers and switches inside Hamilton Street substation.



111. Transformer on west side of Hamilton Street substation.



112. East side of Hamilton Street warehouse.



113. Metal parts stored in Hamilton Street warehouse.



114. Open metal container with gaskets soaking in oil.

**** no access to east side of building****



1. View of site as seen from the north direction.



2. View of north area adjacent to the site, showing access road, transformers and additional building.



3. View of north area adjacent to the site, showing transformers, stacks and pipes.



4. View of site as seen from the south direction.



5. View of south area adjacent to the site.



6. View of south area adjacent to the site.



7. View of site as seen from the west direction.



8. View of west area adjacent to the site.



9. View of west area adjacent to the site, access to pier.



10. View of west area adjacent to the site, adjacent industrial area.



11. Additional building on access road, showing tanks formerly containing poly-electrolytes.



12. Additional building on access road.



13. Potassium permanganate tank.



14. Transformers on access road.



15. Purification treatment equipment, mixing tank for poly-electrolytes, no longer in use.



16. Stacks on top of levee, vacuum pumps.



17. Inside main building, switches, drums and pumping equipment.



18. Battery banks in main building.