

From: LarryEvans@bcpeabody.com
To: [Yousev_Garcia; \[FOIA Exemption \(b\)\(6\)\]_SAJ](mailto:Yousev_Garcia@[FOIA Exemption (b)(6)]_SAJ); [\[FOIA Exemption \(b\)\(6\)\]_SAJ](mailto:[FOIA Exemption (b)(6)]_SAJ)
Cc: [Daniel Pagan](mailto:Daniel_Pagan); IVELISSE_SANCHEZ; andrewgoetz@bcpeabody.com; johannawillis@bcpeabody.com; kencaraccia@bcpeabody.com
Subject: re: HDD Profiles Rio Indio and Rio Bayamón
Date: Sunday, June 12, 2011 9:10:23 PM

Thank you Yousev -

These two documents show where the HDD workpad is proposed on the east side of the river. The HDD pullback area is also depicted. I'll check with [FOIA Exemption (b)(6)] tomorrow to see if this information gives [FOIA Exemption (b)(6)] enough data to postulate potential risk to archaeological boundaries. Thank you again for the quick response to my email!!

Best regards!

Lawrence C. Evans
503.781.7930 (cell)
larryevans@bcpeabody.com
iyutka53@aol.com

From: "Yousev Garcia" <yousevgr@yahoo.com>
Sent: Sunday, June 12, 2011 7:48 PM
To: "[FOIA Exemption (b)(6)]" <[FOIA Exemption (b)(6)]@usace.army.mil>, "[FOIA Exemption (b)(6)]" <[FOIA Exemption (b)(6)]@usace.army.mil>, LarryEvans@bcpeabody.com
Subject: re: HDD Profiles Rio Indio and Rio Bayamón

Larry:

While we wait for the alignment sheets to be updated, attached are two aerial photos (1995 & 2006) with the proposed Rio Indio hdd crossing & required working pads overlaid. Please note that no trench will be excavated within the pink area to the north, since that will be only the required space for pipe welding and pulling racks. Also note that the hdd exit is near the karst geology and trenchin along alluvial deposits will be limited to aprox 175 meters long.

Yousev

--- On Sat, 6/11/11, LarryEvans@bcpeabody.com <LarryEvans@bcpeabody.com> wrote:

From: LarryEvans@bcpeabody.com <LarryEvans@bcpeabody.com>
Subject: re: HDD Profiles Rio Indio and Rio Bayamón
To: "Yousev Garcia" <yousevgr@yahoo.com>, "[FOIA Exemption (b)(6)]" <[FOIA Exemption (b)(6)]@usace.army.mil>, "[FOIA Exemption (b)(6)]" <[FOIA Exemption (b)(6)]@usace.army.mil>
Cc: "Daniel Pagan" <daniel_paganrosa@yahoo.com>, "IVELISSE SANCHEZ" <I-SANCHEZ@PREPA.COM>
Date: Saturday, June 11, 2011, 5:21 AM

G'morning Yousev -

Notwithstanding the fact that this 325 map for the Rio Indio crossing shows the pipeline corridor extending north underneath PR-22 (which has been changed to have the pipeline run parallel to the southern side of PR-22 as it proceeds to the east at this location) does the 325 drawing still correctly identify the location of the HDD workpads on both sides of the Rio Indio? Is it possible we could provide Bob with three maps:

1. 325.10 (this map which provides the depths of the proposed HDD crossing)
2. Wetland Impact Map 66 (which shows the correct/updated pipeline corridor alignment with wetland areas) and,
3. The updated construction alignment drawing 321.72_Rev(?) which should show the current "final" alignment for the pipeline where it crosses Rio Indio and turns east along PR-22

With these three documents, I might suggest David and the Corps would have enough information to answer their questions about possible impacts near the archaeological site where we propose to work and David could give Bob feedback for us so we can consider moving the HDD workpad closer to PR-22 to avoid possible impacts, etc.

Thoughts?

In the meantime, I recommend we have PREPA (or whomever) immediately update the 325 series of HDD profile documents so they reflect the current HDD crossing locations, etc.

Lawrence C. Evans
503.781.7930 (cell)
larryevans@bcpeabody.com
iyutka53@aol.com

From: "Yousev Garcia" <yousevgr@yahoo.com>
Sent: Friday, June 10, 2011 11:44 AM
To: "FOIA Exemption (b)(6)" <FOIA Exemption (b)(6)@usace.army.mil>, "FOIA Exemption (b)(6)" <FOIA Exemption (b)(6)@usace.army.mil>, "Larry Evans" <LarryEvans@bcpeabody.com>
Subject: HDD Profiles Rio Indio and Rio Bayamón

Gentlemen:

Please note that these are not final, particularly the Rio Indio one illustrate a consecutive hdd to the north that was discarded.

Yousev