9.4.3 Case Study, (Service/Reta	The Visitor Center at Zion National Park, Utah iil/Office)	
<b>Building Design</b> Vistors Center (1):	8,800 SF Comfort Station (2): 2,756 SF Fee Station: 170 SF	
<u>Shell</u> Windows	<u>Type</u> <u>U-Factor</u> <u>SHGC (3</u>	<u>)</u>
South/East Glass North/West Glass	Double Pane Insulating Glass, Low-e, Aluminum Frames, Thermally Broken0.440.44Double Pane Insulating Glass, Heat Mirror, Aluminum Frames, Thermally Broken0.370.37	
Window/Wall Ratio:	28%	
Wall/Roof Trombe Walls: Vistor Center Walls: Comfort Station Walls:	MaterialsEffective R-ValueLow-iron Patterned Trombe Wall, CMU (4)2.3Wood Siding, Rigid Insulation Board, Gypsum16.5Wood Siding, Rigid Insulation Board, CMU (4)6.6	
Roof:	Wood Shingles; Sheathing; Insulated Roof Panels 30.9	
HVAC		
<u>Heating</u> Trombe Walls Electric Radiant Ceiling	Cooling   Operable Windows   Panels 3 Cooling Towers	
Lighting Power DensitiMain Area:(5)Offices:1.0Bookstore:0.9		
<u>Energy/Power:</u> PV System: Net Annual Energy Usag	7.2 kW grid-tie system ge (thousand Btu/SF*year): 27.0	
vistors center an Source(s): NREL, Evaluation	ce, bookstore, and service areas. 2) Restroom complex. 3) Solar heat gain coefficient. 4) Concrete masonry unit. 5) The r rea is handled almost entirely with daylighting. Auxiliary fluorescent lighting is used only occasionally to supplement. n of the Low-Energy Design and Energy Performance of the Zion National Park Visitors Center, Feb. 2005, p. 23-37; NREL, Lessons se Studies of Six High-Performance Buildings, June 2006, p. 5 Table A-2 p. 130.	nain

March 2012

Buildings Energy Data Book: 9.4 High Performance Buildings