

ATC ID #	Northing	Easting	Azimuth	Inclination	Depth	Material of Item	Length	Width	Thickness	Aspect Ratio	Weight, lbs	Weight, g	Image
105 ATC035	4369674.287	402866.401	46.6	2.9	0.90	Forged Steel	463	105	105	0.227	30	13608	Direct Fire Recovery Pics Reconfiguration 07\DSCN4441.JPG
105 ATC058	4369696.544	402861.393	310.7	29.5	1.28	Forged Steel	463	105	105	0.227	30	13608	Direct Fire Recovery Pics Reconfiguration 07\DSCN4707.JPG
105 ATC065	4369704.242	402857.557	48.3	73.6	0.60	Forged Steel	463	105	105	0.227	30	13608	Direct Fire Recovery Pics Reconfiguration 07\DSCN4439.JPG
105 ATC086	4369725.171	402805.021	226.0	40.0	1.93	Forged Steel	463	105	105	0.227	30	13608	Direct Fire Recovery Pics Reconfiguration 07\DSCN4438.JPG
105 NS ATC101	4369716.595	402791.642	350.0	32.0	1.23	Forged Steel	388	105	105	0.271	28.86	12740	Direct Fire Recovery Pics Reconfiguration 07\DSCN4653.JPG
105 NS ATC103	4369677.672	402833.125	359.2	30.1	0.45	Forged Steel	388	105	105	0.271	28.86	12740	Direct Fire Recovery Pics Reconfiguration 07\DSCN4440.JPG
105H ATC008	4369710.352	402817.123	243.8	-21.6	0.55	Forged Steel	641	105	105	0.164	20.00	9072.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4652.JPG
105H ATC009	4369648.638	402822.272	145.6	56.0	0.57	Forged Steel	641	105	105	0.164	20.00	9072.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4445.JPG
105H ATC012	4369731.272	402809.662	20.0	35.6	0.72	Forged Steel	641	105	105	0.164	20.00	9072.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4442.JPG
105H ATC051	4369681.053	402872.829	212.7	86.7	0.77	Forged Steel	641	105	105	0.164	20.00	9072.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4443.JPG
105H ATC059	4369735.913	402817.867	118.7	37.9	0.39	Forged Steel	641	105	105	0.164	20.00	9072.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4444.JPG
155 ATC003	4369687.338	402869.022	354.2	54.6	1.54	Forged Steel/Aluminum	870	155	155	0.178	56.45	25606.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4673.JPG
155 ATC006	4369738.122	402802.875	198.5	49.0	1.60	Forged Steel/Aluminum	870	155	155	0.178	56.45	25606.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4689.JPG
155 ATC007	4369695.741	402786.776	250.4	59.8	2.21	Forged Steel/Aluminum	870	155	155	0.178	56.45	25606.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4625.JPG
155 ATC040	4369682.554	402834.208	68.6	60.9	1.47	Forged Steel/Aluminum	870	155	155	0.178	56.45	25606.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4588.JPG
155 ATC165	4369688.493	402860.614	212.0	80.0	0.62	Forged Steel/Aluminum	870	155	155	0.178	56.45	25606.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4715.JPG
155 NS ATC025	4369682.163	402817.415	118.4	33.0	0.37	Forged Steel/Aluminum	870	155	155	0.178	56.45	25606.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4598.JPG
2.75 ATC032	4369680.748	402819.539	40.2	-5.2	0.08	Cast Iron	403	72	72	0.179	8.95	4060	Direct Fire Recovery Pics Reconfiguration 07\DSCN4615.JPG
2.75 ATC038	4369726.875	402830.103	81.9	-26.6	0.84	Cast Iron	403	72	72	0.179	8.95	4060	Direct Fire Recovery Pics Reconfiguration 07\DSCN4718.JPG
2.75 ATC063	4369712.832	402804.930	157.1	35.9	0.28	Cast Iron	403	72	72	0.179	8.95	4060	Direct Fire Recovery Pics Reconfiguration 07\DSCN4622.JPG
2.75 NS ATC024	4369671.089	402800.995	59.0	2.1	0.10	Cast Iron	403	72	72	0.179	8.95	4060	Direct Fire Recovery Pics Reconfiguration 07\DSCN4621.JPG
2.75 NS ATC113	4369698.200	402836.566	124.2	-26.6	0.27	Cast Iron	403	72	72	0.179	8.95	4060	Direct Fire Recovery Pics Reconfiguration 07\DSCN4701.JPG
2.75 NS ATC119	4369656.785	402825.962	53.0	4.7	0.08	Cast Iron	403	72	72	0.179	8.95	4060	Direct Fire Recovery Pics Reconfiguration 07\DSCN4586.JPG
2.75 NS ATC120	4369697.524	402781.572	350.0	49.0	0.45	Cast Iron	403	72	72	0.179	8.95	4060	Direct Fire Recovery Pics Reconfiguration 07\DSCN4624.JPG
2.75 XM229 ATC002	4369636.743	402837.855	326.9	-23.8	0.30	Ferrous	830	72	72	0.087	18.35	8324	Direct Fire Recovery Pics Reconfiguration 07\DSCN4578.JPG
2.75 XM229 ATC003	4369650.544	402835.699	169.1	-8.3	0.14	Ferrous	830	72	72	0.087	18.35	8324	Direct Fire Recovery Pics Reconfiguration 07\DSCN4585.JPG
2.75 XM229 ATC006	4369663.333	402825.014	114.8	38.5	1.02	Ferrous	830	72	72	0.087	18.35	8324	Direct Fire Recovery Pics Reconfiguration 07\DSCN4583.JPG
20 M55 ATC146	4369741.516	402806.087	9.1	15.5	0.38	Alloy Steel	75	20	20	0.267	0.2	91	Direct Fire Recovery Pics Reconfiguration 07\DSCN4685.JPG
20 M97 NS ATC096	4369709.861	402801.427	93.0	58.0	0.34	Alloy Steel	87	20	20	0.23	0.25	113	Direct Fire Recovery Pics Reconfiguration 07\DSCN4619.JPG
40 M385 ATC200	4369644.185	402847.536	43.2	37.0	0.04	Aluminum w Ferrous Band	80	40	40	0.500	0.55	249.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4576.JPG
40 M385 NS ATC019	4369642.162	402850.296	124.1	66.4	0.16	Aluminum w Ferrous Band	80	40	40	0.500	0.55	249.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4577.JPG
40 M385 NS ATC066	4369657.620	402821.164	255.0	34.0	0.06	Aluminum w Ferrous Band	80	40	40	0.500	0.55	249.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4575.JPG
40 M813 NS ATC032	4369743.001	402814.828	341.7	2.7	0.16	Alloy Steel	207	40	40	0.193	2.15	972	Direct Fire Recovery Pics Reconfiguration 07\DSCN4681.JPG
40 M813 NS ATC033	4369693.304	402868.826	25.5	83.7	0.17	Alloy Steel	207	40	40	0.193	2.15	972	Direct Fire Recovery Pics Reconfiguration 07\DSCN4670.JPG
40 M813 NS ATC034	4369710.040	402851.343	224.7	14.7	0.46	Alloy Steel	207	40	40	0.193	2.15	972	Direct Fire Recovery Pics Reconfiguration 07\DSCN4669.JPG
40 M813 NS ATC039	4369691.126	402870.838	238.6	23.0	0.51	Alloy Steel	207	40	40	0.193	2.15	972	Direct Fire Recovery Pics Reconfiguration 07\DSCN4658.JPG
57 M86 ATC008	4369713.295	402786.605	113.8	24.8	0.44	Steel	170	57	57	0.335	6	2722	Direct Fire Recovery Pics Reconfiguration 07\DSCN4623.JPG
57 M86 ATC020	4369672.202	402792.559	212.9	88.0	0.67	Steel	170	57	57	0.335	6	2722	Direct Fire Recovery Pics Reconfiguration 07\DSCN4613.JPG
60 M49 ATC113	4369681.498	402815.744	346.4	-51.2	0.12	Cast PMI/Forged Steel	240	60	60	0.250	2.90	1315.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4449.JPG
60 M49 ATC169	4369664.956	402817.537	102.7	53.3	0.52	Cast PMI/Forged Steel	240	60	60	0.250	2.90	1315.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4447.JPG
60 M49 NS 167	4369641.554	402844.636	311.6	-18.0	0.26	Cast PMI/Forged Steel	130	60	60	0.462	2.20	965.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4448.JPG
60 NS JPG071	4369718.877	402793.652	148.0	-70.4	0.24	Cast PMI/Forged Steel	240	60	60	0.250	2.90	1315.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4687.JPG
60 NS JPG107	4369685.862	402879.116	180.9	-6.1	0.26	Cast PMI/Forged Steel	240	60	60	0.250	2.90	1315.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4657.JPG
60 NS JPG123	4369674.489	402853.075	301.5	-44.5	0.92	Cast PMI/Forged Steel	240	60	60	0.250	2.90	1315.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4664.JPG
60 NS JPG124	4369697.086	402854.291	99.0	11.3	0.16	Cast PMI/Forged Steel	240	60	60	0.250	2.90	1315.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4667.JPG

ATC ID #	Northing	Easting	Azimuth	Inclination	Depth	Material of Item	Length	Width	Thickness	Aspect Ratio	Weight, lbs	Weight, g	Image
81 M374 ATC085	4369647.490	402844.990	160.5	3.7	0.48	Cast PMI/Forged Steel	488	81	81	0.166	6.95	3153	Direct Fire Recovery Pics Reconfiguration 07\DSCN4452.JPG
81 M374 ATC086	4369657.195	402812.489	49.2	17.7	0.69	Cast PMI/Forged Steel	488	81	81	0.166	6.95	3153	Direct Fire Recovery Pics Reconfiguration 07\DSCN4450.JPG
81 M374 ATC095	4369709.853	402824.920	270.9	75.3	1.18	Cast PMI/Forged Steel	488	81	81	0.166	6.95	3153	Direct Fire Recovery Pics Reconfiguration 07\DSCN4651.JPG
81 M374 NS ATC102	4369736.885	402821.773	36.5	-87.7	0.22	Cast PMI/Forged Steel	270	81	81	0.3	5.14	2671	Direct Fire Recovery Pics Reconfiguration 07\DSCN4451.JPG
81 M374 NS ATC105	4369692.219	402768.328	51.8	44.1	0.16	Cast PMI/Forged Steel	270	81	81	0.3	5.14	2671	Direct Fire Recovery Pics Reconfiguration 07\DSCN4454.JPG
81 NS JPG013	4369662.440	402799.725	270.9	75.3	1.18	Cast PMI/Forged Steel	275	81	81	0.295	3.15	1429.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4665.JPG
81 NS JPG016	4369679.949	402843.366	342.0	-51.0	1.67	Cast PMI/Forged Steel	275	81	81	0.295	3.15	1429.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4666.JPG
BDU28 ATC005	4369680.082	402816.730	231.9	43.7	0.09	Ferrous Metallic	97	67	67	0.691	1.7	771	Direct Fire Recovery Pics Reconfiguration 07\DSCN4614.JPG
BDU28 ATC029	4369687.458	402850.134	227.6	32.0	0.09	Ferrous Metallic	97	67	67	0.691	1.7	771	Direct Fire Recovery Pics Reconfiguration 07\DSCN4668.JPG
BLU26 ATC005	4369689.390	402866.334			0.06	Ferrous Metallic	66	66	66	1	0.95	431	Direct Fire Recovery Pics Reconfiguration 07\DSCN4671.JPG
BLU26 ATC006	4369680.932	402863.882			0.09	Ferrous Metallic	66	66	66	1	0.95	431	Direct Fire Recovery Pics Reconfiguration 07\DSCN4659.JPG
BLU26 ATC007	4369710.954	402838.676			0.10	Ferrous Metallic	66	66	66	1	0.95	431	Direct Fire Recovery Pics Reconfiguration 07\DSCN4699.JPG
BLU26 ATC008	4369701.558	402843.211			0.12	Ferrous Metallic	66	66	66	1	0.95	431	Direct Fire Recovery Pics Reconfiguration 07\DSCN4700.JPG
BLU26 ATC009	4369693.028	402817.055			0.13	Ferrous Metallic	66	66	66	1	0.95	431	Direct Fire Recovery Pics Reconfiguration 07\DSCN4702.JPG
BTG047	4369708.497	402834.625			0.09	Ferrous Metallic	250	140	10	0.560	4.29	1945.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4544.JPG
BTG048	4369711.805	402796.002			0.10	Ferrous Metallic	210	98	28	0.467	3.79	1719.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4471.JPG
BTG056	4369674.206	402838.542			0.39	Ferrous Metallic	314	320	5	1.019	2.75	1247.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4584.JPG
BTG058	4369698.379	402782.260			0.03	Ferrous Metallic	175	103	7	0.589	3.58	1623.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4478.JPG
BTG060	4369694.492	402834.128			0.52	Ferrous Metallic	205	147	26	0.717	7.76	3519.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4692.JPG
BTG061	4369722.733	402818.116			0.13	Ferrous Metallic	315	178	3	0.565	2.78	1261.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4490.JPG
BTG088	4369686.429	402808.241			0.71	Ferrous Metallic	950	245	10	0.258	19.40	8799.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4609.JPG
CL0070	4369731.353	402801.524			0.44	Ferrous Metallic	37	30	10	0.811	0.077	35.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4686.JPG
CL0071	4369722.469	402825.712			0.11	Ferrous Metallic	30	21	5	0.700	0.147	66.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4520.JPG
CL0074	4369708.360	402777.569			0.47	Ferrous Metallic	37	36	10	0.973	0.071	32.3	Direct Fire Recovery Pics Reconfiguration 07\DSCN4736.JPG
CL0079	4369694.806	402767.517			0.32	Ferrous Metallic	59	30	8	0.508	0.088	39.7	NOT RECOVERED
CL0086	4369705.833	402835.226			0.33	Ferrous Metallic	56	28	14	0.500	0.110	49.8	NOT RECOVERED
CL0087	4369676.725	402870.808			0.30	Ferrous Metallic	94	68	12	0.723	0.267	121.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4474.JPG
CL0089	4369729.580	402817.388			0.17	Ferrous Metallic	37	25	8	0.676	0.048	21.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4483.JPG
CL0090	4369705.444	402836.379			0.31	Ferrous Metallic	91	62	11	0.681	0.287	130.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4469.JPG
CL0091	4369679.801	402856.405			0.54	Ferrous Metallic	61	47	27	0.770	0.313	141.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4710.JPG
CL0093	4369679.600	402855.363			0.64	Ferrous Metallic	27	21	3	0.778	0.022	10.0	NOT RECOVERED
CL0095	4369703.809	402852.820			0.13	Ferrous Metallic	27	21	3	0.778	0.022	10.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4491.JPG
CL0096	4369717.313	402788.255			0.52	Ferrous Metallic	27	21	3	0.778	0.022	10.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4643.JPG
CL0106	4369677.840	402881.736			0.13	Ferrous Metallic	85	51	1	0.600	0.015	6.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4475.JPG
CL0116	4369727.842	402817.853			0.06	Ferrous Metallic	210	20	10	0.095	0.211	95.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4530.JPG
CL0130	4369677.490	402870.880			0.58	Ferrous Metallic	215	4	4	0.019	0.020	9.1	NOT RECOVERED
CL0131	4369671.197	402879.202			0.15	Ferrous Metallic	300	2	2	0.007	0.005	2.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4507.JPG
CL0136	4369667.670	402868.805			0.26	Ferrous Metallic	163	2	2	0.012	0.019	8.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4500.JPG
CL0137	4369714.388	402813.512			0.23	Ferrous Metallic	95	3	3	0.032	0.021	9.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4463.JPG
CL0139	4369734.035	402805.081			0.50	Ferrous Metallic	203	6	6	0.030	0.204	92.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4680.JPG
CL0140	4369704.766	402835.676			0.38	Ferrous Metallic	202	5	5	0.025	0.130	58.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4695.JPG
CL0142	4369714.995	402814.768			0.16	Ferrous Metallic	205	5	5	0.024	0.153	69.3	Direct Fire Recovery Pics Reconfiguration 07\DSCN4459.JPG
CL0143	4369736.149	402803.365			0.12	Ferrous Metallic	193	5	5	0.026	0.142	64.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4504.JPG
CL0144	4369691.071	402840.140			0.04	Ferrous Metallic	55	28	6	0.509	0.076	34.5	NOT RECOVERED
CL0146	4369710.663	402783.450			0.29	Ferrous Metallic	95	20	9	0.211	0.063	28.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4522.JPG

ATC ID #	Northing	Easting	Azimuth	Inclination	Depth	Material of Item	Length	Width	Thickness	Aspect Ratio	Weight, lbs	Weight, g	Image
CL0147	4369691.181	402838.951			0.48	Ferrous Metallic	50	30	20	0.600	0.149	67.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4704.JPG
CL0150	4369714.843	402782.331			0.16	Ferrous Metallic	70	50	15	0.714	0.235	106.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4529.JPG
CL0151	4369694.130	402768.430			0.20	Ferrous Metallic	90	25	20	0.278	0.208	94.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4525.JPG
CL0153	4369721.679	402791.757			0.49	Ferrous Metallic	60	38	16	0.633	0.268	121.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4645.JPG
CL0154	4369692.594	402836.523			0.48	Ferrous Metallic	33	30	8	0.909	0.050	22.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4703.JPG
CL0155	4369710.180	402780.311			0.13	Ferrous Metallic	65	35	19	0.538	0.200	90.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4479.JPG
CL0157	4369715.742	402812.630			0.55	Ferrous Metallic	80	37	13	0.463	0.162	73.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4683.JPG
CL0158	4369672.088	402879.717			0.44	Ferrous Metallic	55	63	3	1.145	0.067	30.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4661.JPG
CL0159	4369724.742	402818.354			0.08	Ferrous Metallic	61	50	11	0.820	0.226	102.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4521.JPG
CL0161	4369724.500	402822.589			0.19	Ferrous Metallic	54	34	16	0.630	0.189	85.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4532.JPG
CL0162	4369715.059	402789.527			0.12	Ferrous Metallic	70	20	9	0.286	0.149	67.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4509.JPG
CL0163	4369745.675	402808.528			0.10	Ferrous Metallic	95	17	8	0.179	0.080	36.3	Direct Fire Recovery Pics Reconfiguration 07\DSCN4528.JPG
CL0165	4369697.352	402768.204			0.21	Ferrous Metallic	54	18	18	0.333	0.080	36.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4639.JPG
CL0166	4369696.822	402771.914			0.21	Ferrous Metallic	80	10	9	0.125	0.045	20.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4641.JPG
CL0167	4369707.279	402777.641			0.12	Ferrous Metallic	205	2	2	0.010	0.022	9.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4633.JPG
CL0168	4369719.044	402840.909			0.32	Ferrous Metallic	200	10	10	0.050	0.194	87.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4498.JPG
CL0169	4369704.176	402774.768			0.63	Ferrous Metallic	195	7	7	0.036	0.146	66.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4628.JPG
CL0170	4369725.538	402820.717			0.45	Ferrous Metallic	209	7	7	0.033	0.197	89.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4691.JPG
CL0171	4369719.185	402791.935			0.17	Ferrous Metallic	153	4	4	0.026	0.069	31.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4496.JPG
CL0172	4369725.357	402817.583			0.19	Ferrous Metallic	198	7	7	0.035	0.179	81.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4513.JPG
CL0173	4369714.096	402783.295			0.11	Ferrous Metallic	203	8	8	0.039	0.207	94.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4461.JPG
CL0174	4369724.625	402788.159			0.09	Ferrous Metallic	200	7	7	0.035	0.184	83.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4457.JPG
CL0175	4369732.479	402803.023			0.50	Ferrous Metallic	205	10	10	0.049	0.211	95.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4674.JPG
CL0176	4369715.868	402813.925			0.36	Ferrous Metallic	197	9	9	0.046	0.233	105.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4678.JPG
CL0177	4369731.692	402798.740			0.49	Ferrous Metallic	180	9	9	0.050	0.186	84.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4679.JPG
CL0178	4369709.320	402791.358			0.33	Ferrous Metallic	205	8	8	0.039	0.169	76.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4644.JPG
CL0179	4369713.838	402798.148			0.21	Ferrous Metallic	206	8	8	0.039	0.186	84.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4473.JPG
CL0180	4369693.273	402765.801			0.26	Ferrous Metallic	90	50	14	0.556	0.249	112.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4626.JPG
CL0182	4369728.048	402819.620			0.17	Ferrous Metallic	93	30	22	0.323	0.320	145.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4501.JPG
CL0183	4369702.881	402852.017			0.22	Ferrous Metallic	78	36	11	0.462	0.301	136.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4511.JPG
CL0184	4369734.192	402806.390			0.06	Ferrous Metallic	90	32	18	0.356	0.115	52.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4531.JPG
CL0185	4369730.427	402802.726			0.01	Ferrous Metallic	118	25	18	0.212	0.229	104.1	NOT RECOVERED
CL0186	4369741.101	402810.757			0.36	Ferrous Metallic	90	33	15	0.367	0.269	122.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4675.JPG
CL0187	4369705.343	402782.073			0.14	Ferrous Metallic	64	55	5	0.859	0.225	102.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4637.JPG
CL0188	4369723.140	402820.363			0.40	Ferrous Metallic	86	53	3	0.616	0.219	99.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4690.JPG
CL0189	4369741.413	402812.450			0.15	Ferrous Metallic	80	35	6	0.438	0.293	133.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4470.JPG
CL0191	4369720.556	402790.049			0.27	Ferrous Metallic	60	50	30	0.833	0.275	124.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4485.JPG
CL0192	4369707.922	402780.767			0.24	Ferrous Metallic	68	40	17	0.588	0.229	103.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4523.JPG
CL0193	4369733.720	402800.078			0.09	Ferrous Metallic	78	35	7	0.449	0.146	66.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4676.JPG
CL0194	4369722.490	402787.718			0.11	Ferrous Metallic	60	34	9	0.567	0.147	66.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4510.JPG
CL0195	4369734.057	402804.003			0.04	Ferrous Metallic	55	26	5	0.473	0.074	33.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4508.JPG
CL0196	4369741.401	402813.174			0.57	Ferrous Metallic	70	38	6	0.543	0.182	82.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4677.JPG
CL0198	4369713.963	402834.454			0.62	Ferrous Metallic	48	27	13	0.563	0.077	35.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4694.JPG
CL0203	4369694.436	402779.610			0.27	Ferrous Metallic	50	15	9	0.300	0.033	14.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4635.JPG
CL0205	4369692.066	402769.376			0.25	Ferrous Metallic	160	65	9	0.406	0.015	7.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4638.JPG

ATC ID #	Northing	Easting	Azimuth	Inclination	Depth	Material of Item	Length	Width	Thickness	Aspect Ratio	Weight, lbs	Weight, g	Image
CL0206	4369669.069	402868.484			0.13	Ferrous Metallic	160	65	9	0.406	0.015	7.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4499.JPG
CL0207	4369748.091	402810.893			0.35	Ferrous Metallic	84	51	1	0.607	0.015	6.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4688.JPG
CL0208	4369704.199	402782.770			0.46	Ferrous Metallic	199	21	10	0.106	0.181	82.3	Direct Fire Recovery Pics Reconfiguration 07\DSCN4642.JPG
CL0210	4369705.707	402776.688			0.32	Ferrous Metallic	211	22	8	0.104	0.191	86.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4629.JPG
CL0211	4369713.259	402815.630			0.11	Ferrous Metallic	205	22	8	0.107	0.172	78.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4526.JPG
CL0212	4369715.386	402833.755			0.51	Ferrous Metallic	197	11	9	0.056	0.174	79.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4705.JPG
CL0213	4369710.278	402778.698			0.61	Ferrous Metallic	228	4	3	0.018	0.017	7.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4646.JPG
CL0214	4369696.516	402769.117			0.24	Ferrous Metallic	363	6	3	0.017	0.038	17.3	Direct Fire Recovery Pics Reconfiguration 07\DSCN4636.JPG
CL0215	4369738.875	402810.642			0.18	Ferrous Metallic	191	6	2	0.031	0.022	9.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4468.JPG
CL0216	4369714.085	402832.972			0.48	Ferrous Metallic	57	51	6	0.895	0.064	29.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4696.JPG
CL0217	4369701.849	402853.496			0.54	Ferrous Metallic	90	71	14	0.789	0.285	129.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4656.JPG
CL0220	4369711.374	402779.275			0.36	Ferrous Metallic	61	40	24	0.656	0.114	51.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4647.JPG
CL0221	4369717.521	402799.190			0.04	Ferrous Metallic	65	41	18	0.631	0.137	62.1	NOT RECOVERED
CL0223	4369681.058	402853.996			0.52	Ferrous Metallic	63	43	21	0.683	0.263	119.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4713.JPG
CL0224	4369667.535	402869.625			0.07	Ferrous Metallic	59	38	12	0.644	0.169	76.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4735.JPG
CL0226	4369712.271	402793.846			0.18	Ferrous Metallic	85	59	8	0.694	0.259	117.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4502.JPG
CL0227	4369720.836	402784.764			0.29	Ferrous Metallic	82	19	7	0.232	0.049	22.3	Direct Fire Recovery Pics Reconfiguration 07\DSCN4519.JPG
CL0229	4369710.689	402846.447			0.52	Ferrous Metallic	210	17	10	0.081	0.214	97.2	NOT RECOVERED
CL0232	4369696.401	402779.751			0.27	Ferrous Metallic	48	30	28	0.625	0.084	38.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4634.JPG
CL0233	4369712.135	402784.862			0.19	Ferrous Metallic	59	30	13	0.508	0.162	73.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4466.JPG
CL0234	4369723.978	402824.022			0.06	Ferrous Metallic	51	32	8	0.627	0.090	40.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4458.JPG
CL0235	4369676.713	402880.127			0.13	Ferrous Metallic	62	39	23	0.629	0.142	64.3	Direct Fire Recovery Pics Reconfiguration 07\DSCN4516.JPG
CL0237	4369709.331	402787.548			0.02	Ferrous Metallic	113	31	13	0.274	0.103	46.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4640.JPG
CL0247	4369678.799	402882.346			0.13	Ferrous Metallic	46.8	46.8	46.8	1.000	0.186	84.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4484.JPG
CL0251	4369677.954	402882.232			0.12	Ferrous Metallic	170	21	9	0.124	0.197	89.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4481.JPG
CL0252	4369676.483	402881.968			0.10	Ferrous Metallic	203	19	11	0.094	0.227	102.9	NOT RECOVERED
CL0254	4369707.659	402779.062			0.61	Ferrous Metallic	100	10	4	0.100	0.022	9.9	NOT RECOVERED
CL0259	4369690.075	402839.600			0.02	Ferrous Metallic	48	30	19	0.625	0.112	50.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4527.JPG
CL0274	4369677.105	402882.334			0.14	Ferrous Metallic	85	21	8	0.247	0.047	21.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4493.JPG
CL0284	4369678.079	402870.081			0.33	Ferrous Metallic	61	8	3	0.131	0.008	3.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4660.JPG
CL0285	4369739.768	402812.525			0.49	Ferrous Metallic	183	5	5	0.027	0.049	22.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4684.JPG
CL0287	4369719.760	402788.135			0.43	Ferrous Metallic	216	20	6	0.093	0.177	80.3	Direct Fire Recovery Pics Reconfiguration 07\DSCN4649.JPG
CL0289	4369667.923	402798.881			0.22	Ferrous Metallic	64	22	15	0.344	0.070	31.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4503.JPG
CL0290	4369705.845	402773.217			0.31	Ferrous Metallic	57	2	2	0.035	0.004	1.7	NOT RECOVERED
CL0297	4369718.664	402784.094			0.15	Ferrous Metallic	93	51	11	0.548	0.229	103.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4460.JPG
CL0299	4369670.243	402800.007			0.25	Ferrous Metallic	43	40	25	0.930	0.207	93.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4506.JPG
CL0300	4369647.317	402812.404			0.07	Ferrous Metallic	129	38	7	0.295	0.199	90.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4489.JPG
CL0302	4369670.992	402799.036			0.05	Ferrous Metallic	188	34	16	0.181	0.322	146.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4462.JPG
CL0612	4369670.293	402801.845			0.19	Ferrous Metallic	135	56	16	0.415	0.82	372.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4488.JPG
CL0619	4369714.640	402833.768			0.09	Ferrous Metallic	125	45	16	0.360	0.62	281.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4512.JPG
CL0639	4369669.104	402801.894			0.33	Ferrous Metallic	132	61	11	0.462	0.71	322.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4604.JPG
CL0641	4369700.389	402863.586			0.30	Ferrous Metallic	130	81	12	0.623	1.10	499.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4533.JPG
CL0643	4369681.617	402856.350			0.49	Ferrous Metallic	210	80	17	0.381	1.51	684.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4711.JPG
CL0645	4369666.252	402867.899			0.52	Ferrous Metallic	155	79	18	0.510	1.25	567.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4663.JPG
CL0647	4369745.194	402809.976			0.12	Ferrous Metallic	88	87	29	0.989	1.24	562.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4467.JPG

ATC ID #	Northing	Easting	Azimuth	Inclination	Depth	Material of Item	Length	Width	Thickness	Aspect Ratio	Weight, lbs	Weight, g	Image
CL0649	4369672.416	402880.658			0.26	Ferrous Metallic	138	70	20	0.507	0.88	399.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4518.JPG
CL0651	4369669.046	402798.480			0.29	Ferrous Metallic	179	85	11	0.475	1.16	526.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4599.JPG
CL0654	4369712.323	402787.964			0.08	Ferrous Metallic	135	83	10	0.615	0.76	344.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4515.JPG
CL0655	4369668.379	402866.561			0.25	Ferrous Metallic	183	120	5	0.656	0.77	349.3	Direct Fire Recovery Pics Reconfiguration 07\DSCN4514.JPG
CL0657	4369704.566	402837.212			0.09	Ferrous Metallic	149	51	12	0.342	0.96	435.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4464.JPG
CL0658	4369746.543	402808.582			0.16	Ferrous Metallic	119	74	7	0.622	0.66	299.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4456.JPG
CL0661	4369678.683	402869.424			0.25	Ferrous Metallic	205	90	8	0.439	1.42	644.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4495.JPG
CL0664	4369671.299	402798.147			0.34	Ferrous Metallic	69	55	29	0.797	0.56	254.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4608.JPG
CL0673	4369668.242	402800.312			0.45	Ferrous Metallic	193	75	11	0.389	1.53	694.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4607.JPG
CL0674	4369647.420	402812.174			0.15	Ferrous Metallic	146	83	8	0.568	0.84	381.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4505.JPG
CL0680	4369685.138	402863.953			0.28	Ferrous Metallic	178	75	11	0.421	0.99	449.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4477.JPG
CL0686	4369669.785	402801.181			0.27	Ferrous Metallic	157	83	11	0.529	1.47	666.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4600.JPG
CL0703	4369667.775	402801.381			0.06	Ferrous Metallic	75	62	45	0.827	0.71	322.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4487.JPG
CL0704	4369703.114	402850.964			0.47	Ferrous Metallic	59	54	51	0.915	0.87	394.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4697.JPG
CL0705	4369678.730	402879.911			0.21	Ferrous Metallic	85	53	30	0.624	0.78	353.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4476.JPG
CL0706	4369672.654	402799.071			0.03	Ferrous Metallic	102	61	17	0.598	0.85	385.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4517.JPG
CL0707	4369677.229	402880.433			0.14	Ferrous Metallic	215	55	24	0.256	1.42	644.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4524.JPG
CL0715	4369676.958	402881.049			0.14	Ferrous Metallic	151	103	13	0.682	1.02	462.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4482.JPG
CL0781	4369678.272	402818.687			0.13	Ferrous Metallic	219	103	30	0.470	0.80	362.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4558.JPG
CL0783	4369677.637	402881.218			0.03	Ferrous Metallic	182	168	7	0.923	1.00	453.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4494.JPG
CL0790	4369681.023	402817.444			0.23	Ferrous Metallic	152	155	14	1.020	2.19	993.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4573.JPG
CL0796	4369683.986	402819.698			0.03	Ferrous Metallic	172	89	13	0.517	1.66	753.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4572.JPG
CL0800	4369679.266	402815.470			0.06	Ferrous Metallic	297	63	14	0.212	2.18	988.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4560.JPG
CL0802	4369680.629	402818.569			0.02	Ferrous Metallic	144	110	44	0.764	1.65	748.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4567.JPG
CL0809	4369680.419	402815.183			0.14	Ferrous Metallic	150	125	10	0.833	2.12	961.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4564.JPG
CL0825	4369683.247	402817.880			0.14	Ferrous Metallic	219	219	40	1.000	1.85	839.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4569.JPG
CL0870	4369683.683	402806.521			0.40	Ferrous Metallic	315	175	2	0.556	1.97	893.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4605.JPG
CL0883	4369716.219	402842.287			0.31	Ferrous Metallic	226	268	8	1.186	2.23	1011.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4455.JPG
CL0891	4369678.774	402881.643			0.15	Ferrous Metallic	317	130	5	0.410	1.86	843.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4486.JPG
CL0894	4369669.979	402799.797			0.27	Ferrous Metallic	174	144	7	0.828	1.67	757.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4601.JPG
CL0896	4369670.112	402798.024			0.13	Ferrous Metallic	180	172	20	0.956	1.90	861.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4480.JPG
CL0905	4369717.606	402826.943			0.30	Ferrous Metallic	215	137	20	0.637	1.88	852.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4465.JPG
CL1120	4369676.527	402820.262			0.67	Ferrous Metallic	485	305	45	0.629	8.39	3805.7	NOT RECOVERED
CL1139	4369649.482	402842.733			0.25	Ferrous Metallic	280	225	5	0.804	4.01	1818.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4591.JPG
CL1150	4369716.235	402794.725			0.79	Ferrous Metallic	360	330	10	0.917	8.38	3801.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4648.JPG
CL1155	4369644.024	402819.503			0.91	Ferrous Metallic	285	215	4	0.754	2.34	1061.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4545.JPG
CL1156	4369679.969	402815.020			0.01	Ferrous Metallic	335	195	5	0.582	5.14	2331.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4565.JPG
CL1162	4369647.086	402847.903			0.66	Ferrous Metallic	310	300	8	0.968	5.09	2308.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4580.JPG
CL1163	4369678.743	402817.031			0.19	Ferrous Metallic	285	205	8	0.719	2.99	1356.3	Direct Fire Recovery Pics Reconfiguration 07\DSCN4559.JPG
CL1174	4369677.370	402818.726			0.09	Ferrous Metallic	305	210	27	0.689	4.96	2249.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4561.JPG
CL1185	4369645.387	402844.877			0.77	Ferrous Metallic	226	148	7	0.655	2.53	1147.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4554.JPG
CL1191	4369676.011	402825.422			0.27	Ferrous Metallic	322	290	12	0.901	5.42	2458.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4582.JPG
CL1198	4369679.006	402819.492			0.06	Ferrous Metallic	320	292	7	0.913	5.38	2440.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4571.JPG
CL1206	4369676.674	402815.501			0.24	Ferrous Metallic	320	305	22	0.953	5.98	2712.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4563.JPG
CL1208	4369681.955	402820.010			0.55	Ferrous Metallic	382	277	9	0.725	2.93	1329.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4596.JPG

ATC ID #	Northing	Easting	Azimuth	Inclination	Depth	Material of Item	Length	Width	Thickness	Aspect Ratio	Weight, lbs	Weight, g	Image
CL1213	4369654.282	402854.254			0.27	Ferrous Metallic	365	290	10	0.795	5.91	2680.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4581.JPG
CL1219	4369679.690	402851.440			0.48	Ferrous Metallic	300	145	10	0.483	2.91	1320.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4708.JPG
CL1228	4369658.603	402864.927			0.09	Ferrous Metallic	500	185	115	0.370	8.22	3728.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4542.JPG
CL1272	4369690.151	402860.223			0.63	Ferrous Metallic	368	360	23	0.978	8.03	3642.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4714.JPG
CL1284	4369676.268	402863.477			0.39	Ferrous Metallic	310	405	32	1.306	5.48	2485.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4712.JPG
CL1310	4369680.845	402797.997			0.46	Ferrous Metallic	365	205	60	0.562	5.47	2481.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4602.JPG
CL1313	4369661.857	402843.550			0.07	Ferrous Metallic	380	312	60	0.821	8.50	3855.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4593.JPG
CL1370	4369672.145	402801.561			0.22	Ferrous Metallic	580	325	100	0.560	18.73	8495.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4537.JPG
CL1381	4369677.587	402882.111			0.06	Ferrous Metallic	554	452	25	0.816	10.62	4817.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4540.JPG
CL1382	4369696.576	402780.638			0.28	Ferrous Metallic	422	445	200	1.055	16.24	7366.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4618.JPG
CL1387	4369687.883	402790.937			0.33	Ferrous Metallic	354	45	40	0.127	15.71	7126.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4616.JPG
CL1394	4369654.152	402846.208			0.49	Ferrous Metallic	272	70	60	0.257	9.32	4227.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4590.JPG
CL1398	4369670.036	402800.099			0.05	Ferrous Metallic	562	275	115	0.489	17.70	8028.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4536.JPG
CL1399	4369683.223	402814.601			0.04	Ferrous Metallic	316	270	50	0.854	15.25	6917.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4568.JPG
CL1400	4369672.509	402799.852			0.50	Ferrous Metallic	285	290	42	1.018	15.83	7180.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4603.JPG
CL1401	4369723.298	402813.155			0.25	Ferrous Metallic	204	158	27	0.775	10.26	4653.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4492.JPG
CL1407	4369677.169	402880.813			0.51	Ferrous Metallic	395	97	25	0.246	11.10	5035.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4655.JPG
CL1413	4369716.582	402785.491			0.79	Ferrous Metallic	400	102	72	0.255	12.83	5819.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4650.JPG
CL1423	4369676.923	402880.243			0.72	Ferrous Metallic	253	145	55	0.573	9.90	4490.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4654.JPG
CL1428	4369676.740	402881.695			0.65	Ferrous Metallic	205	140	60	0.683	11.48	5207.3	Direct Fire Recovery Pics Reconfiguration 07\DSCN4672.JPG
CL1430	4369671.568	402880.323			0.10	Ferrous Metallic	219	150	26	0.685	8.98	4073.3	Direct Fire Recovery Pics Reconfiguration 07\DSCN4472.JPG
CL1432	4369664.820	402855.814			0.85	Ferrous Metallic	315	287	6	0.911	9.28	4209.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4592.JPG
CL1434	4369689.965	402812.159			0.86	Ferrous Metallic	253	145	50	0.573	10.58	4799.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4606.JPG
CL1435	4369691.741	402837.538			0.84	Ferrous Metallic	405	200	10	0.494	9.95	4513.3	Direct Fire Recovery Pics Reconfiguration 07\DSCN4709.JPG
CL1441	4369659.912	402817.815			0.85	Ferrous Metallic	605	215	20	0.355	10.25	4649.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4562.JPG
CL1445	4369638.727	402823.429			0.29	Ferrous Metallic	198	267	15	1.348	11.54	5234.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4552.JPG
CL1454	4369720.418	402834.745			0.03	Ferrous Metallic	450	450	45	1.000	16.21	7352.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4538.JPG
CL1458	4369666.723	402793.822			0.15	Ferrous Metallic	653	220	10	0.337	15.03	6817.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4595.JPG
CL1462	4369715.588	402845.487			0.47	Ferrous Metallic	480	400	8	0.833	16.25	7371.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4693.JPG
CL1463	4369639.313	402847.861			0.79	Ferrous Metallic	550	332	8	0.604	17.97	8151.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4543.JPG
CL1466	4369685.141	402774.510			0.44	Ferrous Metallic	330	240	18	0.727	9.30	4218.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4620.JPG
CL1496	4369677.111	402814.825			0.60	Ferrous Metallic	220	245	47	1.114	18.65	8459.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4594.JPG
CL1511	4369703.565	402805.744			0.36	Ferrous Metallic	330	330	40	1.000	17.85	8096.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4630.JPG
CL1512	4369664.614	402829.687			0.12	Ferrous Metallic	520	270	11	0.519	14.29	6481.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4570.JPG
CL1523	4369657.885	402804.549			0.68	Ferrous Metallic	635	260	20	0.409	10.33	4685.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4723.JPG
CL1524	4369717.802	402829.958			0.16	Ferrous Metallic	425	275	10	0.647	9.93	4504.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4719.JPG
CL1533	4369747.697	402809.550			0.16	Ferrous Metallic	330	140	90	0.424	10.81	4903.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4733.JPG
CL1550	4369676.715	402805.556			0.47	Ferrous Metallic	385	305	10	0.792	15.12	6858.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4722.JPG
CL1559	4369734.623	402802.797			0.04	Ferrous Metallic	260	320	15	1.231	14.41	6536.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4732.JPG
CL1561	4369680.943	402855.201			0.09	Ferrous Metallic	660	165	65	0.250	14.14	6413.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4729.JPG
CL1565	4369679.317	402882.144			0.55	Ferrous Metallic	280	270	50	0.964	17.76	8055.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4734.JPG
CL1566	4369667.033	402866.623			0.18	Ferrous Metallic	315	280	45	0.889	18.64	8455.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4716.JPG
CL1569	4369678.244	402881.262			0.06	Ferrous Metallic	353	285	15	0.807	14.26	6468.3	Direct Fire Recovery Pics Reconfiguration 07\DSCN4717.JPG
CL1573	4369647.804	402832.246			0.22	Ferrous Metallic	215	360	13	1.674	11.04	5007.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4720.JPG
CL1575	4369677.507	402869.338			0.50	Ferrous Metallic	510	220	5	0.431	14.25	6463.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4730.JPG

ATC ID #	Northing	Easting	Azimuth	Inclination	Depth	Material of Item	Length	Width	Thickness	Aspect Ratio	Weight, lbs	Weight, g	Image
CL1582	4369651.196	402814.927			0.46	Ferrous Metallic	600	375	10	0.625	17.89	8114.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4724.JPG
CL1586	4369712.703	402822.143			0.02	Ferrous Metallic	425	280	95	0.659	21.91	9938.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4731.JPG
CL1590	4369677.044	402839.705			0.77	Ferrous Metallic	490	180	20	0.367	17.42	7901.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4727.JPG
CL1605	4369644.278	402826.487			0.30	Ferrous Metallic	327	115	10	0.352	4.01	1818.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4725.JPG
CL1610	4369676.433	402817.592			0.74	Ferrous Metallic	305	210	10	0.689	7.84	3556.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4728.JPG
CL1624	4369648.449	402854.830			0.79	Ferrous Metallic	200	255	8	1.275	7.78	3529.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4726.JPG
CL1627	4369637.337	402830.874			0.94	Ferrous Metallic	185	115	8	0.622	1.80	816.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4546.JPG
CL1628	4369644.171	402837.716			0.32	Ferrous Metallic	462	110	50	0.238	3.65	1655.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4550.JPG
CL1629	4369645.492	402840.782			0.43	Ferrous Metallic	285	300	12	1.053	4.44	2014.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4553.JPG
CL1634	4369648.247	402838.568			0.84	Ferrous Metallic	380	95	10	0.250	2.64	1197.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4549.JPG
CL1640	4369641.138	402832.491			0.83	Ferrous Metallic	215	143	7	0.665	2.61	1183.9	Direct Fire Recovery Pics Reconfiguration 07\DSCN4555.JPG
CL1649	4369642.428	402822.051			0.93	Ferrous Metallic	235	135	30	0.574	7.64	3465.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4548.JPG
CL1660	4369644.814	402835.593			0.60	Ferrous Metallic	375	160	7	0.427	3.88	1760.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4557.JPG
CL1698	4369644.925	402855.322			0.36	Ferrous Metallic	447	120	15	0.268	4.84	2195.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4579.JPG
CL1705	4369646.210	402830.241			0.78	Ferrous Metallic	168	205	10	1.220	3.05	1383.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4551.JPG
CL1729	4369682.992	402815.965			0.05	Ferrous Metallic	388	193	20	0.497	5.61	2544.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4556.JPG
CL1754	4369668.918	402807.223			0.14	Ferrous Metallic	585	270	30	0.462	22.72	10305.8	Direct Fire Recovery Pics Reconfiguration 07\DSCN4534.JPG
CL1759	4369686.463	402825.580			0.81	Ferrous Metallic	1190	237	40	0.199	40.74	18479.7	Direct Fire Recovery Pics Reconfiguration 07\DSCN4597.JPG
CL1761	4369677.005	402872.416			0.22	Ferrous Metallic	455	335	45	0.736	37.79	17141.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4662.JPG
CL1762	4369707.681	402789.388			0.07	Ferrous Metallic	475	300	70	0.632	22.24	10088.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4539.JPG
CL1770	4369680.817	402782.733			0.09	Ferrous Metallic	275	350	30	1.273	22.15	10047.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4721.JPG
CL1775	4369735.792	402798.868			0.94	Ferrous Metallic	255	162	75	0.635	24.67	11190.3	Direct Fire Recovery Pics Reconfiguration 07\DSCN4682.JPG
CL1781	4369702.567	402770.644			0.69	Ferrous Metallic	310	148	38	0.477	25.70	11657.5	Direct Fire Recovery Pics Reconfiguration 07\DSCN4631.JPG
CL1783	4369686.739	402799.525			0.28	Ferrous Metallic	292	149	43	0.510	25.04	11358.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4611.JPG
CL1790	4369658.633	402814.472			0.08	Ferrous Metallic	540	265	37	0.491	47.50	21546.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4566.JPG
CL1803	4369739.001	402818.801			0.14	Ferrous Metallic	265	303	40	1.143	22.09	10020.0	Direct Fire Recovery Pics Reconfiguration 07\DSCN4535.JPG
CL1804	4369674.497	402842.322			0.58	Ferrous Metallic	750	365	10	0.487	24.50	11113.2	Direct Fire Recovery Pics Reconfiguration 07\DSCN4589.JPG
CL1813	4369650.264	402857.605			0.71	Ferrous Metallic	530	295	12	0.557	26.43	11988.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4541.JPG
CL1817	4369708.067	402827.273			0.67	Ferrous Metallic	700	360	20	0.514	40.30	18280.1	Direct Fire Recovery Pics Reconfiguration 07\DSCN4698.JPG
CL1864	4369695.872	402778.389			0.76	Ferrous Metallic	590	510	17	0.864	39.00	17690.4	Direct Fire Recovery Pics Reconfiguration 07\DSCN4627.JPG
CL1882	4369702.647	402860.615			0.94	Ferrous Metallic	307	305	20	0.993	31.00	14061.6	Direct Fire Recovery Pics Reconfiguration 07\DSCN4706.JPG
CL2004	4369646.685	402823.977			0.16	Ferrous Metallic							Direct Fire Recovery Pics Reconfiguration 07\DSCN4547.JPG
CL2005	4369655.189	402831.791			0.21	Ferrous Metallic							Direct Fire Recovery Pics Reconfiguration 07\DSCN4574.JPG
CL2007	4369661.332	402838.139			0.30	Ferrous Metallic							Direct Fire Recovery Pics Reconfiguration 07\DSCN4587.JPG
FUSE08	4369699.416	402852.214			0.07								Direct Fire Recovery Pics Reconfiguration 07\DSCN4497.JPG
FUSE09	4369690.547	402835.521			0.07								NOT RECOVERED
FUSE17	4369678.397	402814.363			0.07								NOT RECOVERED
MK118 ATC085	4369677.795	402817.580	219.3	34.3	0.40	Cast Aluminum w Ferrous Ring	344	50	50	0.145	1.35	612	Direct Fire Recovery Pics Reconfiguration 07\DSCN4617.JPG
MK118 ATC093	4369677.832	402815.654	218.0	77.8	0.58	Cast Aluminum w Ferrous Ring	344	50	50	0.145	1.35	612	Direct Fire Recovery Pics Reconfiguration 07\DSCN4612.JPG
MK118 ATC101	4369682.788	402818.809	140.2	11.3	0.15	Cast Aluminum w Ferrous Ring	344	50	50	0.145	1.35	612	Direct Fire Recovery Pics Reconfiguration 07\DSCN4610.JPG