


TIMBER SALES INSPECTION

Date 8/8/84
 Purchaser Hinson Pulpwood Sale Name Roadside Zone Thinning
 Operator Allen Goodson Contract No. 7895
 Inspector AL Henry Payment Unit No. Area #1 Deck 2+3

DIVISION 2. TIMBER HARVESTING
 SECTION 02000. DETAILED REQUIREMENTS

1. Are trees being harvested properly marked? yes
2. Are all properly marked trees being cut? No - some not being cut due to
3. Do stump and stump spinters meet contract specifications? yes. physical
4. Are all trees being limbed and topped before skidding or bunching (except in clearcuts)? yes some skidding damage
5. Are pulpwood and topwood being harvested during sawtimbered operation? yes
6. Is directional felling being used? yes
7. If a feller-buncher is required, is it being used? yes
8. Is slash being removed from specified areas? yes
9. Are tops not utilized being lopped to meet contract specifications? yes
10. Is lopping being done as cutting progresses? yes
11. Are unused tops being pulled away from standing timber? yes
12. Are road, paths, trails and firebreaks clean and passable? yes
13. Is slash being removed from utility rights of way? yes
14. Are all precautions being taken to prevent damage to standing timber during:
 - a. Felling yes
 - b. Bunching see #15
 - c. Skidding see #15
15. Does the inspector(s) feel that damage is within acceptable limits? 2 Avoidables + 8 UNavoidables to be cut; 2 Avoidables to leave; 52 minor
16. Do unmarked trees remain uncut? yes
17. Does all the purchasers equipment meet contract specifications? yes
18. Are all ~~precautions~~ yes being taken to prevent damage or unsightly situations?
19. Are damages to grasses areas such as road shoulders or food plots being repaired by the purchaser? N/A
20. Are protective measures such as gravel for haul and skid roads or road shoulders being performed by the purchaser before damage becomes severe or unsightly? N/A
21. Are all roads left clean and passable to two wheel drive vehicles? yes
22. Are adequate sanitation conveniences provided? no
23. Is litter or refuse being picked up in the logging area? yes
24. After completion of the previous deck, was it properly disposed of? yes
25. Are all possible steps being taken to prevent damage to streams or streamside areas? N/A



Are the regulations concerning logs being hauled, skidded, or
ded across streams without approval being complied with?

N/A

7. Are streams and ditches cleared of all logging debris? yes

yes

28. Are repairs or maintenance being done so as to prevent or
minimize soil erosion or damage to the soil? N/A

N/A

29. Are all possible precautions being taken to prevent or
minimize soil erosion or damage to the soil? yes

yes

30. Are corrective actions, for soil erosion, being taken and
completed in each payment unit following logging? N/A

N/A

31. Has the requirement concernng no timber marking equipment
on the job site been complied with? yes

yes

32. Has the authorized representatives of the purchaser taken
corrective action on the preceeding inspection deficiencies, if
any? yes (still working on them)

yes (still working on them)

33. Has the purchaser been cooperative in making it possible for
the OICC to safely inspect the logging and conduct other official
duties? yes

yes


34. Has the purchaser complied with all endangered species
requirements? N/A

N/A

35. Was a copy given to the Purchaser's Representative, and
discussed with him? yes


yes

James Alherton
Purchaser's Representative



Date 8-8-84Purchaser Hinson PulpwoodSale Name Roadside Zone ThinningOperator Allen GoodsonContract No. 7895Inspector AL HenryPayment Unit No. Area #1 Deck #4DIVISION 2. TIMBER HARVESTING
SECTION 02000. DETAILED REQUIREMENTS


1. Are trees being harvested properly marked? yes
2. Are all properly marked trees being cut? No - Some trees NOT cut de.S. location
3. Do stump and stump spinters meet contract specifications? yes To phys
4. Are all trees being limbed and topped before skidding or bunching (except in clearcuts)? Some skidding being done before Toping
5. Are pulpwood and topwood being harvested during sawtimbered operation? yes
6. Is directional felling being used? yes
7. If a feller-buncher is required, is it being used? yes
8. Is slash being removed from specified areas? yes
9. Are tops not utilized being lopped to meet contract specifications? yes
10. Is lopping being done as cutting progresses? yes
11. Are unused tops being pulled away from standing timber? yes
12. Are road, paths, trails and firebreaks clean and passable? yes
13. Is slash being removed from utility rights of way? yes
14. Are all precautions being taken to prevent damage to standing timber during:
 - a. Felling yes
 - b. Bunching yes
 - c. Skidding No Some skidding w/ tops on
15. Does the inspector(s) feel that damage is within acceptable limits? 2 UNAVOIDABLE TO BE CUT, 4 BLUE TREES CUT; 18 MINOR DAMAGES
16. Do unmarked trees remain uncut? 4 UNAUTHORIZED BLUE TREES CUT
17. Does all the purchasers equipment meet contract specifications? yes
18. Are all precautions being taken to prevent damage or unsightly situations? see #14 c above
19. Are damages to grasses areas such as road shoulders or food plots being repaired by the purchaser? N/A
20. Are protective measures such as gravel for haul and skid roads or road shoulders being performed by the purchaser before damage becomes severe or unsightly? N/A
21. Are all roads left clean and passable to two wheel drive vehicles? yes
22. Are adequate sanitation conveniences provided? No
23. Is litter or refuse being picked up in the logging area? yes
24. After completion of the previous deck, was it properly disposed of? yes
25. Are all possible steps being taken to prevent damage to streams or streamside areas? N/A



Are the regulations concerning logs being hauled, skidded, or
dragged across streams without approval being complied with?

7. Are streams and ditches cleared of all logging debris? N/A.
yes
28. Are repairs or maintenance being done so as to prevent or
minimize soil erosion or damage to the soil? N/A
29. Are all possible precautions being taken to prevent or
minimize soil erosion or damage to the soil? yes
30. Are corrective actions, for soil erosion, being taken and
completed in each payment unit following logging? N/A
31. Has the requirement concerning no timber marking equipment
on the job site been complied with? yes
32. Has the authorized representatives of the purchaser taken
corrective action on the preceding inspection deficiencies, if
any? yes being done now
33. Has the purchaser been cooperative in making it possible for
the OICC to safely inspect the logging and conduct other official
duties? yes
34. Has the purchaser complied with all endangered species
requirements? N/A
35. Was a copy given to the Purchaser's Representative, and
discussed with him? yes

James Atkinson
Purchaser's Representative



TIMBER SALES INSPECTION


Date 30 May 85
 Purchaser Hinson Pulpwood Co Sale Name Road Side Zone Thinning
 Operator Pettway Contract No. N62470-84-S-7895
 Inspector A Henry Payment Unit No. Area #3

DIVISION 2. TIMBER HARVESTING
 SECTION 02000. DETAILED REQUIREMENTS

1. Are trees being harvested properly marked? YES
2. Are all properly marked trees being cut? NO
3. Do stump and stump spinters meet contract specifications? YES
4. Are all trees being limbed and topped before skidding or bunching (except in clearcuts)? N/A
5. Are pulpwood and topwood being harvested during sawtimbered operation? YES
6. Is directional felling being used? N/A
7. If a feller-buncher is required, is it being used? N/A
8. Is slash being removed from specified areas? NO - needs to be moved from
9. Are tops not utilized being lopped to meet contract specifications? FOR THE MOST PART YES GOLF COURSE AREA
10. Is lopping being done as cutting progresses? YES
11. Are unused tops being pulled away from standing timber? SOME LEFT
12. Are road, paths, trails and firebreaks clean and passable? AGAINST TREES
13. Is slash being removed from utility rights of way? N/A
14. Are all precautions being taken to prevent damage to standing timber during:
 - a. Felling YES
 - b. Bunching N/A
 - c. Skidding N/A
15. Does the inspector(s) feel that damage is within acceptable limits? YES - 5 blue TREES CUT 8 MINOR
16. Do unmarked trees remain uncut? YES
17. Does all the purchasers equipment meet contract specifications? YES
18. Are all precautions being taken to prevent damage or unsightly situations? YES
19. Are damages to grasses areas such as road shoulders or food plots being repaired by the purchaser? N/A
20. Are protective measures such as gravel for haul and skid roads or road shoulders being performed by the purchaser before damage becomes severe or unsightly? N/A
21. Are all roads left clean and passable to two wheel drive vehicles? YES
22. Are adequate sanitation conveniences provided? NO
23. Is litter or refuse being picked up in the logging area? YES
24. After completion of the previous deck, was it properly disposed of? NO DECK
25. Are all possible steps being taken to prevent damage to streams or streamside areas? N/A

26. Are the regulations concerning logs being hauled, skidded, or yarded across streams without approval being complied with? N/A
27. Are streams and ditches cleared of all logging debris? yes
28. Are repairs or maintenance being done so as to prevent or minimize soil erosion or damage to the soil? N/A
29. Are all possible precautions being taken to prevent or minimize soil erosion or damage to the soil? N/A
30. Are corrective actions, for soil erosion, being taken and completed in each payment unit following logging? N/A
31. Has the requirement concerning no timber marking equipment on the job site been complied with? yes
32. Has the authorized representatives of the purchaser taken corrective action on the preceding inspection deficiencies, if any? yes
33. Has the purchaser been cooperative in making it possible for the OICC to safely inspect the logging and conduct other official duties? yes
34. Has the purchaser complied with all endangered species requirements? N/A
35. Was a copy given to the Purchaser's Representative, and discussed with him? NO

Purchaser's Representative



TIMBER SALES INSPECTION

Date Aug 6 1984

Purchaser Hinson Pulpwood

Sale Name Roadside Zone Thinning

Operator Allen Goodson

Contract No. 7895


Inspector AL Henry

Payment Unit No. Area #1 Deck 1

DIVISION 2. TIMBER HARVESTING
SECTION 02000. DETAILED REQUIREMENTS

1. Are trees being harvested properly marked? yes
2. Are all properly marked trees being cut? No - see below *
3. Do stump and stump spinters meet contract specifications? Some need to be cut
4. Are all trees being limbed and topped before skidding or bunching (except in clearcuts)? yes
5. Are pulpwood and topwood being harvested during sawtimbered operation? yes
6. Is directional felling being used? yes
7. If a feller-buncher is required, is it being used? yes
8. Is slash being removed from specified areas? yes
9. Are tops not utilized being lopped to meet contract specifications? yes
10. Is lopping being done as cutting progresses? yes
11. Are unused tops being pulled away from standing timber? yes
12. Are road, paths, trails and firebreaks clean and passable? yes
13. Is slash being removed from utility rights of way? yes
14. Are all precautions being taken to prevent damage to standing timber during:
 - a. Felling yes
 - b. Bunching yes
 - c. Skidding see #15
15. Does the inspector(s) feel that damage is within acceptable limits? yes Two (2) Avoidable - 2 To be cut; 35 unavoidable or minor damaged
16. Do unmarked trees remain uncut? yes
17. Does all the purchasers equipment meet contract specifications? yes
18. Are all precautions being taken to prevent damage or unsightly situations? yes
19. Are damages to grasses areas such as road shoulders or food plots being repaired by the purchaser? N/A
20. Are protective measures such as gravel for haul and skid roads or road shoulders being performed by the purchaser before damage becomes severe or unsightly? N/A
21. Are all roads left clean and passable to two wheel drive vehicles? yes
22. Are adequate sanitation conveniences provided? No
23. Is litter or refuse being picked up in the logging area? yes
24. After completion of the previous deck, was it properly disposed of? 1st Deck -
25. Are all possible steps being taken to prevent damage to streams or streamside areas? N/A


* - unable to cut some trees due to location of power lines & roads



Are the regulations concerning logs being hauled, skidded, or
ded across streams without approval being complied with?

7. Are streams and ditches N/A
yes cleared of all logging debris?
28. Are repairs or maintenance being done so as to prevent or
minimize soil erosion or damage to the soil? N/A
29. Are all possible precautions being taken to prevent or
minimize soil erosion or damage to the soil? yes
30. Are corrective actions, for soil erosion, being taken and
completed in each payment unit following logging? N/A
31. Has the requirement concernng no timber marking equipment
on the job site been complied with? yes
32. Has the authorized representatives of the purchaser taken
corrective action on the preceeding inspection deficiencies, if
any? 1st Inspection
33. Has the purchaser been cooperative in making it possible for
the OICC to safely inspect the logging and conduct other official
duties? yes
34. Has the purchaser complied with all endangered species
requirements? N/A
35. Was a copy given to the Purchaser's Representative, and
discussed with him? yes

Alla Doodu
Purchaser's Representative



23 MAY 84

FROM: AC/S FAC

TO: ROICC JAX N.C. AREA


SUBJ: TIMBER SALE; ADDITION TO

REF: CONTRACT # N62470-84-S-7895

ENCL: 7 MAPS

IT IS REQUESTED THAT THE REF. BE


INCREASED BY 121.93 MBF PINE SAWTIMBER
AND 130.47 CORDS PINE PULPWOOD. THE
CONTRACTOR HAS VIEWED THE ADDITIONAL HARVEST
AREAS AND AGREED TO ADD THE TIMBER AT
THE OFFICIAL BID PRICE OF \$115⁰⁰/MBF
AND \$10⁰⁰/C.D. FOR A NET INCREASE OF
\$15,326.65. THE TIMBER IS LOCATED IN THE
12 SITES ^{SHOWN IN THE ENCL.} AND SHOULD BE REMOVED AT THE
EARLIEST POSSIBLE DATE FOR THE CONVENIENCE
OF THE GOVT.



Gun Position - H

- == DIRT ROAD
- Gun Position Boundary
- ... Food Plot
- ▨ Harvest Areas

1" = 20 ch.



3-1-1941

11


Gun Position 24

-  Paved Road
-  Dirt Road
-  Gun Position Boundary

 Food Plot

 Harvest Area


1" = 20 ch.




1871

Gun Position - 33


-  Paved Road
 -  Dirt Road
 -  Gun Position Boundary
 -  Harvest Area
- 1" = 20 ch.






Gun Position - MAC 36

- ==== Dirt Road
 - Gun Position Boundary
 - ▨ Harvest Area
- 1" - 20ch.






Gun Position 27
and 31

-  Paved Road
-  Dirt Road
-  Gun Position Boundary
-  Food Plot
-  Harvest Area

1" = 20 ch.



1000

1000

1000

1000


1000


1000

1000

1000

Gun Positions : 10
 12
 13
 14

-  Paved Road
-  Dirt Road
-  Food Plot
-  Gun Position Boundary
-  Harvest Areas
-  Surface Hazard Area
1" - 20ch.



11

