

APPENDIX A – PHOTO ALBUM



Figure 33. Photo. Measuring with the PSPA on the Side of the Road at Site 1.



Figure 34. Photo. Coring at Site 1.



Figure 35. Photo. Cores from Site 1.



Figure 36. Photo. Coring at Site 2.



Figure 37. Photo. Examples of Cracks at Site 2.



Figure 38. Photo. View of Site 2.



Figure 39. Photo. Cores from Site 2.



Figure 40. Photo. View of Site 3.



Figure 41. Photo. Coring at Site 3.



Figure 42. Photo. Cores from Site 3.



Figure 43. Photo. Close up of Site 4.



Figure 44. Photo. View of Site 4.



Figure 45. Photo. Coring at Site 4.



Figure 46. Photo. Cores from Site 4.



Figure 47. Photo. Close up of Site 5.



Figure 48. Photo. View of Site 5.



Figure 49. Photo. Coring at Site 5.



Figure 50. Photo. Cores from Site 5.



Figure 51. Photo. Close up of Site 6.



Figure 52. Photo. Cracking at Site 6.



Figure 53. Photo. View of Site 6.



Figure 54. Photo. Cores at Site 6.

