

Allen Fossil Plant (ALF) Fact Sheet



Stantec

Issues Found

- ◆ Sloughing on interior slope of Fly Ash Pond (FAP) north dike.
- ◆ Steep slopes on FAP east divider dike and East Stilling Pond east dike.
- ◆ Seepage areas on FAP north dike near coal yard.
- ◆ Seepage areas on East Stilling Pond east dike.
- ◆ Seepage areas on south embankment near the fuel containment area.
- ◆ Erosion on interior slope of FAP south dike.
- ◆ Erosion on interior slopes of East Stilling Pond east dike.
- ◆ Steep slopes on East Stilling Pond east dike.

Remediation Projects Completed

- ◆ Repaired sloughing on FAP north dike in 2009.
- ◆ Repaired erosion on FAP south dike interior slope in 2009.

Remediation Projects Partially Completed

- ◆ East Stilling Pond east dike slope stability project underway. Scheduled for completion in November 2011.

Future Remediation Projects

- ◆ Seepage issues will be addressed along FAP north dike near the coal yard and south embankment near fuel containment area.

