

## Summary Report of Occurrences Reviewed From February 1 – 5, 2010

**Summary:** 24 occurrences at 13 sites reviewed during this period.

### Occurrences of Significant Interest (2)

#### **Near Miss – 2 occurrences at 2 sites**

- **NA – Y12 National Security Complex (Significance Category 3).** On February 1, while in the process of exiting the driver's side of a pick-up truck to apply de-icer to the back window, an employee's left foot slipped on the icy pavement. The truck engine was running and the transmission was in Park at the time. While trying to keep from falling, he flailed both hands and his right foot/leg got caught in the truck as he fell. As the employee nearly righted himself, the truck began to roll backwards approximately 60 feet. The employee started to yell for help as he clung to the door and was dragged on his side and back on the ground. Another employee heard the cries for help, ran to the moving truck, entered it, and applied the brake. The truck was then moved forward about 2 feet and the fallen employee was assisted to his feet. The employee reported to Y-12 Occupational Health Services, where he was examined and found to have no injuries. An investigation was started.
- **NA – Nevada Test Site (Significance Category 4).** On January 29, a Security Police Officer (SPO) II fired his assigned .40-caliber Sig Sauer P-226 pistol without authorization, in the Perimeter Access Control Station to a security area. While attempting to adjust the equipment on his pistol belt, the SPO removed the holster and pistol. He then removed the pistol from the holster without authority and removed the ammunition magazine from the pistol. However, he failed to ensure that the barrel was clear of live ammunition. Thinking he was pointing the pistol in a safe direction and that it was unloaded, the SPO pointed it toward the ceiling in the guard station and pulled the trigger. The pistol functioned as designed and discharged a round into a drop-down false ceiling, struck the bullet resistant armored roof of the building, and came to rest somewhere in the insulation between the ceiling and the roof. No one was injured. The SPO was relieved of duty pending disciplinary action. A certified armorer performed a limited functional test and technical inspection of the pistol and found no abnormalities.

**Other Occurrences (22).** See Table (Note: The Table includes the occurrence listed above).

Occurrence Category	Number of Occurrences				Number of Sites
	E&E	NNSA	SC	DOE Total	
Injury - Industrial Hygiene/Occupational Safety	0	2	0	2	2
Near Miss	2	2	0	4	4
Authorization Basis	1	1	0	2	2
Radiological Concerns	2	1	1	4	3
Environmental	0	1	0	1	1
Fire Safety	2	0	0	2	2
Shipping/Quality Assurance	2	0	0	2	1
Criticality Concerns	0	0	0	0	0
Industrial Operations	0	0	0	0	0
Conduct of Operations	1	0	1	2	2
Electrical Safety	1	2	0	3	3

Occurrence Category	Number of Occurrences				Number of Sites
	E&E	NNSA	SC	DOE Total	
Vehicle Accident	0	0	0	0	0
Equipment Failures	1	0	0	1	1
Safeguards and Security	1	0	0	1	1
Suspect & Counterfeit Parts	0	0	0	0	0
Other	0	0	0	0	0
<b>Total</b>	<b>13</b>	<b>9</b>	<b>2</b>	<b>24</b>	

ORPS Significance Categories	OE	SC1	SC2	SC3	SC4	R
Totals for the Week:	0	0	5	14	4	1

### Secretarial Office Summary

National Nuclear Security Administration	9 occurrences	(6 sites)
Office of Environmental Management	11 occurrences	(4 sites)
Office of Nuclear Energy	2 occurrences	(1 site)
Office of Science	2 occurrences	(2 sites)